

LV - Pedal Box

PDLO - Pedal Box Brake Overtravel Switch
Molex MX150 12 Pin Connector

PDL-INRT-12V HV
PDL-PDM2-12V_HV 1C-4-RED
PDL-PDM2-12V_HV 4C-1-BLA

PDLT - Transponder Molex MX150 2 Pin Connector PDLT-PDM1-12V TRAN 4C-1-RED PDLT-CHS-GND_TRAN 1C-10-BLA