NORTH ZONE REFINERY - INSPECTION REPORT

Report ID: IR-E202-2026-08-21

Equipment: E-202 Pressure Vessel

Inspection findings

Tube wall thickness: Rows 12-15 measured 3.8-4.2 mm.

Minimum allowable tube wall thickness: 4.6 mm.

Localised pitting corrosion at the shell inlet nozzle; maximum depth 1.8 mm.

The report does not state an approval status.

verify after repair

- field inspector

Page 2 - follow-up observations

Follow-up visual inspection complete. No new defects observed.

Inspector annotation is retained as source evidence.