

MCU ports:		Note:
GPIO_0	IO1	General Purpose Input/Output ports
GPIO_1	IO0	
GPIO_2	IO7	
GPIO_3	IO6	
GPIO_4	IO5	
GPIO_5	IO4	
GPIO_6	IO16	
GPIO_7	IO9	
GPIO_8	IO18	
GPIO_9	IO19	
GPIO_10	IO20	
GPIO_11	IO21	
GPIO_12	IO22	
GPIO_13	IO23	
GPIO_14	IO15	
GPIO_15	IO17	
COM		This must be connected with the supply voltage of the driven devices.
OUT_0	Shiftreg: IO8, IO10, IO11	Darlington Transistor Array with 500mA collector current capability
OUT_1		
OUT_2		
OUT_3		
OUT_4		
OUT_5		
OUT_6		
BUS_0	Does not connect to the mcu.	Extra wires in the CAT6 cable to be able to connect boards with a redundant line if it is needed.
BUS_1		
BUS_2		
BUS_3		
BUS_4		
BUS_5		
BUS_6		
BUS_7		