



Scenario A — Smooth concrete warehouse aisle cruise (favours Traditional PID)

Controller: PID

Velocity tracking



Tracking error (RMSE = 0.0255 m/s)



Control effort ($\int u^2 dt = 0.075$, mean compute = 2.8 μ s)

