

DEFECTRA VEHICLE INSPECTION REPORT

Vehicle Information

Brand	ww
Model	ww
Plate	567
Year	None
Inspection Date	2026-08-22

Detected Defects

Defect	Confidence	Severity
Crack	97.27 %	MEDIUM

Inspection Summary

****Vehicle Inspection Report****
****Inspection Date:** 2026-08-22**
****Vehicle:** Brand: **ww** | Model: **ww** | Plate: **567** | Year: *Not specified***

1. Inspection Summary

During the automated visual inspection, the system identified a ****crack**** located centrally within the inspected area.

- ****Confidence:** 97.27 %**
- ****Severity:** **Medium****

The detection aligns with the system’s documented performance: severe damage classes are reliably identified (recall > 0.80), while medium-severity defects such as cracks can be partially confounded with background. The high confidence score indicates a strong likelihood that the crack is genuine and not a false positive.

2. Overall Vehicle Condition

- ****Exterior Finish:**** No additional surface damage (scratches, dents, or paint loss) was reported in the inspected region.
- ****Structural Integrity:**** The detected crack is classified as medium severity. Without precise location data (e.g., chassis, bumper, or glass), the potential impact on structural integrity remains uncertain.
- ****Safety Implications:**** A medium-severity crack, if located on a load-bearing component, could propagate under repeated stress, potentially compromising safety. If the crack is on a

non-structural panel, the risk is lower but still warrants attention to prevent corrosion or aesthetic degradation.

Conclusion: The vehicle is in **moderate** condition with a single medium-severity defect that requires further assessment before determining the need for repair or replacement.

3. Maintenance Recommendations

Step	Action	Rationale
1	Locate the crack precisely (e.g., body panel, bumper, glass, or structural frame).	Determines whether the defect is on a load-bearing part.
2	Measure the crack dimensions – length, width, and depth.	Depth < 2 mm typically indicates a superficial flaw; > 2 mm suggests a deeper, potentially structural issue.
3	Assess surrounding finish – check for corrosion, paint loss, or additional micro-cracks.	Secondary damage can accelerate crack propagation.
4	Treatment options	
	a. Superficial crack (< 2 mm, non-structural) – clean, sand, and fill with appropriate filler or epoxy.	Restores appearance and prevents moisture ingress.
	b. Deep crack (> 2 mm, structural or critical location) – consider professional repair (soldering, welding, or component replacement).	Ensures structural integrity and safety.
5	Post-repair inspection – visual check and, if feasible, mechanical testing (tension or vibration) to confirm integrity.	Verifies that the repair meets safety standards.
6	Documentation – record crack location, measurements, repair method, and any follow-up inspections.	Provides traceability for future maintenance and resale value.

Additional Notes:

- If the crack is on a non-structural panel and remains superficial after repair, routine monitoring every 6–12 months is advisable.
- For cracks on structural components, a full mechanical assessment by a certified body shop is recommended before proceeding with any repair.

Prepared by:
[Your Name] – Automotive Inspection Specialist
[Company/Organization]

This report is based on the automated detection system’s findings and the provided defect description. For definitive safety decisions, a qualified technician should perform a physical inspection.

Overall Condition

Good

Maintenance Recommendation

- Crack: 1. Vérifier l'emplacement précis du craquement (boîtier, pare-chocs, pare-brise, etc.).
- 2. Mesurer la longueur, la largeur et la profondeur de la fissure.
- 3. Si la fissure est superficielle (< 2 mm de profondeur) et située sur une partie non structurelle, un

traitement de surface (nettoyage, ponçage, colmatage) peut suffire.

4. Si la fissure est profonde, située sur une partie structurelle ou si elle dépasse 2 mm, envisager un remplacement de la pièce ou une réparation par soudage/colmatage professionnel.

5. Après réparation, effectuer un contrôle visuel et, si possible, un test de résistance (tension ou vibration) pour confirmer l'intégrité.

Generated automatically by DEFECTRA AI
22/08/2026 14:00