

#### Department of Mechanical, Automotive, & Materials Engineering

401 Sunset Avenue, Windsor Ontario, Canada N9B 3P4 519 253 3000 (2616) www.uwindsor.ca

### First Line of Title Here Second Line of Title Here

John Smith: ID 12345678 Jane Smith: ID 87654321

September 15, 2015

# Contents

1	Introduction	1
	1.1 System Description	1
2	Analysis	3
	2.1 Eigenvalue Analysis	3
	2.2 Frequency Response Plots	4
	2.3 Steady State Gains	7
	2.4 Equilibrium Analysis	7
3	Conclusion	9
Α	Equations of Motion	10

## List of Figures

2.1	Frequency response: actuator	5
2.2	Frequency response: twist actuator	6

## LIST OF TABLES

1.1	Body Location and Properties	1
1.2	Connection Location and Properties	2
2.1	Eigenvalues	3
2.2	Eigenvalue Analysis	4
2.3	Steady State Gains	7
2.4	System Static Deflections	7
2.5	System Preloads	8

## CHAPTER 1

## Introduction

Replace this text with the introduction of your report.

### 1.1 System Description

The system properties are given in Tables 1.1 and 1.2.

Table 1.1: Body Location and Properties

No.	Body Name	Location [m]	Mass [kg]	Inertia [kg·m <sup>2</sup> ] ( $I_{xx}$ , $I_{yy}$ , $I_{zz}$ ; $I_{xy}$ , $I_{yz}$ , $I_{zx}$ )
1	f-axle	0.762, 0.000, 0.100	10.000	1.633, 0.000, 1.633; 0.000, 0.000, 0.000
2	lf-axle	0.762, 0.550, 0.229	0.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000
3	rf-axle	0.762, -0.550, 0.229	0.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000
4	r-axle-t	-0.762,  0.000,  0.329	5.000	0.817, 0.000, 0.817; 0.000, 0.000, 0.000
5	r-axle-b	-0.762,  0.000,  0.129	5.000	0.817, 0.000, 0.817; 0.000, 0.000, 0.000
6	lr-axle	-0.762,  0.550,  0.229	0.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000
7	rr-axle	-0.762, -0.550, 0.229	0.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000
8	chassis	0.000, 0.000, 0.300	300.000	50.000, 120.000, 180.000; 0.000, 0.000, 0.000
9	lf-wheel	0.762, 0.600, 0.229	10.000	0.500, 1.000, 0.500; 0.000, 0.000, 0.000
10	rf-wheel	0.762, -0.600, 0.229	10.000	0.500, 1.000, 0.500; 0.000, 0.000, 0.000
11	lr-wheel	-0.762, 0.600, 0.229	10.000	0.500, 1.000, 0.500; 0.000, 0.000, 0.000
12	rr-wheel	-0.762, -0.600, 0.229	10.000	0.500, 1.000, 0.500; 0.000, 0.000, 0.000
13	left-rear-bellcrank	-0.662, 0.200, 0.200	1.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000
14	right-rear-bellcrank	-0.662, -0.200, 0.200	1.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000
15	centre-rear-bellcrank	-0.562,  0.000,  0.100	1.000	0.000, 0.000, 0.000; 0.000, 0.000, 0.000

Note: inertias are defined as the positive integral over the body, e.g.,  $I_{xy} = + \int r_x r_y \, dm$ .

 Table 1.2: Connection Location and Properties

No.	Connection Name	Location [m]	Ur	nit Axis	Stiffness [N/m]	Damping [Ns/m]
1	lf-tire	0.762, 0.600, 0.000	0.000,	0.000, 1.000	_	-
2	rf-tire	0.762, -0.600, 0.000	1.000,	0.000, 0.000	_	-
3	rr-tire	-0.762, -0.600, 0.000	0.000,	0.000, 1.000	_	-
4	lr-tire	-0.762,  0.600, 0.000	1.000,	0.000, 0.000	-	-
5	lf-wb	0.762, 0.600, 0.229	0.000,	1.000, 0.000	_	-
6	rf-wb	0.762, -0.600, 0.229	0.000,	1.000, 0.000	_	_
7	lr-wb	-0.762, 0.600, 0.229	0.000,	1.000, 0.000	_	_
8	rr-wb	-0.762, -0.600, 0.229	0.000,	1.000, 0.000	_	_
9	lf	0.762, 0.550, 0.229	-0.170,	-0.170, 0.970	_	_
10	rf	0.762, -0.550, 0.229	-0.170,	0.170, 0.970	_	_
11	lr	-0.762, 0.550, 0.329	1.000,	0.000, 0.000	_	_
12	rr	-0.762, -0.550, 0.329	1.000,	0.000, 0.000	_	_
13	lr	-0.762, 0.550, 0.129	1.000,	0.000, 0.000	_	_
14	rr	-0.762, -0.550, 0.129	1.000,	0.000, 0.000	_	_
15	lf-pin	-0.662, 0.200, 0.200	1.000,	0.000, 0.000	_	_
16	rf-pin	-0.662, -0.200, 0.200	1.000,	0.000, 0.000	_	_
17	rear spring hinge	-0.562, 0.000, 0.100	0.000,	1.000, 0.000	_	_
18	lf-tire	0.762, 0.600, 0.000	0.000,	0.000, 1.000	100,000	0
19	rf-tire	0.762, -0.600, 0.000	0.000,	0.000, 1.000	100,000	0
20	rr-tire	-0.762, -0.600, 0.000	0.000,	0.000, 1.000	100,000	0
21	lr-tire	-0.762,  0.600, 0.000	0.000,	0.000, 1.000	100,000	0
22	front left	0.800, 0.500, 0.100			5,000	200
_	front left	0.900, 0.400, 0.300		- '	_	_
23	front right	0.800, -0.500, 0.100	_ ,	_ ,	5,000	200
-	front right	0.900, -0.400, 0.300	_ ,		-	_
24	rear left	-0.700, 0.500, 0.100		–	5,000	200
-	rear left	-0.600, 0.400, 0.300		- , -	-	_
25	rear right	-0.700, -0.500, 0.100		- ,-	5,000	200
23 -	rear right	-0.600, -0.400, 0.300	_	_ ,	-	_
26	right-b	0.762, 0.000, 0.100		_ ,	_	_
_	right-b	0.462, -0.400, 0.100	_ ,		_	_
27	left-b	0.762, 0.000, 0.100		- ,-	_	_
_	left-b	0.462, 0.400, 0.100	_	- ,-	_	_
28	right-b	0.762, -0.500, 0.300	_	- ,-	_	_
_	right-b	0.462, -0.500, 0.300	_	_ ,	_	_
29	left-b	0.762, 0.500, 0.300	_	_ ,	_	_
-	left-b	0.462, 0.500, 0.300	_	, _	_	_
30	lf-tie-rod	0.662, 0.500, 0.150	_	_ ,	_	_
-	lf-tie-rod	0.662, 0.100, 0.150	_	, _	_	_
31	rf-tie-rod	0.662, -0.500, 0.150	_	_ ,	_	_
- J1	rf-tie-rod	0.662, -0.100, 0.150	_	_ ,	_	_
	right rear lower	-0.762, 0.000, 0.100	_	, _	_	_
32 -	right rear lower	-0.462, -0.500, 0.100	_ ,	_ ,_	_	_
	left rear lower	-0.762, 0.000, 0.100	_ ,	_ ,_	_	_
33	left rear lower	-0.462, 0.500, 0.100	_ ,	_ ,_	_	_
			_ ,	_ , _	_	_
34	right rear upper right rear upper	-0.762, -0.500, 0.300 -0.462, -0.500, 0.300	_ ,	, =	_	_
	left rear upper	-0.462, -0.300, 0.300 -0.762, 0.500, 0.300	_ ,	, =	_	
35 -	left rear upper	-0.462, 0.500, 0.300	_	, =	_	_
- 36	lr-link	-0.462, 0.300, 0.300 -0.662, 0.250, 0.150	_ ,	, =	_	
	lr-link		- ,	, –		<del>-</del>
-			- ,	- , -	_	_
37	rr-link rr-link	-0.662, -0.250, 0.150	- ,	- , -	_	_
		-0.662, -0.600, 0.229	- ,	- , -	_	_
38	lr-link-c	-0.662, 0.100, 0.200	- ,			<del>_</del> _
Unīver	sily-linkvindsor	-0.662, 0.100, 0.100	- ,	- , -	automati <del>c</del> ally gene	rated by EōM
Vehicle	Dynamics and Contr	ol Research Group -0.662, -0.100, 0.200 -0.662, -0.100, 0.100	2 _ ,	- , -	- Septe	mber 15, 2 <u>0</u> 15
_	11-1111K-C	-0.002, -0.100, 0.100	- ,	- , -	_ ^	

### CHAPTER 2

### ANALYSIS

Replace this text with the body of your report. Add sections or subsections as appropriate.

#### 2.1 Eigenvalue Analysis

The eigenvalue properties are given in Tables 2.1 and 2.2.

Table 2.1: Eigenvalues

No.	Real [rad/s]	Imaginary [rad/s]	Real [Hz]	Imaginary [Hz]
1	$-4.5097 \times 10^{0}$	$8.2778 \times 10^{1}$	$-7.1774 \times 10^{-1}$	$1.3175 \times 10^{1}$
2	$-4.5097 \times 10^0$	$-8.2778 \times 10^{1}$	$-7.1774 \times 10^{-1}$	$-1.3175 \times 10^{1}$
3	$-4.4637 \times 10^{0}$	$8.1831 \times 10^{1}$	$-7.1042 \times 10^{-1}$	$1.3024 \times 10^{1}$
4	$-4.4637 \times 10^0$	$-8.1831 \times 10^{1}$	$-7.1042 \times 10^{-1}$	$-1.3024 \times 10^{1}$
5	$-2.2760 \times 10^0$	$7.1334 \times 10^{1}$	$-3.6224 \times 10^{-1}$	$1.1353 \times 10^{1}$
6	$-2.2760 \times 10^{0}$	$-7.1334 \times 10^{1}$	$-3.6224 \times 10^{-1}$	$-1.1353 \times 10^{1}$
7	$-2.9782 \times 10^0$	$7.4037 \times 10^{1}$	$-4.7400 \times 10^{-1}$	$1.1783 \times 10^{1}$
8	$-2.9782 \times 10^{0}$	$-7.4037 \times 10^{1}$	$-4.7400 \times 10^{-1}$	$-1.1783 \times 10^{1}$
9	$-1.0520 \times 10^0$	$7.0729 \times 10^{0}$	$-1.6743 \times 10^{-1}$	$1.1257 \times 10^{0}$
10	$-1.0520 \times 10^0$	$-7.0729 \times 10^0$	$-1.6743 \times 10^{-1}$	$-1.1257 \times 10^0$
11	$-1.0118 \times 10^{0}$	$3.7812 \times 10^{0}$	$-1.6103 \times 10^{-1}$	$6.0180 \times 10^{-1}$
12	$-1.0118 \times 10^0$	$-3.7812 \times 10^0$	$-1.6103 \times 10^{-1}$	$-6.0180 \times 10^{-1}$
13	$-1.0301 \times 10^0$	$5.6001 \times 10^{0}$	$-1.6395 \times 10^{-1}$	$8.9128 \times 10^{-1}$
14	$-1.0301 \times 10^0$	$-5.6001 \times 10^0$	$-1.6395 \times 10^{-1}$	$-8.9128 \times 10^{-1}$
15	$0.0000 \times 10^{0}$	$0.0000 \times 10^{0}$	$0.0000 \times 10^{0}$	$0.0000 \times 10^{0}$
16	$0.0000 \times 10^{0}$	$0.0000 \times 10^{0}$	$0.0000 \times 10^{0}$	$0.0000 \times 10^{0}$

Note: oscillatory roots appear as complex conjugates.

There are 7 oscillatory modes, 7 damped modes, o unstable modes, and 2 rigid body modes.

Table 2.2: Eigenvalue Analysis

No.	Frequency [Hz]	Damping Ratio	Time Constant [s]	Wavelength [s]
1	$1.3194 \times 10^{1}$	$5.4399 \times 10^{-2}$	$2.2174 \times 10^{-1}$	$7.5904 \times 10^{-2}$
2	$1.3194 \times 10^{1}$	$5.4399 \times 10^{-2}$	$2.2174 \times 10^{-1}$	$7.5904 \times 10^{-2}$
3	$1.3043 \times 10^{1}$	$5.4467 \times 10^{-2}$	$2.2403 \times 10^{-1}$	$7.6783 \times 10^{-2}$
4	$1.3043 \times 10^{1}$	$5.4467 \times 10^{-2}$	$2.2403 \times 10^{-1}$	$7.6783 \times 10^{-2}$
5	$1.1359 \times 10^{1}$	$3.1890 \times 10^{-2}$	$4.3937 \times 10^{-1}$	$8.8081 \times 10^{-2}$
6	$1.1359 \times 10^{1}$	$3.1890 \times 10^{-2}$	$4.3937 \times 10^{-1}$	$8.8081 \times 10^{-2}$
7	$1.1793 \times 10^{1}$	$4.0193 \times 10^{-2}$	$3.3577 \times 10^{-1}$	$8.4865 \times 10^{-2}$
8	$1.1793 \times 10^{1}$	$4.0193 \times 10^{-2}$	$3.3577 \times 10^{-1}$	$8.4865 \times 10^{-2}$
9	$1.1381 \times 10^{0}$	$1.4712 \times 10^{-1}$	$9.5057 \times 10^{-1}$	$8.8835 \times 10^{-1}$
10	$1.1381 \times 10^{0}$	$1.4712 \times 10^{-1}$	$9.5057 \times 10^{-1}$	$8.8835 \times 10^{-1}$
11	$6.2297 \times 10^{-1}$	$2.5849 \times 10^{-1}$	$9.8834 \times 10^{-1}$	$1.6617 \times 10^{0}$
12	$6.2297 \times 10^{-1}$	$2.5849 \times 10^{-1}$	$9.8834 \times 10^{-1}$	$1.6617 \times 10^{0}$
13	$9.0624 \times 10^{-1}$	$1.8091 \times 10^{-1}$	$9.7078 \times 10^{-1}$	$1.1220 \times 10^{0}$
14	$9.0624 \times 10^{-1}$	$1.8091 \times 10^{-1}$	$9.7078 \times 10^{-1}$	$1.1220 \times 10^{0}$
15	_	_	_	_
16	_	_	_	_

Notes: a) oscillatory roots are listed twice, b) negative time constants denote unstable roots.

### 2.2 Frequency Response Plots




Figure 2.1: Frequency response: actuator




Figure 2.2: Frequency response: twist actuator

#### 2.3 Steady State Gains

The steady state gains are given in Table 2.3.

Table 2.3: Steady State Gains

Output/Input	Gain
sensor/actuator	$2.5750 \times 10^{-1}$
sensor/twist actuator twist sensor/actuator	$-1.1000 \times 10^{-7}$ $-8.7445 \times 10^{-1}$
twist sensor/twist actuator	$5.0579 \times 10^{-1}$

### 2.4 Equilibrium Analysis

The results of the equlibrium load analysis are given in Tables 2.4 and 2.5.

Table 2.4: System Static Deflections

No.	Body Name	Туре	Deflection [m] or [rad]
1	f-axle	translation	$3.1101 \times 10^{-4}$ , $0.0000 \times 10^{0}$ , $-8.8419 \times 10^{-3}$
_	_	rotation	$0.0000 \times 10^{0}$ , $-2.4694 \times 10^{-3}$ , $0.0000 \times 10^{0}$
2	lf-axle	translation	$-6.5600 \times 10^{-6}$ , $0.0000 \times 10^{0}$ , $-8.8419 \times 10^{-3}$
_	_	rotation	$0.0000 \times 10^{0}$ , $-2.4694 \times 10^{-3}$ , $2.0000 \times 10^{-8}$
3	rf-axle	translation	$-6.5600 \times 10^{-6}$ , $0.0000 \times 10^{0}$ , $-8.8419 \times 10^{-3}$
_	_	rotation	$-1.2000 \times 10^{-7}$ , $-2.4693 \times 10^{-3}$ , $6.8000 \times 10^{-7}$
4	r-axle-t	translation	$-2.5349 \times 10^{-4}$ , $-1.0000 \times 10^{-8}$ , $-8.9633 \times 10^{-3}$
_	_	rotation	$0.0000 \times 10^{0}$ , $-2.4694 \times 10^{-3}$ , $3.0000 \times 10^{-8}$
5	r-axle-b	translation	$2.4039 \times 10^{-4}$ , $0.0000 \times 10^{0}$ , $-8.9633 \times 10^{-3}$
_	_	rotation	$0.0000 \times 10^{0}$ , $-2.4694 \times 10^{-3}$ , $3.0000 \times 10^{-8}$
6	lr-axle	translation	$-6.5700 \times 10^{-6}$ , $-1.0000 \times 10^{-8}$ , $-8.9633 \times 10^{-3}$
_	_	rotation	$3.0000 \times 10^{-8}$ , $-2.4694 \times 10^{-3}$ , $3.0000 \times 10^{-8}$
7	rr-axle	translation	$-6.5400 \times 10^{-6}$ , $-1.0000 \times 10^{-8}$ , $-8.9633 \times 10^{-3}$
_	-	rotation	$3.0000 \times 10^{-8}$ , $-2.4694 \times 10^{-3}$ , $3.0000 \times 10^{-8}$
8	chassis	translation	$-1.8288 \times 10^{-4}$ , $0.0000 \times 10^{0}$ , $-2.3183 \times 10^{-1}$
-	-	rotation	$-1.0000 \times 10^{-8}$ , $-2.4695 \times 10^{-3}$ , $0.0000 \times 10^{0}$
9	lf-wheel	translation	$-6.5700 \times 10^{-6}$ , $0.0000 \times 10^{0}$ , $-8.8419 \times 10^{-3}$
-	-	rotation	$0.0000 \times 10^{0}$ , $-2.8750 \times 10^{-5}$ , $2.0000 \times 10^{-8}$
10	rf-wheel	translation	$-6.5300 \times 10^{-6}$ , $0.0000 \times 10^{0}$ , $-8.8419 \times 10^{-3}$
_	_	rotation	$-1.2000 \times 10^{-7}$ , $-2.8560 \times 10^{-5}$ , $6.8000 \times 10^{-7}$
11	lr-wheel	translation	$-6.5800 \times 10^{-6}$ , $-2.0000 \times 10^{-8}$ , $-8.9633 \times 10^{-3}$
-	-	rotation	$3.0000 \times 10^{-8}$ , $-2.8790 \times 10^{-5}$ , $3.0000 \times 10^{-8}$
12	rr-wheel	translation	$-6.5300 \times 10^{-6}$ , $-1.0000 \times 10^{-8}$ , $-8.9633 \times 10^{-3}$
-	-	rotation	$3.0000 \times 10^{-8}$ , $-2.8590 \times 10^{-5}$ , $3.0000 \times 10^{-8}$
13	left-rear-bellcrank	translation	$6.4070 \times 10^{-5}$ , $0.0000 \times 10^{0}$ , $-2.3347 \times 10^{-1}$
-	-	rotation	$8.2434 \times 10^{-1}$ , $-2.4695 \times 10^{-3}$ , $0.0000 \times 10^{0}$
14	right-rear-bellcrank	translation	$6.4070 \times 10^{-5}$ , $0.0000 \times 10^{0}$ , $-2.3347 \times 10^{-1}$
_	_	rotation	$-8.2434 \times 10^{-1}$ , $-2.4695 \times 10^{-3}$ , $0.0000 \times 10^{0}$
15	centre-rear-bellcrank	translation	$3.1101 \times 10^{-4}$ , $0.0000 \times 10^{0}$ , $-2.3322 \times 10^{-1}$
-	_	rotation	$-1.0000 \times 10^{-8}$ , $-8.2681 \times 10^{-1}$ , $0.0000 \times 10^{0}$

 Table 2.5: System Preloads

No.	Connector Name	Туре	Load [N] or [Nm] (Components; Magnitude)
1	lf-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $0.0000 \times 10^{0}$
2	rf-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $0.0000 \times 10^{0}$
3	rr-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $0.0000 \times 10^{0}$
4	lr-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $0.0000 \times 10^{0}$
5	lf-wb	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-7.8609 \times 10^{2}$ ; $7.8609 \times 10^{2}$
6	rf-wb	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-7.8609 \times 10^{2}$ ; $7.8609 \times 10^{2}$
7	lr-wb	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-7.9823 \times 10^{2}$ ; $7.9823 \times 10^{2}$
8	rr-wb	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-7.9823 \times 10^{2}$ ; $7.9823 \times 10^{2}$
9	lf	force	$0.0000 \times 10^{0}$ , $-6.0544 \times 10^{1}$ , $7.8609 \times 10^{2}$ ; $7.8842 \times 10^{2}$
_	_	moment	$3.4546 \times 10^{1}$ , $0.0000 \times 10^{0}$ , $6.0544 \times 10^{0}$ ; $3.5072 \times 10^{1}$
10	rf	force	$0.0000 \times 10^{0}$ , $6.0544 \times 10^{1}$ , $7.8609 \times 10^{2}$ ; $7.8842 \times 10^{2}$
_	_	moment	$-3.4546 \times 10^{1}$ , $0.0000 \times 10^{0}$ , $-6.0544 \times 10^{0}$ ; $3.5072 \times 10^{1}$
11	lr	force	$0.0000 \times 10^{0}$ , $-4.4042 \times 10^{2}$ , $2.4525 \times 10^{1}$ ; $4.4110 \times 10^{2}$
_	_	moment	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-3.5586 \times 10^{0}$ ; $3.5586 \times 10^{0}$
12	rr	force	$0.0000 \times 10^{0}$ , $4.4042 \times 10^{2}$ , $2.4525 \times 10^{1}$ ; $4.4110 \times 10^{2}$
_	_	moment	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $3.5586 \times 10^{0}$ ; $3.5586 \times 10^{0}$
13	lr	force	$-6.0683 \times 10^{2}$ , $8.1501 \times 10^{2}$ , $2.4525 \times 10^{1}$ ; $1.0164 \times 10^{3}$
_	_	moment	$0.0000 \times 10^{0}$ , $1.7355 \times 10^{1}$ , $-3.5586 \times 10^{0}$ ; $1.7717 \times 10^{1}$
14	rr	force	$-6.0683 \times 10^{2}$ , $-8.1501 \times 10^{2}$ , $2.4525 \times 10^{1}$ ; $1.0164 \times 10^{3}$
_	_	moment	$0.0000 \times 10^{0}$ , $1.7355 \times 10^{1}$ , $3.5586 \times 10^{0}$ ; $1.7717 \times 10^{1}$
15	lf-pin	force	$0.0000 \times 10^{0}$ , $-2.0000 \times 10^{-5}$ , $9.8100 \times 10^{0}$ ; $9.8100 \times 10^{0}$
16	rf-pin	force	$0.0000 \times 10^{0}$ , $-2.0000 \times 10^{-5}$ , $9.8100 \times 10^{0}$ ; $9.8100 \times 10^{0}$
17	rear spring hinge	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-9.8100 \times 10^{0}$ ; $9.8100 \times 10^{0}$
18	lf-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $8.8419 \times 10^{2}$ ; $8.8419 \times 10^{2}$
19	rf-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $8.8419 \times 10^{2}$ ; $8.8419 \times 10^{2}$
20	rr-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $8.9633 \times 10^{2}$ ; $8.9633 \times 10^{2}$
21	lr-tire	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $8.9633 \times 10^{2}$ ; $8.9633 \times 10^{2}$
22	front left	force	$-3.6852 \times 10^2$ , $3.6852 \times 10^2$ , $-7.3704 \times 10^2$ ; $-9.0268 \times 10^2$
23	front right	force	$-3.6852 \times 10^{2}$ , $-3.6852 \times 10^{2}$ , $-7.3704 \times 10^{2}$ ; $-9.0268 \times 10^{2}$
24	rear left	force	$-3.7459 \times 10^{2}$ , $3.7459 \times 10^{2}$ , $-7.4918 \times 10^{2}$ ; $-9.1755 \times 10^{2}$
25	rear right	force	$-3.7459 \times 10^{2}$ , $-3.7459 \times 10^{2}$ , $-7.4918 \times 10^{2}$ ; $-9.1755 \times 10^{2}$
26	right-b	force	$5.0856 \times 10^2$ , $6.7807 \times 10^2$ , $0.0000 \times 10^0$ ; $-8.4759 \times 10^2$
27	left-b	force	$5.0856 \times 10^2$ , $-6.7807 \times 10^2$ , $0.0000 \times 10^0$ ; $-8.4759 \times 10^2$
28	right-b	force	$-1.4004 \times 10^{2}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $1.4004 \times 10^{2}$
29	left-b	force	$-1.4004 \times 10^{2}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $1.4004 \times 10^{2}$
30	lf-tie-rod	force	$0.0000 \times 10^{0}$ , $-6.0544 \times 10^{1}$ , $0.0000 \times 10^{0}$ ; $6.0544 \times 10^{1}$
31	rf-tie-rod	force	$0.0000 \times 10^{0}$ , $6.0544 \times 10^{1}$ , $0.0000 \times 10^{0}$ ; $6.0544 \times 10^{1}$
32	right rear lower	force	$6.0683 \times 10^{2}$ , $-1.0114 \times 10^{3}$ , $0.0000 \times 10^{0}$ ; $1.1795 \times 10^{3}$
33	left rear lower	force	$6.0683 \times 10^{2}$ , $1.0114 \times 10^{3}$ , $0.0000 \times 10^{0}$ ; $1.1795 \times 10^{3}$
34	right rear upper	force	$-2.3225 \times 10^{2}$ , $0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ ; $-2.3225 \times 10^{2}$
35	left rear upper	force	$-2.3225 \times 10^2$ , $0.0000 \times 10^0$ , $0.0000 \times 10^0$ ; $-2.3225 \times 10^2$
36	lr-link	force	$0.0000 \times 10^{0}$ , $2.0000 \times 10^{-5}$ , $1.0000 \times 10^{-5}$ ; $2.0000 \times 10^{-5}$
37	rr-link	force	$0.0000 \times 10^{0}$ , $2.0000 \times 10^{-5}$ , $-1.0000 \times 10^{-5}$ ; $-2.0000 \times 10^{-5}$
38	lr-link-c	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $1.0000 \times 10^{-5}$ ; $-1.0000 \times 10^{-5}$
39	rr-link-c	force	$0.0000 \times 10^{0}$ , $0.0000 \times 10^{0}$ , $-1.0000 \times 10^{-5}$ ; $1.0000 \times 10^{-5}$

## CHAPTER 3

# Conclusion

Replace this text with the conclusion to your report.

### APPENDIX A

# **EQUATIONS OF MOTION**

The equations of motion are of the form

$$\begin{bmatrix} \mathbf{I} & \mathbf{0} \\ \mathbf{0} & \mathbf{M} \end{bmatrix} \begin{Bmatrix} \dot{\mathbf{p}} \\ \dot{\mathbf{w}} \end{Bmatrix} + \begin{bmatrix} \mathbf{V} & -\mathbf{I} \\ \mathbf{K} & \mathbf{C} \end{bmatrix} \begin{Bmatrix} \mathbf{p} \\ \mathbf{w} \end{Bmatrix} = \begin{Bmatrix} \mathbf{0} \\ f \end{Bmatrix} + \begin{bmatrix} \mathbf{0} \\ \mathbf{F} \end{bmatrix} \begin{Bmatrix} \mathbf{u} \end{Bmatrix}$$

The mass matrix of the system is

Row	Column	Value	Row	Column	Value	Row	Column	Value
1	1	$1.0000 \times 10^{1}$	46	46	$5.0000 \times 10^{1}$	64	64	$5.0000 \times 10^{-1}$
2	2	$1.0000 \times 10^{1}$	47	47	$1.2000 \times 10^2$	65	65	$1.0000 \times 10^{0}$
3	3	$1.0000 \times 10^{1}$	48	48	$1.8000 \times 10^{2}$	66	66	$5.0000 \times 10^{-1}$
4	4	$1.6333 \times 10^{0}$	49	49	$1.0000 \times 10^{1}$	67	67	$1.0000 \times 10^{1}$
6	6	$1.6333 \times 10^{0}$	50	50	$1.0000 \times 10^{1}$	68	68	$1.0000 \times 10^{1}$
19	19	$5.0000 \times 10^{0}$	51	51	$1.0000 \times 10^{1}$	69	69	$1.0000 \times 10^{1}$
20	20	$5.0000 \times 10^{0}$	52	52	$5.0000 \times 10^{-1}$	70	70	$5.0000 \times 10^{-1}$
21	21	$5.0000 \times 10^{0}$	53	53	$1.0000 \times 10^{0}$	71	71	$1.0000 \times 10^{0}$
22	22	$8.1667 \times 10^{-1}$	54	54	$5.0000 \times 10^{-1}$	72	72	$5.0000 \times 10^{-1}$
24	24	$8.1667 \times 10^{-1}$	55	55	$1.0000 \times 10^{1}$	73	73	$1.0000 \times 10^{0}$
25	25	$5.0000 \times 10^{0}$	56	56	$1.0000 \times 10^{1}$	74	74	$1.0000 \times 10^{0}$
26	26	$5.0000 \times 10^{0}$	57	57	$1.0000 \times 10^{1}$	75	75	$1.0000 \times 10^{0}$
27	27	$5.0000 \times 10^{0}$	58	58	$5.0000 \times 10^{-1}$	79	79	$1.0000 \times 10^{0}$
28	28	$8.1667 \times 10^{-1}$	59	59	$1.0000 \times 10^{0}$	80	80	$1.0000 \times 10^{0}$
30	30	$8.1667 \times 10^{-1}$	60	60	$5.0000 \times 10^{-1}$	81	81	$1.0000 \times 10^{0}$
43	43	$3.0000 \times 10^{2}$	61	61	$1.0000 \times 10^{1}$	85	85	$1.0000 \times 10^{0}$
44	44	$3.0000 \times 10^{2}$	62	62	$1.0000 \times 10^{1}$	86	86	$1.0000 \times 10^{0}$
45	45	$3.0000 \times 10^{2}$	63	63	$1.0000 \times 10^{1}$	87	87	$1.0000 \times 10^{0}$

The damping matrix is

Row	Column	Value	Row	Column	Value	Row	Column	Value
1	1	$6.6667 \times 10^{1}$	31	36	$-4.0000 \times 10^{-1}$	40	43	$-7.6200 \times 10^0$

3	1	$1.3333 \times 10^{2}$	32	36	$4.0000 \times 10^{-1}$	41	43	$8.4200 \times 10^{0}$
5	1	$-5.0667 \times 10^{0}$	33	36	$-8.0000 \times 10^{-1}$	42	43	$-4.0000 \times 10^{-1}$
43	1	$-6.6667 \times 10^{1}$	34	36	$9.1440 \times 10^{-2}$	43	43	$1.3333 \times 10^{2}$
45	1	$-1.3333 \times 10^{2}$	35	36	$1.0104 \times 10^{-1}$	45	43	$2.6667 \times 10^{2}$
47	1	$1.2000 \times 10^2$	36	36	$4.8000 \times 10^{-3}$	47	43	$-4.0000 \times 10^{1}$
2	2	$6.6667 \times 10^{1}$	43	36	$4.0000 \times 10^{-1}$	2	44	$-6.6667 \times 10^{1}$
4	2	$-6.6667 \times 10^{1}$	44	36	$-4.0000 \times 10^{-1}$	4	44	$6.6667 \times 10^{1}$
6	2	$3.5867 \times 10^{1}$	45	36	$8.0000 \times 10^{-1}$	6	44	$-3.5867 \times 10^{1}$
44	2	$-6.6667 \times 10^{1}$	46	36	$3.2000 \times 10^{-1}$	31	44	$3.3333 \times 10^{1}$
46	2	$5.3333 \times 10^{1}$	47	36	$4.8000 \times 10^{-1}$	32	44	$-3.3333 \times 10^{1}$
48	2	$-8.6667 \times 10^{1}$	48	36	$8.0000 \times 10^{-2}$	33	44	$6.6667 \times 10^{1}$
1	3	$1.3333 \times 10^{2}$	37	37	$3.3333 \times 10^{1}$	34	44	$-7.6200 \times 10^{0}$
3	3	$2.6667 \times 10^2$	38	37	$3.3333 \times 10^{1}$	35	44	$-8.4200 \times 10^{0}$
5	3	$-1.0133 \times 10^{1}$	39	37	$6.6667 \times 10^{1}$	36	44	$-4.0000 \times 10^{-1}$
43	3	$-1.3333 \times 10^2$	40	37	$7.6200 \times 10^{0}$	37	44	$-3.3333 \times 10^{1}$
45	3	$-2.6667 \times 10^2$	41	37	$-8.4200 \times 10^{0}$	38	44	$-3.3333 \times 10^{1}$
47	3	$2.4000 \times 10^{2}$	42	37	$4.0000 \times 10^{-1}$	39	44	$-6.6667 \times 10^{1}$
2	4	$-6.6667 \times 10^{1}$	43	37	$-3.3333 \times 10^{1}$	40	44	$-7.6200 \times 10^{0}$
4	4	$6.6667 \times 10^{1}$	44	37	$-3.3333 \times 10^{1}$	41	44	$8.4200 \times 10^{0}$
6	4	$-3.5867 \times 10^{1}$	45	37	$-6.6667 \times 10^{1}$	42	44	$-4.0000 \times 10^{-1}$
44	4	$6.6667 \times 10^{1}$	46	37	$2.6667 \times 10^{1}$	44	44	$1.3333 \times 10^{2}$
46	4	$-5.3333 \times 10^{1}$	47	37	$-4.0000 \times 10^{1}$	46	44	$-1.0667 \times 10^2$
48	4	$8.6667 \times 10^{1}$	48	37	$6.6667 \times 10^{0}$	48	44	$7.3333 \times 10^{1}$
1	5	$-5.0667 \times 10^{0}$	37	38	$3.3333 \times 10^{1}$	1	45	$-1.3333 \times 10^{2}$
3	5	$-1.0133 \times 10^{1}$	38	38	$3.3333 \times 10^{1}$	3	45	$-2.6667 \times 10^2$
5	5	$3.8507 \times 10^{-1}$	39	38	$6.6667 \times 10^{1}$	5	45	$1.0133 \times 10^{1}$
43	5	$5.0667 \times 10^{0}$	40	38	$7.6200 \times 10^{0}$	31	45	$-6.6667 \times 10^{1}$
45	5	$1.0133 \times 10^{1}$	41	38	$-8.4200 \times 10^{0}$	32	45	$6.6667 \times 10^{1}$
47	5	$-9.1200 \times 10^{0}$	42	38	$4.0000 \times 10^{-1}$	33	45	$-1.3333 \times 10^2$
2	6	$3.5867 \times 10^{1}$	43	38	$-3.3333 \times 10^{1}$	34	45	$1.5240 \times 10^{1}$
4	6	$-3.5867 \times 10^{1}$	44	38	$-3.3333 \times 10^{1}$	35	45	$1.6840 \times 10^{1}$
6	6	$1.9296 \times 10^{1}$	45	38	$-6.6667 \times 10^{1}$	36	45	$8.0000 \times 10^{-1}$
44	6	$-3.5867 \times 10^{1}$	46	38	$2.6667 \times 10^{1}$	37	45	$-6.6667 \times 10^{1}$
46	6	$2.8693 \times 10^{1}$	47	38	$-4.0000 \times 10^{1}$	38	45	$-6.6667 \times 10^{1}$
48	6	$-4.6627 \times 10^{1}$ $3.3333 \times 10^{1}$	48	38	$6.6667 \times 10^{0}$	39	45	$-1.3333 \times 10^2$
31	31		37	39	$6.6667 \times 10^1$ $6.6667 \times 10^1$	40	45	$-1.5240 \times 10^{1}$
32	31	$-3.3333 \times 10^{1}$ $6.6667 \times 10^{1}$	38	39	$6.6667 \times 10^{2}$ $1.3333 \times 10^{2}$	41	45	$1.6840 \times 10^{1}$ $-8.0000 \times 10^{-1}$
33	31		39	39	$1.5240 \times 10^{1}$	42	45	$-8.0000 \times 10^{-2}$ $2.6667 \times 10^{2}$
34	31	$-7.6200 \times 10^{0}$ $-8.4200 \times 10^{0}$	40	39 39	$1.5240 \times 10^{4}$ $-1.6840 \times 10^{1}$	43	45	$2.6667 \times 10^{2}$ $5.3333 \times 10^{2}$
35	31	$-8.4200 \times 10^{-1}$ $-4.0000 \times 10^{-1}$	41			45	45	$-8.0000 \times 10^{1}$
36	31	$-4.0000 \times 10^{-1}$ $-3.3333 \times 10^{1}$	42	39	$8.0000 \times 10^{-1}$ $-6.6667 \times 10^{1}$	47	45	$-8.0000 \times 10^{-3}$ $5.3333 \times 10^{1}$
43	31	$-3.3333 \times 10^{1}$ $3.3333 \times 10^{1}$	43 44	39 39	$-6.6667 \times 10^{1}$ $-6.6667 \times 10^{1}$	2 4	46 46	$-5.3333 \times 10^{1}$
44	31	$-6.6667 \times 10^{1}$	44	39	$-0.0007 \times 10^{-1.3333} \times 10^{2}$			$-3.3333 \times 10^{-3}$ $2.8693 \times 10^{1}$
45	31 31	$-0.6667 \times 10^{-1}$ $-2.6667 \times 10^{1}$	45 46	39 39	$-1.3333 \times 10^{-1}$ $5.3333 \times 10^{1}$	6 31	46 46	$-2.6667 \times 10^{1}$
46 47	31	$-2.0007 \times 10^{-1}$ $-4.0000 \times 10^{1}$	40 47	39	$-8.0000 \times 10^{1}$	32	46	$-2.6667 \times 10^{1}$ $2.6667 \times 10^{1}$
48		$-6.6667 \times 10^{0}$	48	39	$-8.0000 \times 10^{-1}$ $1.3333 \times 10^{1}$	33	46	$-5.3333 \times 10^{1}$
31	31 32	$-3.3333 \times 10^{1}$	37	40	$7.6200 \times 10^{0}$	33 34	46	$-3.3333 \times 10^{-3}$ $6.0960 \times 10^{0}$
32	32	$-3.3333 \times 10^{-1}$ $3.3333 \times 10^{1}$	38	40	$7.6200 \times 10^{\circ}$ $7.6200 \times 10^{\circ}$	35	46	$6.7360 \times 10^{0}$
33	32	$-6.6667 \times 10^{1}$	39	40	$1.5240 \times 10^{1}$	36	46	$3.2000 \times 10^{-1}$
34	32	$7.6200 \times 10^{0}$	40	40	$1.7419 \times 10^{0}$	37	46	$2.6667 \times 10^{1}$
		$8.4200 \times 10^{0}$			$-1.9248 \times 10^{0}$			$2.6667 \times 10^{1}$
35 36	32 32	$4.0000 \times 10^{-1}$	41 42	40 40	$-1.9248 \times 10^{-2}$ $9.1440 \times 10^{-2}$	38 39	46 46	$5.3333 \times 10^{1}$
36 43	32 32	$3.3333 \times 10^{1}$	43	40	$-7.6200 \times 10^{0}$	39 40	46 46	$6.0960 \times 10^{0}$
43 44	32 32	$-3.3333 \times 10^{1}$	43 44	40	$-7.6200 \times 10^{\circ}$ $-7.6200 \times 10^{\circ}$	40 41	46 46	$-6.7360 \times 10^{0}$
44 45	32 32	$-3.3333 \times 10$ $6.6667 \times 10^{1}$	44 45	40	$-7.6200 \times 10^{4}$ $-1.5240 \times 10^{1}$	41	46 46	$-6.7360 \times 10^{-1}$ $3.2000 \times 10^{-1}$
46	32 32	$2.6667 \times 10^{1}$	46	40	$-1.3240 \times 10^{-1.3240} \times 10^{-1.3240} \times 10^{-1.3240}$	44	46	$-1.0667 \times 10^2$
47	32	$4.0000 \times 10^{1}$	47	40	$-9.1440 \times 10^{0}$	46	46	$8.5333 \times 10^{1}$
-1/	JL	T.0000 A 10	7/	40	7.17TU \ 1U	70	40	0.3333 \ 10

48	32	$6.6667 \times 10^{0}$	48	40	$1.5240 \times 10^0$	48	46	$-5.8667 \times 10^{1}$
31	33	$6.6667 \times 10^{1}$	37	41	$-8.4200 \times 10^{0}$	1	47	$1.2000 \times 10^{2}$
32	33	$-6.6667 \times 10^{1}$	38	41	$-8.4200 \times 10^{0}$	3	47	$2.4000 \times 10^{2}$
33	33	$1.3333 \times 10^{2}$	39	41	$-1.6840 \times 10^{1}$	5	47	$-9.1200 \times 10^{0}$
34	33	$-1.5240 \times 10^{1}$	40	41	$-1.9248 \times 10^{0}$	31	47	$-4.0000 \times 10^{1}$
35	33	$-1.6840 \times 10^{1}$	41	41	$2.1269 \times 10^{0}$	32	47	$4.0000 \times 10^{1}$
36	33	$-8.0000 \times 10^{-1}$	42	41	$-1.0104 \times 10^{-1}$	33	47	$-8.0000 \times 10^{1}$
43	33	$-6.6667 \times 10^{1}$	43	41	$8.4200 \times 10^{0}$	34	47	$9.1440 \times 10^{0}$
44	33	$6.6667 \times 10^{1}$	44	41	$8.4200 \times 10^{0}$	35	47	$1.0104 \times 10^{1}$
45	33	$-1.3333 \times 10^2$	45	41	$1.6840 \times 10^{1}$	36	47	$4.8000 \times 10^{-1}$
46	33	$-5.3333 \times 10^{1}$	46	41	$-6.7360 \times 10^{0}$	37	47	$-4.0000 \times 10^{1}$
47	33	$-8.0000 \times 10^{1}$	47	41	$1.0104 \times 10^{1}$	38	47	$-4.0000 \times 10^{1}$
48	33	$-1.3333 \times 10^{1}$	48	41	$-1.6840 \times 10^{0}$	39	47	$-8.0000 \times 10^{1}$
31	34	$-7.6200 \times 10^{0}$	37	42	$4.0000 \times 10^{-1}$	40	47	$-9.1440 \times 10^{0}$
32	34	$7.6200 \times 10^{0}$	38	42	$4.0000 \times 10^{-1}$	41	47	$1.0104 \times 10^{1}$
33	34	$-1.5240 \times 10^{1}$	39	42	$8.0000 \times 10^{-1}$	42	47	$-4.8000 \times 10^{-1}$
34	34	$1.7419 \times 10^{0}$	40	42	$9.1440 \times 10^{-2}$	43	47	$-4.0000 \times 10^{1}$
35	34	$1.9248 \times 10^{0}$	41	42	$-1.0104 \times 10^{-1}$	45	47	$-8.0000 \times 10^{1}$
36	34	$9.1440 \times 10^{-2}$	42	42	$4.8000 \times 10^{-3}$	47	47	$3.1200 \times 10^2$
43	34	$7.6200 \times 10^{0}$	43	42	$-4.0000 \times 10^{-1}$	2	48	$-8.6667 \times 10^{1}$
44	34	$-7.6200 \times 10^0$	44	42	$-4.0000 \times 10^{-1}$	4	48	$8.6667 \times 10^{1}$
45	34	$1.5240 \times 10^{1}$	45	42	$-8.0000 \times 10^{-1}$	6	48	$-4.6627 \times 10^{1}$
46	34	$6.0960 \times 10^{0}$	46	42	$3.2000 \times 10^{-1}$	31	48	$-6.6667 \times 10^0$
47	34	$9.1440 \times 10^{0}$	47	42	$-4.8000 \times 10^{-1}$	32	48	$6.6667 \times 10^{0}$
48	34	$1.5240 \times 10^{0}$	48	42	$8.0000 \times 10^{-2}$	33	48	$-1.3333 \times 10^{1}$
31	35	$-8.4200 \times 10^{0}$	1	43	$-6.6667 \times 10^{1}$	34	48	$1.5240 \times 10^{0}$
32	35	$8.4200 \times 10^{0}$	3	43	$-1.3333 \times 10^2$	35	48	$1.6840 \times 10^{0}$
33	35	$-1.6840 \times 10^{1}$	5	43	$5.0667 \times 10^{0}$	36	48	$8.0000 \times 10^{-2}$
34	35	$1.9248 \times 10^{0}$	31	43	$-3.3333 \times 10^{1}$	37	48	$6.6667 \times 10^{0}$
35	35	$2.1269 \times 10^{0}$	32	43	$3.3333 \times 10^{1}$	38	48	$6.6667 \times 10^{0}$
36	35	$1.0104 \times 10^{-1}$	33	43	$-6.6667 \times 10^{1}$	39	48	$1.3333 \times 10^{1}$
43	35	$8.4200 \times 10^{0}$	34	43	$7.6200 \times 10^{0}$	40	48	$1.5240 \times 10^{0}$
44	35	$-8.4200 \times 10^{0}$	35	43	$8.4200 \times 10^{0}$	41	48	$-1.6840 \times 10^{0}$
45	35	$1.6840 \times 10^{1}$	36	43	$4.0000 \times 10^{-1}$	42	48	$8.0000 \times 10^{-2}$
46	35	$6.7360 \times 10^{0}$	37	43	$-3.3333 \times 10^{1}$	44	48	$7.3333 \times 10^{1}$
47	35	$1.0104 \times 10^{1}$	38	43	$-3.3333 \times 10^{1}$	46	48	$-5.8667 \times 10^{1}$
48	35	$1.6840 \times 10^{0}$	39	43	$-6.6667 \times 10^{1}$	48	48	$1.1533 \times 10^{2}$

#### The stiffness matrix is

Row	Column	Value	Row	Column	Value	Row	Column	Value
1	1	$-6.6451 \times 10^3$	34	32	$6.5595 \times 10^2$	44	46	$-4.6782 \times 10^3$
2	1	$-5.3496 \times 10^{-5}$	35	32	$3.6820 \times 10^{2}$	45	46	$-3.8464 \times 10^{-5}$
3	1	$5.7901 \times 10^3$	36	32	$-8.2159 \times 10^2$	46	46	$6.0363 \times 10^2$
4	1	$3.2860 \times 10^{-5}$	43	32	$1.4576 \times 10^3$	47	46	$9.3833 \times 10^{-5}$
5	1	$-2.2002 \times 10^2$	44	32	$3.0624 \times 10^{3}$	48	46	$-2.8936 \times 10^3$
6	1	$8.0902 \times 10^{-5}$	45	32	$2.9153 \times 10^{3}$	88	46	$-1.9620 \times 10^{0}$
11	1	$-7.8609 \times 10^2$	46	32	$1.1661 \times 10^{3}$	90	46	$6.4418 \times 10^{-11}$
12	1	$-6.0544 \times 10^{1}$	47	32	$1.7492 \times 10^3$	1	47	$4.7771 \times 10^3$
17	1	$-7.8609 \times 10^2$	48	32	$-2.3137 \times 10^3$	2	47	$-6.3276 \times 10^{-5}$
18	1	$6.0544 \times 10^{1}$	74	32	$-3.2362 \times 10^{-6}$	3	47	$2.6539 \times 10^3$
43	1	$6.6451 \times 10^3$	75	32	$1.4411 \times 10^{-5}$	4	47	$-4.6300 \times 10^{-5}$
44	1	$5.3496 \times 10^{-5}$	76	32	$5.5873 \times 10^{-7}$	5	47	$-1.4398 \times 10^2$
45	1	$-5.7901 \times 10^3$	31	33	$2.9153 \times 10^{3}$	6	47	$-3.1822 \times 10^{-5}$
46	1	$-2.2161 \times 10^{-5}$	32	33	$-2.9153 \times 10^3$	7	47	$2.2704 \times 10^{1}$

 $University\ of\ Windsor$ 

automatically generated by EoM September 15, 2015

47	1	$4.7771 \times 10^{3}$	33	33	$1.3106 \times 10^{3}$	9	47	$1.0020 \times 10^{2}$
48	1	$-3.7618 \times 10^{-5}$	34	33	$-6.5846 \times 10^{1}$	10	47	$-5.0100 \times 10^0$
1	2	$-5.3496 \times 10^{-5}$	35	33	$1.0268 \times 10^2$	11	47	$8.2355 \times 10^{0}$
2	2	$-4.7623 \times 10^3$	36	33	$-3.4984 \times 10^{1}$	12	47	$1.1352 \times 10^{0}$
3	2	$-6.5721 \times 10^{-5}$	43	33	$-2.9153 \times 10^3$	13	47	$2.2704 \times 10^{1}$
4	2	$-3.0818 \times 10^3$	44	33	$2.9153 \times 10^{3}$	15	47	$1.0020 \times 10^2$
5	2	$2.4974 \times 10^{-6}$	45	33	$-1.3106 \times 10^3$	16	47	$5.0100 \times 10^{0}$
6	2	$1.2775 \times 10^3$	46	33	$-4.4681 \times 10^2$	17	47	$8.2355 \times 10^{0}$
10	2	$7.8609 \times 10^{2}$	47	33	$-8.9317 \times 10^2$	18	47	$-1.1352 \times 10^{0}$
12	2	$-1.4558 \times 10^{-9}$	48	33	$-5.8306 \times 10^2$	25	47	$5.9494 \times 10^2$
16	2	$7.8609 \times 10^2$	74	33	$1.4411 \times 10^{-5}$	26	47	$-1.1833 \times 10^{-5}$
18	2	$1.3257 \times 10^{-9}$	75	33	$-6.4170 \times 10^{-5}$	27	47	$-1.8690 \times 10^3$
43	2	$5.3496 \times 10^{-5}$	76	33	$-2.4880 \times 10^{-6}$	28	47	$-3.3844 \times 10^{-7}$
44	2	$4.7623 \times 10^3$	31	34	$-3.3322 \times 10^2$	29	47	$-1.7015 \times 10^{1}$
45	2	$6.5721 \times 10^{-5}$	32	34	$-9.3229 \times 10^{1}$	31	47	$-1.7492 \times 10^3$
46	2	$2.5602 \times 10^{3}$	33	34	$-4.4043 \times 10^2$	32	47	$1.7492 \times 10^3$
47	2	$-6.3276 \times 10^{-5}$	34	34	$7.6592 \times 10^{1}$	33	47	$-8.9317 \times 10^2$
48	2	$2.3514 \times 10^{3}$	35	34	$4.2217 \times 10^{1}$	34	47	$2.6960 \times 10^{2}$
1	3	$5.7901 \times 10^3$	36	34	$-5.7458 \times 10^{1}$	35	47	$3.0250 \times 10^{2}$
2	3	$-6.5721 \times 10^{-5}$	43	34	$3.3322 \times 10^{2}$	36	47	$2.0990 \times 10^{1}$
3	3	$1.7531 \times 10^3$	44	34	$9.3229 \times 10^{1}$	37	47	$-1.7492 \times 10^3$
4	3	$-6.9062 \times 10^{-5}$	45	34	$4.4043 \times 10^2$	38	47	$-1.7492 \times 10^3$
5	3	$-1.5998 \times 10^2$	46	34	$1.7230 \times 10^2$	39	47	$-8.9317 \times 10^2$
6	3	$-3.5358 \times 10^{-5}$	47	34	$2.6960 \times 10^2$	40	47	$-2.6960 \times 10^2$
10	3	$6.0544 \times 10^{1}$	48	34	$-1.9685 \times 10^2$	41	47	$3.0250 \times 10^2$
11	3	$1.4558 \times 10^{-9}$	74	34	$7.2054 \times 10^{-7}$	42	47	$-2.0990 \times 10^{1}$
16	3	$-6.0544 \times 10^{1}$	75	34	$-3.2085 \times 10^{-6}$	43	47	$-1.9191 \times 10^3$
17	3	$-1.3257 \times 10^{-9}$	76	34	$-1.2440 \times 10^{-7}$	44	47	$1.1486 \times 10^{-4}$
43	3	$-5.7901 \times 10^3$	31	35	$1.1352 \times 10^2$	45	47	$8.0113 \times 10^2$
44	3	$6.5721 \times 10^{-5}$	32	35	$3.6820 \times 10^2$	46	47	$6.2595 \times 10^{-5}$
45	3	$-1.7531 \times 10^3$	33	35	$-5.0416 \times 10^2$	47	47	$5.3127 \times 10^3$
46	3	$7.9686 \times 10^{-5}$	34	35	$4.2217 \times 10^{1}$	48	47	$6.3540 \times 10^{-5}$
47	3	$2.6539 \times 10^3$	35	35	$8.9779 \times 10^{1}$	88	47	$-4.8177 \times 10^{-10}$
48	3	$8.5437 \times 10^{-5}$	36	35	$7.6677 \times 10^{1}$	89	47	$-1.9620 \times 10^{0}$
1	4	$3.2860 \times 10^{-5}$	43	35	$-1.1352 \times 10^2$	90	47	$-1.7145 \times 10^{-10}$
2	4	$-3.0818 \times 10^3$	44	35	$-3.6820 \times 10^2$	1	48	$-3.7618 \times 10^{-5}$
3	4	$-6.9060 \times 10^{-5}$	45	35	$5.0416 \times 10^2$	2	48	$2.3514 \times 10^3$
4	4	$1.8277 \times 10^3$	46	35	$2.0166 \times 10^2$	3	48	$8.5437 \times 10^{-5}$
5	4	$2.5522 \times 10^{-7}$	47	35	$3.0250 \times 10^2$	4	48	$3.8498 \times 10^3$
6	4	$-1.5035 \times 10^3$	48	35	$2.6633 \times 10^2$	5	48	$-3.2466 \times 10^{-6}$
10	4	$-6.7792 \times 10^{1}$	74	35	$-1.4411 \times 10^{-6}$	6	48	$-2.9867 \times 10^2$
11	4	$8.0067 \times 10^{-10}$	75	35	$6.4170 \times 10^{-6}$	7	48	$1.5136 \times 10^{1}$
12	4	$1.8721 \times 10^{-10}$	76	35	$2.4880 \times 10^{-7}$	11	48	$-1.1897 \times 10^{0}$
16	4	$-6.7792 \times 10^{1}$	31	36	$-2.0479 \times 10^2$	12	48	$7.5680 \times 10^{-1}$
17	4	$-0.7792 \times 10^{-10}$ $7.2911 \times 10^{-10}$	32	36	$-2.0479 \times 10^{2}$ $-2.1475 \times 10^{2}$	13	48	$-1.5136 \times 10^{1}$
18	4	$-1.7048 \times 10^{-10}$	33	36	$-2.1473 \times 10^{-1}$ $-3.4984 \times 10^{1}$	17	48	$1.1897 \times 10^{0}$
43	4	$-3.2860 \times 10^{-5}$	34	36	$-3.4964 \times 10^{0}$ $3.2255 \times 10^{0}$	18	48	$7.5680 \times 10^{-1}$
44	4	$-3.2800 \times 10$ $3.0818 \times 10^3$	35	36	$-8.9544 \times 10^{0}$	25	48	$2.1971 \times 10^{-5}$
45	4	$6.9062 \times 10^{-5}$	36	36	$-6.5508 \times 10^{1}$	26	48	$-3.9765 \times 10^2$
46	4	$-1.0754 \times 10^3$	43	36	$-0.3308 \times 10^{-0.3308} \times 10^{-0.33$	28	48	$-3.9763 \times 10^{-1}$ $-1.1373 \times 10^{1}$
47	4	$-4.6300 \times 10^{-5}$	43	36	$2.1475 \times 10^2$	28 29	48	$-6.2836 \times 10^{-7}$
48		$-4.6300 \times 10^{-3}$ $3.8498 \times 10^{3}$	44	36	$3.4984 \times 10^{1}$	31	48 48	$-0.2836 \times 10^{-1}$ $-1.7899 \times 10^{3}$
	4	$-2.2002 \times 10^{2}$		36 36	$3.4984 \times 10^{-1}$ $1.3993 \times 10^{1}$	32		$-1.7899 \times 10^{3}$ $-2.3137 \times 10^{3}$
1	5	$-2.2002 \times 10^{2}$ $2.4974 \times 10^{-6}$	46		$1.3993 \times 10^{1}$ $2.0990 \times 10^{1}$		48	$-2.3137 \times 10^{3}$ $-5.8306 \times 10^{2}$
2	5		47	36		33	48	
3	5	$-1.5998 \times 10^{2}$	48	36	$-2.1077 \times 10^2$	34	48	$-1.9685 \times 10^2$
4	5	$2.5204 \times 10^{-7}$	73	36	$3.3703 \times 10^{-6}$	35	48	$2.6633 \times 10^2$
5	5	$1.6849 \times 10^{2}$	74	36	$-3.2362 \times 10^{-7}$	36	48	$-2.1077 \times 10^2$
6	5	$3.0625 \times 10^{-6}$	75	36	$1.4411 \times 10^{-6}$	37	48	$1.7899 \times 10^3$

11	5	$-1.0109 \times 10^2$	76	36	$5.5873 \times 10^{-8}$	38	48	$-2.3137 \times 10^3$
12	5	$-7.7859 \times 10^{0}$	77	36	$-1.6852 \times 10^{-7}$	39	48	$5.8306 \times 10^{2}$
17	5	$-1.0109 \times 10^2$	78	36	$-1.6852 \times 10^{-7}$	40	48	$-1.9685 \times 10^2$
18	5	$7.7859 \times 10^{0}$	37	37	$-2.2882 \times 10^3$	41	48	$-2.6633 \times 10^2$
43	5	$2.2002 \times 10^2$	38	37	$1.4576 \times 10^{3}$	42	48	$-2.1077 \times 10^2$
44	5	$-2.4974 \times 10^{-6}$	39	37	$2.9153 \times 10^{3}$	43	48	$-7.1116 \times 10^{-5}$
45	5	$1.5998 \times 10^{2}$	40	37	$3.3322 \times 10^{2}$	44	48	$2.6736 \times 10^{3}$
46	5	$-9.9896 \times 10^{-7}$	41	37	$-6.3566 \times 10^2$	45	48	$-9.8689 \times 10^{-5}$
47	5	$-1.4398 \times 10^2$	42	37	$5.7938 \times 10^{2}$	46	48	$-2.8806 \times 10^3$
48	5	$-3.2466 \times 10^{-6}$	43	37	$2.2882 \times 10^{3}$	47	48	$7.6157 \times 10^{-5}$
1	6	$8.0900 \times 10^{-5}$	44	37	$-1.4576 \times 10^3$	48	48	$-6.8543 \times 10^3$
2	6	$1.2775 \times 10^{3}$	45	37	$-2.9153 \times 10^3$	88	48	$5.5132 \times 10^{0}$
3	6	$-3.5358 \times 10^{-5}$	46	37	$1.1661 \times 10^{3}$	90	48	$-1.8101 \times 10^{-10}$
4	6	$-1.5035 \times 10^3$	47	37	$-1.7492 \times 10^3$	11	49	$7.8609 \times 10^{2}$
5	6	$3.0611 \times 10^{-6}$	48	37	$1.7899 \times 10^{3}$	12	49	$2.1298 \times 10^{-9}$
6	6	$-7.2996 \times 10^2$	79	37	$6.7403 \times 10^{-5}$	10	50	$-7.8609 \times 10^2$
11	6	$4.3235 \times 10^{2}$	83	37	$-3.3701 \times 10^{-6}$	12	50	$-9.7597 \times 10^{-11}$
12	6	$3.3299 \times 10^{1}$	84	37	$3.3701 \times 10^{-6}$	10	51	$-2.1298 \times 10^{-9}$
17	6	$-4.3235 \times 10^2$	37	38	$1.4576 \times 10^3$	11	51	$9.7597 \times 10^{-11}$
18	6	$3.3299 \times 10^{1}$	38	38	$-3.0624 \times 10^3$	51	51	$1.0000 \times 10^5$
43	6	$-8.0902 \times 10^{-5}$	39	38	$2.9153 \times 10^3$	50	52	$-1.5827 \times 10^{-8}$
44	6	$-1.2775 \times 10^3$	40	38	$6.5595 \times 10^2$	51	52	$1.4834 \times 10^{-11}$
45	6	$3.5358 \times 10^{-5}$	41	38	$-3.6820 \times 10^2$	52	52	$-2.0213 \times 10^2$
46	6	$1.2460 \times 10^3$	42	38	$-8.2159 \times 10^2$	49	53	$1.5827 \times 10^{-8}$
47	6	$-3.1822 \times 10^{-5}$	43	38	$-1.4576 \times 10^3$	51	53	$5.4954 \times 10^{-10}$
48	6	$-2.9867 \times 10^2$	44	38	$3.0624 \times 10^3$	52	53	$5.6166 \times 10^{-11}$
7	7	$1.5136 \times 10^2$	45	38	$-2.9153 \times 10^3$	54	53	$-1.2239 \times 10^{-9}$
11	7	$-1.1897 \times 10^{1}$	46	38	$1.1661 \times 10^3$	49	54	$-1.4834 \times 10^{-11}$
12	7	$6.8112 \times 10^{1}$	47	38	$-1.7492 \times 10^3$	50	54	$-5.4954 \times 10^{-10}$
43	7	$-1.5136 \times 10^2$	48	38	$-2.3137 \times 10^3$	52	54	$-1.4794 \times 10^{-10}$
47	7	$2.2704 \times 10^{1}$	80	38	$3.2361 \times 10^{-6}$	53	54	$-4.8348 \times 10^{-10}$
48	7	$1.5136 \times 10^{1}$	81	38	$1.4410 \times 10^{-5}$	17	55	$7.8609 \times 10^2$
10	8	$2.9740 \times 10^{-10}$	82	38	$-5.5870 \times 10^{-7}$	18	55	$1.6707 \times 10^{-9}$
12	8	$1.5534 \times 10^{-9}$	37	39	$2.9153 \times 10^3$	16	56	$-7.8609 \times 10^2$
9	9	$1.5136 \times 10^2$	38	39	$2.9153 \times 10^3$	18	56	$-1.8664 \times 10^{-9}$
10	9	$-6.8112 \times 10^{1}$	39	39	$1.3106 \times 10^3$	16	57	$-1.6707 \times 10^{-9}$
11	9	$1.5136 \times 10^{1}$	40	39	$6.5846 \times 10^{1}$	17	57	$1.8664 \times 10^{-9}$
45	9	$-1.5136 \times 10^2$	41	39	$1.0268 \times 10^2$	57	57	$1.0001 \times 10^{5}$ $1.0000 \times 10^{5}$
46	9	$-1.5136 \times 10^{1}$	42	39	$3.4984 \times 10^{1}$	56	58	$-9.8101 \times 10^{-8}$
47	9	$1.0020 \times 10^2$	43	39	$-2.9153 \times 10^3$	57	58	$1.6707 \times 10^{-9}$
8	10	$-2.9740 \times 10^{-10}$	44	39	$-2.9153 \times 10^3$	58	58	$-2.0213 \times 10^2$
9	10	$-7.5680 \times 10^{0}$	45	39	$-1.3106 \times 10^3$	55	59	$9.8101 \times 10^{-8}$
10	10	$3.2304 \times 10^{0}$	46	39	$4.4681 \times 10^2$	57	59	$1.4542 \times 10^{-9}$
11	10	$-9.3200 \times 10^{-1}$	47	39	$-8.9317 \times 10^2$	58	59	$-3.4083 \times 10^{-10}$
12	10	$9.9967 \times 10^{-1}$	48	39	$-6.9317 \times 10^{-10}$ $5.8306 \times 10^{2}$	60	59	$-8.0906 \times 10^{-10}$
45	10	$7.5680 \times 10^{0}$	80	39	$1.4410 \times 10^{-5}$	55	60	$-3.6700 \times 10^{-9}$ $-1.6707 \times 10^{-9}$
46	10	$7.5680 \times 10^{-1}$ $7.5680 \times 10^{-1}$	81	39	$6.4167 \times 10^{-5}$	56	60	$-1.4542 \times 10^{-9}$
47	10	$-5.0100 \times 10^{0}$	82	39	$-2.4878 \times 10^{-6}$	58	60	$-7.5908 \times 10^{-10}$
7		$-3.0100 \times 10^{4}$ $-1.1897 \times 10^{1}$	37	40	$-2.4676 \times 10^{-2}$ $3.3322 \times 10^{2}$	35		$7.9823 \times 10^2$
9	11 11	$-1.1897 \times 10$ $1.5136 \times 10^{1}$	37 38	40	$-9.3229 \times 10^{1}$	36	61	$-2.9467 \times 10^{-10}$
10	11	$-9.3200 \times 10^{-1}$	39	40	$-9.3229 \times 10$ $4.4043 \times 10^2$	36 34	61 62	$-2.9467 \times 10^{-2}$ $-7.9823 \times 10^{2}$
		$-9.3200 \times 10^{-9.3200} \times 10^{-9.3200} \times 10^{-9.3200}$			$7.6592 \times 10^{1}$			$5.8537 \times 10^{-12}$
11	11	$8.3279 \times 10^{3}$ $-3.8900 \times 10^{1}$	40	40 40	$-4.2217 \times 10^{1}$	36 34	62 63	$5.8537 \times 10^{-12}$ $2.9467 \times 10^{-10}$
12	11	$-3.8900 \times 10^{-1}$ $1.1897 \times 10^{-1}$	41		$-4.2217 \times 10^{1}$ $-5.7458 \times 10^{1}$			$-5.8537 \times 10^{-12}$
43	11	$1.1897 \times 10^{4}$ $-1.5136 \times 10^{1}$	42	40	$-5.7458 \times 10^{2}$ $-3.3322 \times 10^{2}$	35	63	$-5.8537 \times 10^{-12}$ $1.0000 \times 10^{5}$
45	11		43	40		63	63	$1.0000 \times 10^{3}$ $2.0031 \times 10^{-8}$
46	11	$-1.5136 \times 10^0$ $8.2355 \times 10^0$	44	40	$9.3229 \times 10^{1}$ $-4.4043 \times 10^{2}$	62	64	$2.0031 \times 10^{-6}$ $-2.9467 \times 10^{-10}$
47	11	$8.2355 \times 10^{\circ}$ $-1.1897 \times 10^{0}$	45 46	40	$-4.4043 \times 10^{2}$ $1.7230 \times 10^{2}$	63	64	$-2.9467 \times 10^{-10}$ $-2.0490 \times 10^{2}$
48	11	-1.169/ X 10°	46	40	1./230 X 10 <sup>-</sup>	64	64	-2.0490 X 10 <sup>-</sup>

7	12	$7.5680 \times 10^{0}$	47	40	$-2.6960 \times 10^2$	61	65	$-2.0031 \times 10^{-8}$
8	12	$-1.5534 \times 10^{-9}$	48	40	$-1.9685 \times 10^2$	63	65	$3.8377 \times 10^{-10}$
10	12	$9.9967 \times 10^{-1}$	80	40	$-7.2050 \times 10^{-7}$	64	65	$-7.1234 \times 10^{-10}$
11	12	$4.0482 \times 10^{-1}$	81	40	$-3.2083 \times 10^{-6}$	66	65	$-2.9151 \times 10^{-10}$
12	12	$-2.2984 \times 10^{0}$	82	40	$1.2439 \times 10^{-7}$	61	66	$2.9467 \times 10^{-10}$
43	12	$-7.5680 \times 10^{0}$	37	41	$1.1352 \times 10^2$	62	66	$-3.8377 \times 10^{-10}$
47	12	$1.1352 \times 10^{0}$	38	41	$-3.6820 \times 10^2$	64	66	$-8.6391 \times 10^{-11}$
48	12	$7.5680 \times 10^{-1}$	39	41	$-5.0416 \times 10^2$	41	67	$7.9823 \times 10^2$
13	13	$1.5136 \times 10^{2}$	40	41	$-4.2217 \times 10^{1}$	42	67	$-1.2267 \times 10^{-9}$
17	13	$-1.1897 \times 10^{1}$	41	41	$8.9779 \times 10^{1}$	40	68	$-7.9823 \times 10^2$
18	13	$-6.8112 \times 10^{1}$	42	41	$-7.6677 \times 10^{1}$	42	68	$-1.5125 \times 10^{-9}$
43	13	$-1.5136 \times 10^2$	43	41	$-1.1352 \times 10^2$	40	69	$1.2267 \times 10^{-9}$
47	13	$2.2704 \times 10^{1}$	44	41	$3.6820 \times 10^{2}$	41	69	$1.5125 \times 10^{-9}$
48	13	$-1.5136 \times 10^{1}$	45	41	$5.0416 \times 10^{2}$	69	69	$1.0000 \times 10^5$
16	14	$8.5606 \times 10^{-11}$	46	41	$-2.0166 \times 10^2$	68	70	$1.2130 \times 10^{-8}$
18	14	$5.4071 \times 10^{-10}$	47	41	$3.0250 \times 10^{2}$	69	70	$-5.1469 \times 10^{-10}$
15	15	$1.5136 \times 10^{2}$	48	41	$-2.6633 \times 10^2$	70	70	$-2.0490 \times 10^2$
16	15	$6.8112 \times 10^{1}$	80	41	$-1.4410 \times 10^{-6}$	67	71	$-1.2130 \times 10^{-8}$
17	15	$1.5136 \times 10^{1}$	81	41	$-6.4167 \times 10^{-6}$	69	71	$-1.0581 \times 10^{-9}$
45	15	$-1.5136 \times 10^2$	82	41	$2.4878 \times 10^{-7}$	70	71	$-9.4609 \times 10^{-10}$
46	15	$1.5136 \times 10^{1}$	37	42	$2.0479 \times 10^2$	72	71	$9.4851 \times 10^{-11}$
47	15	$1.0020 \times 10^2$	38	42	$-2.1475 \times 10^2$	67	72	$5.1469 \times 10^{-10}$
14	16	$-8.5606 \times 10^{-11}$	39	42	$3.4984 \times 10^{1}$	68	72	$1.0581 \times 10^{-9}$
15	16	$7.5680 \times 10^{0}$	40	42	$3.2255 \times 10^{0}$	70	72	$-1.0389 \times 10^{-10}$
16	16	$3.2304 \times 10^{0}$	41	42	$8.9544 \times 10^{0}$	71	72	$1.6277 \times 10^{-10}$
17	16	$9.3200 \times 10^{-1}$	42	42	$-6.5508 \times 10^{1}$	31	73	$-6.7406 \times 10^{-5}$
18	16	$9.9967 \times 10^{-1}$	43	42	$-2.0479 \times 10^2$	36	73	$3.3703 \times 10^{-6}$
45	16	$-7.5680 \times 10^{0}$	44	42	$2.1475 \times 10^2$	47	73	$-9.8100 \times 10^{0}$
46	16	$7.5680 \times 10^{-1}$ $7.5680 \times 10^{-1}$	45	42	$-3.4984 \times 10^{1}$	48	73	$-2.3592 \times 10^{-5}$
47	16	$5.0100 \times 10^{0}$	46	42	$1.3993 \times 10^{1}$	73	73	$-7.7045 \times 10^{-5}$
13	17	$-1.1897 \times 10^{1}$	47	42	$-2.0990 \times 10^{1}$	77	73	$-3.3703 \times 10^{-6}$
15	17	$1.5136 \times 10^{1}$	48	42	$-2.1077 \times 10^2$	78	73	$-1.7815 \times 10^{-5}$
16	17	$9.3200 \times 10^{-1}$	79	42	$3.3701 \times 10^{-6}$	85	73	$1.7613 \times 10^{-4}$ $1.4445 \times 10^{-4}$
17	17	$8.3279 \times 10^{0}$	80	42	$3.2361 \times 10^{-7}$	90	73	$-1.4445 \times 10^{-5}$
18	17	$3.8900 \times 10^{1}$	81	42	$1.4410 \times 10^{-6}$	32	73 74	$-3.2362 \times 10^{-6}$
43	17	$1.1897 \times 10^{1}$	82	42	$-5.5870 \times 10^{-8}$	33	74 74	$-3.2362 \times 10^{-5}$ $1.4411 \times 10^{-5}$
45 45	17	$-1.5136 \times 10^{1}$	83	42	$-3.3870 \times 10$ $-1.6851 \times 10^{-7}$	33 34	74 74	$7.2054 \times 10^{-7}$
46	17	$-1.5136 \times 10$ $1.5136 \times 10^{0}$	84	42	$1.6851 \times 10^{-7}$	35	74 74	$-1.4411 \times 10^{-6}$
		$8.2355 \times 10^{0}$		42	$6.6451 \times 10^3$	36	74 74	$-3.2362 \times 10^{-7}$
47 48	17	$1.1897 \times 10^{0}$	1 2	43 43	$5.3496 \times 10^{-5}$	36 46	7 <del>4</del> 74	$-3.2362 \times 10^{-3}$ $9.8100 \times 10^{0}$
	17				$-5.7901 \times 10^3$			$-7.4647 \times 10^{-10}$
13	18	$-7.5680 \times 10^{0}$ $-5.4071 \times 10^{-10}$	3	43	$-3.2860 \times 10^{-5}$	48	74	$-7.4647 \times 10^{-2}$ $-1.4121 \times 10^{-4}$
14	18	$-5.40/1 \times 10^{-1}$ $9.9967 \times 10^{-1}$	4	43	$-3.2860 \times 10^{-3}$ $2.2002 \times 10^{2}$	74	74	$-1.4121 \times 10^{-5}$ $-1.4411 \times 10^{-5}$
16	18	$-4.0482 \times 10^{-1}$	5	43	$-8.0902 \times 10^{-5}$	75 76	74	$-1.4411 \times 10^{-7}$ $-5.5873 \times 10^{-7}$
17	18	$-4.0482 \times 10^{-2}$ $-2.2984 \times 10^{0}$	6	43	$-8.0902 \times 10^{-2}$ $-1.5136 \times 10^{2}$	76	74	$-5.58/3 \times 10^{-4}$ $1.4445 \times 10^{-4}$
18	18	$-2.2984 \times 10^{\circ}$ $7.5680 \times 10^{\circ}$	7	43	$-1.5136 \times 10^{-1}$ $1.1897 \times 10^{1}$	86	74	$-1.4445 \times 10^{-5}$
43	18		11	43		90	74	
47	18	$-1.1352 \times 10^{0}$	12	43	$-7.5680 \times 10^{0}$	32	75 75	$1.4411 \times 10^{-5}$
48	18	$7.5680 \times 10^{-1}$	13	43	$-1.5136 \times 10^2$	33	75	$-6.4170 \times 10^{-5}$
35	19	$-2.4525 \times 10^{1}$	17	43	$1.1897 \times 10^{1}$	34	75 75	$-3.2085 \times 10^{-6}$
36	19	$-4.4042 \times 10^2$	18	43	$7.5680 \times 10^{0}$	35	75 75	$6.4170 \times 10^{-6}$
41	19	$-2.4525 \times 10^{1}$	25	43	$-2.9747 \times 10^3$	36	75	$1.4411 \times 10^{-6}$
42	19	$4.4042 \times 10^2$	26	43	$5.9167 \times 10^{-5}$	46	75 75	$2.3592 \times 10^{-5}$
34	20	$2.4525 \times 10^{1}$	28	43	$1.6922 \times 10^{-6}$	47	75	$7.4647 \times 10^{-10}$
36	20	$3.0928 \times 10^{-6}$	29	43	$8.5076 \times 10^{1}$	74	75	$-1.4411 \times 10^{-5}$
40	20	$2.4525 \times 10^{1}$	31	43	$2.2882 \times 10^3$	75	75	$6.4170 \times 10^{-5}$
42	20	$-3.0934 \times 10^{-6}$	32	43	$1.4576 \times 10^3$	76	75	$2.4880 \times 10^{-6}$
34	21	$4.4042 \times 10^2$	33	43	$-2.9153 \times 10^3$	32	76	$5.5873 \times 10^{-7}$
35	21	$-3.0928 \times 10^{-6}$	34	43	$3.3322 \times 10^2$	33	76	$-2.4880 \times 10^{-6}$

40	21	$-4.4042 \times 10^2$	35	43	$-1.1352 \times 10^2$	34	76	$-1.2440 \times 10^{-7}$
41	21	$3.0934 \times 10^{-6}$	36	43	$2.0479 \times 10^2$	35	76	$2.4880 \times 10^{-7}$
20	22	$7.8124 \times 10^{-11}$	37	43	$2.2882 \times 10^3$	36	76	$5.5873 \times 10^{-8}$
21	22	$-3.8034 \times 10^{-10}$	38	43	$-1.4576 \times 10^3$	74	76	$-5.5967 \times 10^{-7}$
22	22	$-4.8446 \times 10^2$	39	43	$-2.9153 \times 10^3$	75	76	$2.4882 \times 10^{-6}$
23	22	$3.4054 \times 10^{-6}$	40	43	$-3.3322 \times 10^2$	76	76	$1.0112 \times 10^{-6}$
24	22	$-3.9362 \times 10^{-11}$	41	43	$-1.1352 \times 10^2$	77	76	$2.0251 \times 10^{-9}$
34	22	$2.4223 \times 10^2$	42	43	$-2.0479 \times 10^2$	78	76	$1.9780 \times 10^{-10}$
35	22	$-1.7010 \times 10^{-6}$	43	43	$-7.9442 \times 10^3$	31	77	$3.3703 \times 10^{-6}$
40	22	$2.4223 \times 10^2$	44	43	$-7.9534 \times 10^{-5}$	36	77	$-1.6852 \times 10^{-7}$
41	22	$-1.7014 \times 10^{-6}$	45	43	$1.1621 \times 10^4$	73	77	$-3.3694 \times 10^{-6}$
19	23	$-7.8124 \times 10^{-11}$	46	43	$-1.6175 \times 10^{-5}$	75	77	$-7.4647 \times 10^{-10}$
21	23	$-6.2120 \times 10^{-10}$	47	43	$-1.8995 \times 10^3$	77	77	$-9.6391 \times 10^{-8}$
22	23	$3.4024 \times 10^{-6}$	48	43	$-2.3931 \times 10^{-5}$	78	77	$1.3481 \times 10^{-6}$
24	23	$-4.7074 \times 10^{-10}$	89	43	$9.8100 \times 10^{0}$	31	78	$3.3703 \times 10^{-6}$
19	24	$3.8034 \times 10^{-10}$	90	43	$8.5724 \times 10^{-10}$	36	78	$-1.6852 \times 10^{-7}$
20	24	$6.2120 \times 10^{-10}$	1	44	$5.3496 \times 10^{-5}$	73	78	$-1.7816 \times 10^{-5}$
24	24	$-4.8446 \times 10^2$	2	44	$4.7623 \times 10^3$	74	78	$7.4647 \times 10^{-10}$
35	24	$1.3489 \times 10^{1}$	3	44	$6.5721 \times 10^{-5}$	77	78	$1.3481 \times 10^{-6}$
36	24	$2.4223 \times 10^2$	4	44	$3.0818 \times 10^3$	78	78	$-9.6386 \times 10^{-8}$
41	24	$-1.3489 \times 10^{1}$	5	44	$-2.4974 \times 10^{-6}$	85	78	$1.4445 \times 10^{-5}$
42	24	$2.4223 \times 10^2$	6	44	$-1.2775 \times 10^3$	90	78	$-1.4445 \times 10^{-6}$
25	25	$2.9747 \times 10^3$	25	44	$5.9167 \times 10^{-5}$	37	79	$6.7403 \times 10^{-5}$
26	25	$-5.9167 \times 10^{-5}$	26	44	$-1.0709 \times 10^3$	42	79	$3.3701 \times 10^{-6}$
28	25	$-1.6922 \times 10^{-6}$	28	44	$-3.0627 \times 10^{1}$	47	79	$-9.8100 \times 10^{0}$
29	25	$-8.5076 \times 10^{1}$	29	44	$-1.6922 \times 10^{-6}$	48	79	$-2.3593 \times 10^{-5}$
35	25	$-2.4525 \times 10^{1}$	31	44	$1.4576 \times 10^3$	79	79	$7.7047 \times 10^{-5}$
36	25	$8.1501 \times 10^2$	32	44	$3.0624 \times 10^3$	83	79	$3.3701 \times 10^{-6}$
41	25	$-2.4525 \times 10^{1}$	33	44	$2.9153 \times 10^3$	84	79	$-1.7815 \times 10^{-5}$
42	25	$-8.1501 \times 10^2$	34	44	$9.3229 \times 10^{1}$	85	79	$-1.4445 \times 10^{-4}$
43	25	$-2.9747 \times 10^3$	35	44	$-3.6820 \times 10^2$	90	79	$-1.4445 \times 10^{-5}$
44	25	$5.9167 \times 10^{-5}$	36	44	$2.1475 \times 10^2$	38	80	$3.2361 \times 10^{-6}$
46	25	$1.1833 \times 10^{-5}$	37	44	$-1.4576 \times 10^3$	39	80	$1.4410 \times 10^{-5}$
47	25	$5.9494 \times 10^2$	38	44	$3.0624 \times 10^3$	40	80	$-7.2050 \times 10^{-7}$
48	25	$2.1971 \times 10^{-5}$	39	44	$-2.9153 \times 10^3$	41	80	$-1.4410 \times 10^{-6}$
25	26	$-5.9167 \times 10^{-5}$	40	44	$9.3229 \times 10^{1}$	42	80	$3.2361 \times 10^{-7}$
26	26	$1.0709 \times 10^3$	41	44	$3.6820 \times 10^2$	46	80	$9.8100 \times 10^{0}$
28	26	$3.0627 \times 10^{1}$	42	44	$2.1475 \times 10^2$	48	80	$6.4480 \times 10^{-11}$
29	26	$1.6922 \times 10^{-6}$	43	44	$-7.9534 \times 10^{-5}$	80	80	$1.4121 \times 10^{-4}$
34	26	$2.4525 \times 10^{1}$	44	44	$-9.8162 \times 10^3$	81	80	$-1.4410 \times 10^{-5}$
36	26	$6.0683 \times 10^2$	45	44	$5.3713 \times 10^{-7}$	82	80	$5.5870 \times 10^{-7}$
40	26	$2.4525 \times 10^{1}$	46	44	$-4.6978 \times 10^3$	86	80	$-1.4445 \times 10^{-4}$
42	26	$6.0683 \times 10^2$	47	44	$1.1486 \times 10^{-4}$	90	80	$1.4445 \times 10^{-5}$
43	26	$5.9167 \times 10^{-5}$	48	44	$2.6736 \times 10^3$	38	81	$1.4410 \times 10^{-5}$
43	26	$-1.0709 \times 10^3$	88	44	$-9.8100 \times 10^{0}$	39	81	$6.4167 \times 10^{-5}$
46	26	$-2.1418 \times 10^2$	90	44	$3.2209 \times 10^{-10}$	40	81	$-3.2083 \times 10^{-6}$
47	26	$-2.1418 \times 10$ $-1.1833 \times 10^{-5}$	1	45	$-5.7901 \times 10^3$	41	81	$-6.4167 \times 10^{-6}$
48	26 26	$-3.9765 \times 10^2$	2	45	$6.5721 \times 10^{-5}$	42	81	$-0.4107 \times 10^{-6}$ $1.4410 \times 10^{-6}$
27	20 27	$-3.9763 \times 10$ $4.0456 \times 10^3$	3	45	$-1.7531 \times 10^3$	46	81	$2.3593 \times 10^{-5}$
		$-8.1501 \times 10^2$		45 45	$6.9062 \times 10^{-5}$			$-6.4480 \times 10^{-11}$
34 35	27 27	$-8.1501 \times 10$ $-6.0683 \times 10^2$	4 5	45 45	$1.5998 \times 10^2$	47 80	81 81	$-6.4480 \times 10$ $-1.4410 \times 10^{-5}$
					$3.5358 \times 10^{-5}$			$-6.4167 \times 10^{-5}$
40	27	$8.1501 \times 10^2$ $-6.0683 \times 10^2$	6 9	45	$3.5358 \times 10^{-3}$ $-1.5136 \times 10^{2}$	81	81	
41	27			45		82	81	$2.4878 \times 10^{-6}$ $-5.5870 \times 10^{-7}$
45	27	$-4.0456 \times 10^3$ $-6.7056 \times 10^{-5}$	10	45	$7.5680 \times 10^{0}$	38	82	
46	27		11	45	$-1.5136 \times 10^{1}$	39	82	$-2.4878 \times 10^{-6}$
47	27	$-1.8690 \times 10^3$	15	45	$-1.5136 \times 10^{2}$	40	82	$1.2439 \times 10^{-7}$
25	28	$-1.6922 \times 10^{-6}$	16	45	$-7.5680 \times 10^{0}$	41	82	$2.4878 \times 10^{-7}$
26	28	$3.0627 \times 10^{1}$	17	45	$-1.5136 \times 10^1$	42	82	$-5.5870 \times 10^{-8}$

27	28	$1.0978 \times 10^{-9}$	27	45	$-4.0456 \times 10^3$	80	82	$5.6043 \times 10^{-7}$
28	28	$8.9738 \times 10^2$	31	45	$-2.9153 \times 10^3$	81	82	$2.4862 \times 10^{-6}$
29	28	$3.1927 \times 10^{-6}$	32	45	$2.9153 \times 10^3$	82	82	$-1.0111 \times 10^{-6}$
30	28	$3.4711 \times 10^{1}$	33	45	$-1.3106 \times 10^3$	83	82	$2.0249 \times 10^{-9}$
34	28	$-4.4825 \times 10^2$	34	45	$4.4043 \times 10^2$	84	82	$1.9698 \times 10^{-10}$
35	28	$-3.3376 \times 10^2$	35	45	$5.0416 \times 10^2$	37	83	$-3.3701 \times 10^{-6}$
40	28	$-4.4825 \times 10^2$	36	45	$3.4984 \times 10^{1}$	42	83	$-1.6851 \times 10^{-7}$
41	28	$3.3376 \times 10^{2}$	37	45	$-2.9153 \times 10^3$	79	83	$3.3684 \times 10^{-6}$
43	28	$1.6922 \times 10^{-6}$	38	45	$-2.9153 \times 10^3$	81	83	$6.4480 \times 10^{-11}$
44	28	$-3.0627 \times 10^{1}$	39	45	$-1.3106 \times 10^3$	83	83	$9.6386 \times 10^{-8}$
46	28	$-6.1255 \times 10^{0}$	40	45	$-4.4043 \times 10^2$	84	83	$1.3481 \times 10^{-6}$
47	28	$-3.3844 \times 10^{-7}$	41	45	$5.0416 \times 10^2$	37	84	$3.3701 \times 10^{-6}$
48	28	$-1.1373 \times 10^{1}$	42	45	$-3.4984 \times 10^{1}$	42	84	$1.6851 \times 10^{-7}$
25	29	$-8.5076 \times 10^{1}$	43	45	$1.1621 \times 10^4$	79	84	$-1.7813 \times 10^{-5}$
26	29	$1.6922 \times 10^{-6}$	44	45	$5.3713 \times 10^{-7}$	80	84	$-6.4480 \times 10^{-11}$
27	29	$5.3933 \times 10^{-10}$	45	45	$8.7225 \times 10^3$	83	84	$1.3481 \times 10^{-6}$
28	29	$3.1896 \times 10^{-6}$	46	45	$-8.5648 \times 10^{-5}$	84	84	$9.6444 \times 10^{-8}$
29	29	$2.4332 \times 10^{0}$	47	45	$8.0113 \times 10^2$	85	84	$1.4445 \times 10^{-5}$
30	29	$1.9175 \times 10^{-6}$	48	45	$-9.8689 \times 10^{-5}$	90	84	$1.4445 \times 10^{-6}$
43	29	$8.5076 \times 10^{1}$	88	45	$-8.5724 \times 10^{-10}$	73	85	$1.4445 \times 10^{-4}$
44	29	$-1.6922 \times 10^{-6}$	89	45	$-3.2209 \times 10^{-10}$	78	85	$1.4445 \times 10^{-5}$
46	29	$-3.3844 \times 10^{-7}$	1	46	$-2.2161 \times 10^{-5}$	79	85	$-1.4445 \times 10^{-4}$
47	29	$-1.7015 \times 10^{1}$	2	46	$2.5602 \times 10^3$	84	85	$1.4445 \times 10^{-5}$
48	29	$-6.2836 \times 10^{-7}$	3	46	$7.9686 \times 10^{-5}$	85	85	$-1.1778 \times 10^{-9}$
25	30	$-1.0978 \times 10^{-9}$	4	46	$-1.0754 \times 10^3$	89	85	$-9.8100 \times 10^{0}$
26	30	$-5.3933 \times 10^{-10}$	5	46	$-9.9896 \times 10^{-7}$	90	85	$2.8889 \times 10^{-5}$
28	30	$3.4711 \times 10^{1}$	6	46	$1.2460 \times 10^3$	74	86	$1.4445 \times 10^{-4}$
29	30	$1.9178 \times 10^{-6}$	9	46	$-1.5136 \times 10^{1}$	80	86	$-1.4445 \times 10^{-4}$
30	30	$8.9651 \times 10^2$	10	46	$7.5680 \times 10^{-1}$	86	86	$-1.1778 \times 10^{-9}$
35	30	$1.3489 \times 10^{1}$	11	46	$-1.5136 \times 10^{0}$	88	86	$9.8100 \times 10^{0}$
36	30	$-4.4825 \times 10^2$	15	46	$1.5136 \times 10^{1}$	90	86	$-2.0431 \times 10^{-10}$
41	30	$-1.3489 \times 10^{1}$	16	46	$7.5680 \times 10^{-1}$	88	87	$8.5724 \times 10^{-10}$
42	30	$-4.4825 \times 10^2$	17	46	$1.5136 \times 10^{0}$	89	87	$3.2209 \times 10^{-10}$
31	31	$-2.2882 \times 10^3$	25	46	$1.1833 \times 10^{-5}$	86	88	$9.3060 \times 10^{-10}$
32	31	$-1.4576 \times 10^3$	26	46	$-2.1418 \times 10^2$	87	88	$-8.5724 \times 10^{-10}$
33	31	$2.9153 \times 10^3$	27	46	$-6.7056 \times 10^{-5}$	90	88	$-1.1778 \times 10^{-11}$
34	31	$-3.3322 \times 10^2$	28	46	$-6.1255 \times 10^{0}$	85	89	$-9.3060 \times 10^{-10}$
35	31	$-6.3566 \times 10^2$	29	46	$-3.3844 \times 10^{-7}$	87	89	$-3.2209 \times 10^{-10}$
36	31	$-5.7937 \times 10^2$	31	46	$-1.1661 \times 10^3$	88	89	$-2.0241 \times 10^{-9}$
43	31	$2.2882 \times 10^3$	32	46	$1.1661 \times 10^3$	90	89	$-1.3345 \times 10^{-9}$
44	31	$1.4576 \times 10^3$	33	46	$-4.4681 \times 10^2$	73	90	$-1.4445 \times 10^{-5}$
45	31	$-2.9153 \times 10^3$	33 34	46	$-4.4031 \times 10^{2}$ $1.7230 \times 10^{2}$	73 74	90	$-1.4445 \times 10^{-5}$
46	31	$-1.1661 \times 10^3$	35	46	$1.7230 \times 10^{-2}$ $2.0166 \times 10^{2}$	7 <del>4</del> 78	90	$-1.4445 \times 10^{-6}$
47	31	$-1.7492 \times 10^3$	36	46	$1.3993 \times 10^{1}$	79	90	$-1.4445 \times 10^{-5}$
		$-1.7899 \times 10^3$	37		$1.3993 \times 10^{3}$ $1.1661 \times 10^{3}$			$-1.4443 \times 10^{-5}$ $1.4445 \times 10^{-5}$
48 73	31 31	$-6.7406 \times 10^{-5}$	38	46 46	$1.1661 \times 10^{3}$ $1.1661 \times 10^{3}$	80 84	90 90	$1.4445 \times 10^{-6}$ $1.4445 \times 10^{-6}$
		$-6.7406 \times 10^{-6}$ $3.3703 \times 10^{-6}$	38 39		$4.4681 \times 10^{3}$ $4.4681 \times 10^{2}$			$1.4445 \times 10^{-5}$ $2.8891 \times 10^{-5}$
77 78	31	$3.3703 \times 10^{-6}$ $3.3703 \times 10^{-6}$	39 40	46	$4.4681 \times 10^{-1}$ $1.7230 \times 10^{2}$	85 86	90	$4.3987 \times 10^{-10}$
78	31	$-1.4576 \times 10^3$	40 41	46	$-2.0166 \times 10^{2}$	86	90	$-2.3556 \times 10^{-11}$
31	32	$-1.45/6 \times 10^{3}$ $-3.0624 \times 10^{3}$	41 42	46	$-2.0166 \times 10^{2}$ $1.3993 \times 10^{1}$	90	90	-2.3336 X 10 11
32	32	$-3.0624 \times 10^{3}$ $-2.9153 \times 10^{3}$		46	$-1.6175 \times 10^{-5}$	_	_	_
33	32	-2.9155 X 10°	43	46	$-1.01/5 \times 10^{-3}$			

The velocity matrix is

_	Row	Column	Value	Row	Column	Value	Row	Column	Value	
University	y of Wii	ndsor					au	tomatically	generated	ł by EoM
Vehicle D	ynamic	s and Control	l Research Grou	p	17				Septembe	r 15, 2015

1 1 0.0000 >	$< 10^0 -$	_	_	-	-	-	
--------------	------------	---	---	---	---	---	--

#### The input force matrix is

Row	Column	Value	Row	Column	Value	Row	Column	Value
3	1	$1.0000 \times 10^5$	4	1	$6.0000 \times 10^4$	46	2	$-1.0000 \times 10^3$

The system is subject to constraints

$$\begin{bmatrix} J_h & 0 \\ -J_h V & J_h \\ 0 & J_{nh} \end{bmatrix} \begin{bmatrix} \dot{\boldsymbol{p}} & \boldsymbol{p} \\ \dot{\boldsymbol{w}} & \boldsymbol{w} \end{bmatrix} = \begin{bmatrix} 0 & 0 \\ 0 & 0 \\ 0 & 0 \end{bmatrix}$$

Row	Column	Value	Row	Column	Value	Row	Column	Value
1	1	$-6.0000 \times 10^{-1}$	73	46	$-2.0000 \times 10^{-1}$	148	118	$5.5000 \times 10^{-1}$
2	1	$-6.0000 \times 10^{-1}$	77	46	$-1.0000 \times 10^{-1}$	153	118	$-5.5000 \times 10^{-1}$
3	1	$-1.0000 \times 10^{0}$	78	46	$2.0000 \times 10^{-1}$	92	119	$-1.4715 \times 10^{-2}$
4	1	$-1.0000 \times 10^{0}$	82	46	$2.0000 \times 10^{-1}$	93	119	$-1.4715 \times 10^{-2}$
41	1	$1.0000 \times 10^{0}$	84	46	$-1.0000 \times 10^{0}$	149	119	$1.0000 \times 10^{0}$
46	1	$1.0000 \times 10^{0}$	1	47	$-1.2000 \times 10^{-1}$	154	119	$1.0000 \times 10^{0}$
1	2	$-8.0000 \times 10^{-1}$	2	47	$-1.2000 \times 10^{-1}$	146	120	$-5.5000 \times 10^{-1}$
2	2	$8.0000 \times 10^{-1}$	7	47	$1.0290 \times 10^{-1}$	150	120	$1.0000 \times 10^{0}$
42	2	$1.0000 \times 10^{0}$	8	47	$1.0290 \times 10^{-1}$	151	120	$5.5000 \times 10^{-1}$
47	2	$1.0000 \times 10^{0}$	71	47	$1.0000 \times 10^{-1}$	155	120	$1.0000 \times 10^{0}$
43	3	$1.0000 \times 10^{0}$	73	47	$-6.6200 \times 10^{-1}$	95	121	$1.0000 \times 10^{0}$
48	3	$1.0000 \times 10^{0}$	74	47	$-1.0000 \times 10^0$	116	121	$-1.0000 \times 10^0$
42	4	$-1.2860 \times 10^{-1}$	76	47	$1.0000 \times 10^{-1}$	136	121	$-1.0000 \times 10^{0}$
43	4	$5.5000 \times 10^{-1}$	78	47	$-6.6200 \times 10^{-1}$	146	121	$-1.0000 \times 10^0$
44	4	$9.7063 \times 10^{-1}$	79	47	$-1.0000 \times 10^{0}$	96	122	$-9.7570 \times 10^{-1}$
45	4	$-1.7011 \times 10^{-1}$	81	47	$-2.0000 \times 10^{-1}$	117	122	$-1.0000 \times 10^0$
47	4	$-1.2860 \times 10^{-1}$	83	47	$5.6200 \times 10^{-1}$	137	122	$-1.0000 \times 10^{0}$
48	4	$-5.5000 \times 10^{-1}$	1	48	$6.0960 \times 10^{-1}$	147	122	$-1.0000 \times 10^{0}$
49	4	$9.7063 \times 10^{-1}$	2	48	$-6.0960 \times 10^{-1}$	96	123	$-2.1911 \times 10^{-1}$
50	4	$1.7011 \times 10^{-1}$	3	48	$5.0000 \times 10^{-1}$	118	123	$-1.0000 \times 10^0$
3	5	$-2.0000 \times 10^{-1}$	4	48	$-5.0000 \times 10^{-1}$	138	123	$-1.0000 \times 10^0$
4	5	$-2.0000 \times 10^{-1}$	5	48	$6.6200 \times 10^{-1}$	148	123	$-1.0000 \times 10^0$
41	5	$1.2860 \times 10^{-1}$	6	48	$-6.6200 \times 10^{-1}$	96	124	$-1.0956 \times 10^{-2}$
44	5	$1.4111 \times 10^{-1}$	7	48	$-6.5341 \times 10^{-1}$	118	124	$-5.0000 \times 10^{-2}$
45	5	$9.7527 \times 10^{-1}$	8	48	$6.5341 \times 10^{-1}$	119	124	$1.0000 \times 10^{0}$
46	5	$1.2860 \times 10^{-1}$	9	48	$-5.0000 \times 10^{-1}$	137	124	$1.0000 \times 10^{-1}$
49	5	$-1.4111 \times 10^{-1}$	10	48	$5.0000 \times 10^{-1}$	147	124	$-1.0000 \times 10^{-1}$
50	5	$9.7527 \times 10^{-1}$	71	48	$2.0000 \times 10^{-1}$	95	125	$7.1400 \times 10^{-2}$
3	6	$-5.0000 \times 10^{-1}$	72	48	$6.6200 \times 10^{-1}$	96	125	$2.1911 \times 10^{-2}$
4	6	$5.0000 \times 10^{-1}$	75	48	$-1.0000 \times 10^0$	136	125	$-1.0000 \times 10^{-1}$
41	6	$-5.5000 \times 10^{-1}$	76	48	$-2.0000 \times 10^{-1}$	139	125	$-1.0000 \times 10^0$
44	6	$1.9484 \times 10^{-1}$	77	48	$6.6200 \times 10^{-1}$	146	125	$1.0000 \times 10^{-1}$
45	6	$1.4111 \times 10^{-1}$	80	48	$-1.0000 \times 10^0$	149	125	$-1.0000 \times 10^0$
46	6	$5.5000 \times 10^{-1}$	82	48	$-5.6200 \times 10^{-1}$	95	126	$5.0000 \times 10^{-2}$

University of Windsor

automatically generated by EoM

49	6	$1.9484 \times 10^{-1}$	85	48	$1.0000 \times 10^{0}$	96	126	$-9.7570 \times 10^{-2}$
50	6	$-1.4111 \times 10^{-1}$	16	49	$-1.0000 \times 10^0$	116	126	$5.0000 \times 10^{-2}$
21	7	$-1.0000 \times 10^0$	21	49	$1.0000 \times 10^{0}$	120	126	$-1.0000 \times 10^0$
41	7	$-1.0000 \times 10^0$	15	50	$1.0000 \times 10^{0}$	140	126	$-1.0000 \times 10^{0}$
5	8	$-1.0000 \times 10^0$	22	50	$1.0000 \times 10^{0}$	150	126	$-1.0000 \times 10^0$
22	8	$-1.0000 \times 10^0$	23	51	$1.0000 \times 10^{0}$	94	127	$1.0000 \times 10^{0}$
42	8	$-1.0000 \times 10^0$	15	52	$2.2860 \times 10^{-1}$	121	127	$-1.0000 \times 10^0$
23	9	$-1.0000 \times 10^0$	24	52	$-1.0000 \times 10^0$	141	127	$-1.0000 \times 10^0$
43	9	$-1.0000 \times 10^0$	16	53	$2.2860 \times 10^{-1}$	151	127	$-1.0000 \times 10^{0}$
5	10	$-7.8600 \times 10^{-2}$	25	54	$1.0000 \times 10^{0}$	97	128	$9.7570 \times 10^{-1}$
23	10	$-5.0000 \times 10^{-2}$	17	55	$1.0000 \times 10^{0}$	122	128	$-1.0000 \times 10^0$
24	10	$1.0000 \times 10^{0}$	26	55	$1.0000 \times 10^{0}$	142	128	$-1.0000 \times 10^0$
44	10	$-9.7063 \times 10^{-1}$	27	56	$1.0000 \times 10^{0}$	152	128	$-1.0000 \times 10^0$
45	10	$1.7011 \times 10^{-1}$	28	57	$1.0000 \times 10^{0}$	97	129	$-2.1911 \times 10^{-1}$
44	11	$-1.4111 \times 10^{-1}$	29	58	$-1.0000 \times 10^0$	123	129	$-1.0000 \times 10^{0}$
45	11	$-9.7527 \times 10^{-1}$	17	59	$-2.2860 \times 10^{-1}$	143	129	$-1.0000 \times 10^0$
5	12	$1.0000 \times 10^{-1}$	30	60	$1.0000 \times 10^{0}$	153	129	$-1.0000 \times 10^0$
21	12	$5.0000 \times 10^{-2}$	20	61	$1.0000 \times 10^{0}$	97	130	$1.0956 \times 10^{-2}$
25	12	$-1.0000 \times 10^0$	31	61	$1.0000 \times 10^{0}$	123	130	$5.0000 \times 10^{-2}$
44	12	$-1.9484 \times 10^{-1}$	32	62	$1.0000 \times 10^{0}$	124	130	$1.0000 \times 10^{0}$
45	12	$-1.4111 \times 10^{-1}$	33	63	$1.0000 \times 10^{0}$	142	130	$1.0000 \times 10^{-1}$
26	13	$-1.0000 \times 10^0$	34	64	$-1.0000 \times 10^0$	152	130	$-1.0000 \times 10^{-1}$
46	13	$-1.0000 \times 10^0$	20	65	$-2.2860 \times 10^{-1}$	94	131	$7.1400 \times 10^{-2}$
6	14	$1.0000 \times 10^{0}$	35	66	$1.0000 \times 10^{0}$	97	131	$2.1911 \times 10^{-2}$
27	14	$-1.0000 \times 10^0$	19	67	$-1.0000 \times 10^{0}$	141	131	$-1.0000 \times 10^{-1}$
47	14	$-1.0000 \times 10^0$	36	67	$1.0000 \times 10^{0}$	144	131	$-1.0000 \times 10^0$
28	15	$-1.0000 \times 10^{0}$	18	68	$1.0000 \times 10^{0}$	151	131	$1.0000 \times 10^{-1}$
48	15	$-1.0000 \times 10^0$	37	68	$1.0000 \times 10^{0}$	154	131	$-1.0000 \times 10^0$
6	16	$7.8600 \times 10^{-2}$	38	69	$1.0000 \times 10^{0}$	94	132	$-5.0000 \times 10^{-2}$
28	16	$5.0000 \times 10^{-2}$	18	70	$2.2860 \times 10^{-1}$	97	132	$9.7570 \times 10^{-2}$
29	16	$1.0000 \times 10^{0}$	39	70	$-1.0000 \times 10^{0}$	121	132	$-5.0000 \times 10^{-2}$
49	16	$-9.7063 \times 10^{-1}$	19	71	$2.2860 \times 10^{-1}$	125	132	$-1.0000 \times 10^{0}$
50	16	$-1.7011 \times 10^{-1}$	40	72	$1.0000 \times 10^{0}$	145	132	$-1.0000 \times 10^{0}$
49	17	$1.4111 \times 10^{-1}$	71	73	$1.0000 \times 10^{0}$	155	132	$-1.0000 \times 10^{0}$
50	17	$-9.7527 \times 10^{-1}$	11	74	$9.7570 \times 10^{-1}$	86	133	$6.0000 \times 10^{-1}$
6	18	$-1.0000 \times 10^{-1}$	72	74	$1.0000 \times 10^{0}$	87	133	$6.0000 \times 10^{-1}$
26	18	$-5.0000 \times 10^{-2}$	11	75	$2.1911 \times 10^{-1}$	88	133	$1.0000 \times 10^{0}$
30	18	$-1.0000 \times 10^{0}$	13	75	$-1.0000 \times 10^{0}$	89	133	$1.0000 \times 10^{0}$
49	18	$-1.9484 \times 10^{-1}$	73	75	$1.0000 \times 10^{0}$	92	133	$-5.1450 \times 10^{-1}$
50	18	$1.4111 \times 10^{-1}$	11	76	$5.9741 \times 10^{-2}$	93	133	$-5.1450 \times 10^{-1}$
51	19	$1.0000 \times 10^{0}$	13	76	$1.0000 \times 10^{-1}$	94	133	$-1.0000 \times 10^{0}$
56	19	$1.0000 \times 10^{0}$	74	77	$1.0000 \times 10^{0}$	95	133	$-1.0000 \times 10^{0}$
52	20	$1.0000 \times 10^{0}$	75	78	$1.0000 \times 10^{0}$	156	133	$-1.0000 \times 10^{0}$
57	20	$1.0000 \times 10^{0}$	76	79	$1.0000 \times 10^{0}$	161	133	$-1.0000 \times 10^{0}$
53	21	$1.0000 \times 10^{0}$	12	80	$-9.7570 \times 10^{-1}$	166	133	$1.0000 \times 10^{0}$
58	21	$1.0000 \times 10^{0}$	77	80	$1.0000 \times 10^{0}$	86	134	$8.0000 \times 10^{-1}$
53	22	$5.5000 \times 10^{-1}$	12	81	$2.1911 \times 10^{-1}$	87	134	$-8.0000 \times 10^{-1}$
58	22	$-5.5000 \times 10^{-1}$	14	81	$-1.0000 \times 10^{0}$	90	134	$1.0000 \times 10^{0}$
54	23	$1.0000 \times 10^{0}$	78	81	$1.0000 \times 10^{0}$	91	134	$-1.0000 \times 10^{0}$
59	23	$1.0000 \times 10^{0}$	12	82	$-5.9741 \times 10^{-2}$	92	134	$8.5749 \times 10^{-1}$
51	24	$-5.5000 \times 10^{-1}$	14	82	$-1.0000 \times 10^{-1}$	93	134	$-8.5749 \times 10^{-1}$
55	24	$1.0000 \times 10^{0}$	79	83	$1.0000 \times 10^{0}$	157	134	$-1.0000 \times 10^{0}$
56	24	$5.5000 \times 10^{-1}$	80	84	$1.0000 \times 10^{0}$	162	134	$-1.0000 \times 10^{0}$
60	24	$1.0000 \times 10^{0}$	81	85	$-1.0000 \times 10^{0}$	167	134	$1.0000 \times 10^{0}$
7	25	$5.1450 \times 10^{-1}$	82	86	$-1.0000 \times 10^{0}$	158	135	$-1.0000 \times 10^{0}$
8	25	$5.1450 \times 10^{-1}$	13	87	$1.0000 \times 10^{0}$	163	135	$-1.0000 \times 10^{0}$
61	25	$1.0000 \times 10^{0}$	14	87	$1.0000 \times 10^{0}$	168	135	$1.0000 \times 10^{0}$
66	25	$1.0000 \times 10^{0}$	83	87	$-1.0000 \times 10^0$	86	136	$1.6000 \times 10^{-1}$

7	26	$-8.5749 \times 10^{-1}$	13	88	$1.0000 \times 10^{-1}$	87	136	$-1.6000 \times 10^{-1}$
8	26	$8.5749 \times 10^{-1}$	14	88	$-1.0000 \times 10^{-1}$	90	136	$1.5000 \times 10^{-1}$
62	26	$1.0000 \times 10^{0}$	84	88	$1.0000 \times 10^{0}$	91	136	$-1.5000 \times 10^{-1}$
67	26	$1.0000 \times 10^{0}$	13	89	$1.0000 \times 10^{-1}$	92	136	$1.7150 \times 10^{-1}$
63	27	$1.0000 \times 10^{0}$	14	89	$1.0000 \times 10^{-1}$	93	136	$-1.7150 \times 10^{-1}$
68	27	$1.0000 \times 10^{0}$	85	90	$-1.0000 \times 10^{0}$	157	136	$-1.0000 \times 10^{-1}$
7	28	$-2.4524 \times 10^{-2}$	86	91	$-6.0000 \times 10^{-1}$	158	136	$-2.0000 \times 10^{-1}$
8	28	$2.4524 \times 10^{-2}$	87	91	$-6.0000 \times 10^{-1}$	162	136	$-1.0000 \times 10^{-1}$
63	28	$5.5000 \times 10^{-1}$	88	91	$-1.0000 \times 10^{0}$	163	136	$2.0000 \times 10^{-1}$
68	28	$-5.5000 \times 10^{-1}$	89	91	$-1.0000 \times 10^{0}$	167	136	$2.0000 \times 10^{-1}$
7	29	$-1.4715 \times 10^{-2}$	126	91	$1.0000 \times 10^{0}$	169	136	$-1.0000 \times 10^{0}$
8	29	$-1.4715 \times 10^{-2}$	131	91	$1.0000 \times 10^{0}$	86	137	$-1.2000 \times 10^{-1}$
64	29	$1.0000 \times 10^{0}$	86	92	$-8.0000 \times 10^{-1}$	87	137	$-1.2000 \times 10^{-1}$
69	29	$1.0000 \times 10^{0}$	87	92	$8.0000 \times 10^{-1}$	92	137	$1.0290 \times 10^{-1}$
61	30	$-5.5000 \times 10^{-1}$	127	92	$1.0000 \times 10^{0}$	93	137	$1.0290 \times 10^{-1}$
65	30	$1.0000 \times 10^{0}$	132	92	$1.0000 \times 10^{0}$	156	137	$1.0000 \times 10^{-1}$
66	30	$5.5000 \times 10^{-1}$	128	93	$1.0000 \times 10^{0}$	158	137	$-6.6200 \times 10^{-1}$
70	30	$1.0000 \times 10^{0}$	133	93	$1.0000 \times 10^{0}$	159	137	$-1.0000 \times 10^0$
10	31	$1.0000 \times 10^{0}$	127	94	$-1.2860 \times 10^{-1}$	161	137	$1.0000 \times 10^{-1}$
31	31	$-1.0000 \times 10^0$	128	94	$5.5000 \times 10^{-1}$	163	137	$-6.6200 \times 10^{-1}$
51	31	$-1.0000 \times 10^{0}$	129	94	$9.7063 \times 10^{-1}$	164	137	$-1.0000 \times 10^{0}$
61	31	$-1.0000 \times 10^{0}$	130	94	$-1.7011 \times 10^{-1}$	166	137	$-2.0000 \times 10^{-1}$
11	32	$-9.7570 \times 10^{-1}$	132	94	$-1.2860 \times 10^{-1}$	168	137	$5.6200 \times 10^{-1}$
32	32	$-1.0000 \times 10^0$	133	94	$-5.5000 \times 10^{-1}$	86	138	$6.0960 \times 10^{-1}$
52	32	$-1.0000 \times 10^{0}$	134	94	$9.7063 \times 10^{-1}$	87	138	$-6.0960 \times 10^{-1}$
62	32	$-1.0000 \times 10^{0}$	135	94	$1.7011 \times 10^{-1}$	88	138	$5.0000 \times 10^{-1}$
11	33	$-2.1911 \times 10^{-1}$	88	95	$-2.0000 \times 10^{-1}$	89	138	$-5.0000 \times 10^{-1}$
33	33	$-1.0000 \times 10^{0}$	89	95	$-2.0000 \times 10^{-1}$	90	138	$6.6200 \times 10^{-1}$
53	33	$-1.0000 \times 10^0$	126	95	$1.2860 \times 10^{-1}$	91	138	$-6.6200 \times 10^{-1}$
63	33	$-1.0000 \times 10^{0}$	129	95	$1.4111 \times 10^{-1}$	92	138	$-6.5341 \times 10^{-1}$
11	34	$-1.0956 \times 10^{-2}$	130	95	$9.7527 \times 10^{-1}$	93	138	$6.5341 \times 10^{-1}$
33	34	$-5.0000 \times 10^{-2}$	131	95	$1.2860 \times 10^{-1}$	94	138	$-5.0000 \times 10^{-1}$
34	34	$1.0000 \times 10^{0}$	134	95	$-1.4111 \times 10^{-1}$	95	138	$5.0000 \times 10^{-1}$
52	34	$1.0000 \times 10^{-1}$	135	95	$9.7527 \times 10^{-1}$	156	138	$2.0000 \times 10^{-1}$
62	34	$-1.0000 \times 10^{-1}$	88	96	$-5.0000 \times 10^{-1}$	157	138	$6.6200 \times 10^{-1}$
10	35	$7.1400 \times 10^{-2}$	89	96	$5.0000 \times 10^{-1}$	160	138	$-1.0000 \times 10^0$
11	35	$2.1911 \times 10^{-2}$	126	96	$-5.5000 \times 10^{-1}$	161	138	$-2.0000 \times 10^{-1}$
51	35	$-1.0000 \times 10^{-1}$	129	96	$1.9484 \times 10^{-1}$	162	138	$6.6200 \times 10^{-1}$
54	35	$-1.0000 \times 10^0$	130	96	$1.4111 \times 10^{-1}$	165	138	$-1.0000 \times 10^0$
61	35	$1.0000 \times 10^{-1}$	131	96	$5.5000 \times 10^{-1}$	167	138	$-5.6200 \times 10^{-1}$
64	35	$-1.0000 \times 10^0$	134	96	$1.9484 \times 10^{-1}$	170	138	$1.0000 \times 10^{0}$
10	36	$5.0000 \times 10^{-2}$	135	96	$-1.4111 \times 10^{-1}$	101	139	$-1.0000 \times 10^{0}$
11	36	$-9.7570 \times 10^{-2}$	106	97	$-1.0000 \times 10^{0}$	106	139	$1.0000 \times 10^{0}$
31	36	$5.0000 \times 10^{-2}$	126	97	$-1.0000 \times 10^{0}$	100	140	$1.0000 \times 10^{0}$
35	36	$-1.0000 \times 10^0$	90	98	$-1.0000 \times 10^0$	107	140	$1.0000 \times 10^{0}$
55	36	$-1.0000 \times 10^{0}$	107	98	$-1.0000 \times 10^0$	108	141	$1.0000 \times 10^{0}$
65	36	$-1.0000 \times 10^0$	127	98	$-1.0000 \times 10^0$	100	142	$2.2860 \times 10^{-1}$
9	37	$1.0000 \times 10^{0}$	108	99	$-1.0000 \times 10^0$	109	142	$-1.0000 \times 10^0$
36	37	$-1.0000 \times 10^{0}$	128	99	$-1.0000 \times 10^{0}$	101	143	$2.2860 \times 10^{-1}$
56	37	$-1.0000 \times 10^{0}$	90	100	$-7.8600 \times 10^{-2}$	110	144	$1.0000 \times 10^{0}$
66	37	$-1.0000 \times 10^{0}$	108	100	$-5.0000 \times 10^{-2}$	102	145	$1.0000 \times 10^{0}$
12	38	$9.7570 \times 10^{-1}$	109	100	$1.0000 \times 10^{0}$	111	145	$1.0000 \times 10^{0}$
37	38	$-1.0000 \times 10^{0}$	129	100	$-9.7063 \times 10^{-1}$	112	146	$1.0000 \times 10^{0}$
57	38	$-1.0000 \times 10^{0}$	130	100	$1.7011 \times 10^{-1}$	113	147	$1.0000 \times 10^{0}$
67	38	$-1.0000 \times 10^{0}$	129	101	$-1.4111 \times 10^{-1}$	114	148	$-1.0000 \times 10^0$
12	39	$-2.1911 \times 10^{-1}$	130	101	$-9.7527 \times 10^{-1}$	102	149	$-2.2860 \times 10^{-1}$
38	39	$-1.0000 \times 10^{0}$	90	102	$1.0000 \times 10^{-1}$	115	150	$1.0000 \times 10^{0}$
58	39	$-1.0000 \times 10^0$	106	102	$5.0000 \times 10^{-2}$	105	151	$1.0000 \times 10^{0}$

68	39	$-1.0000 \times 10^{0}$	110	102	$-1.0000 \times 10^{0}$	116	151	$1.0000 \times 10^{0}$
12	40	$1.0956 \times 10^{-2}$	129	102	$-1.9484 \times 10^{-1}$	117	152	$1.0000 \times 10^{0}$
38	40	$5.0000 \times 10^{-2}$	130	102	$-1.4111 \times 10^{-1}$	118	153	$1.0000 \times 10^{0}$
39	40	$1.0000 \times 10^{0}$	111	103	$-1.0000 \times 10^{0}$	119	154	$-1.0000 \times 10^{0}$
57	40	$1.0000 \times 10^{-1}$	131	103	$-1.0000 \times 10^{0}$	105	155	$-2.2860 \times 10^{-1}$
67	40	$-1.0000 \times 10^{-1}$	91	104	$1.0000 \times 10^{0}$	120	156	$1.0000 \times 10^{0}$
9	41	$7.1400 \times 10^{-2}$	112	104	$-1.0000 \times 10^{0}$	104	157	$-1.0000 \times 10^{0}$
12	41	$2.1911 \times 10^{-2}$	132	104	$-1.0000 \times 10^0$	121	157	$1.0000 \times 10^{0}$
56	41	$-1.0000 \times 10^{-1}$	113	105	$-1.0000 \times 10^0$	103	158	$1.0000 \times 10^{0}$
59	41	$-1.0000 \times 10^0$	133	105	$-1.0000 \times 10^0$	122	158	$1.0000 \times 10^{0}$
66	41	$1.0000 \times 10^{-1}$	91	106	$7.8600 \times 10^{-2}$	123	159	$1.0000 \times 10^{0}$
69	41	$-1.0000 \times 10^0$	113	106	$5.0000 \times 10^{-2}$	103	160	$2.2860 \times 10^{-1}$
9	42	$-5.0000 \times 10^{-2}$	114	106	$1.0000 \times 10^{0}$	124	160	$-1.0000 \times 10^0$
12	42	$9.7570 \times 10^{-2}$	134	106	$-9.7063 \times 10^{-1}$	104	161	$2.2860 \times 10^{-1}$
36	42	$-5.0000 \times 10^{-2}$	135	106	$-1.7011 \times 10^{-1}$	125	162	$1.0000 \times 10^{0}$
40	42	$-1.0000 \times 10^{0}$	134	107	$1.4111 \times 10^{-1}$	156	163	$1.0000 \times 10^{0}$
60	42	$-1.0000 \times 10^{0}$	135	107	$-9.7527 \times 10^{-1}$	96	164	$9.7570 \times 10^{-1}$
70	42	$-1.0000 \times 10^{0}$	91	108	$-1.0000 \times 10^{-1}$	157	164	$1.0000 \times 10^{0}$
1	43	$6.0000 \times 10^{-1}$	111	108	$-5.0000 \times 10^{-2}$	96	165	$2.1911 \times 10^{-1}$
2	43	$6.0000 \times 10^{-1}$	115	108	$-1.0000 \times 10^{0}$	98	165	$-1.0000 \times 10^{0}$
3	43	$1.0000 \times 10^{0}$	134	108	$-1.9484 \times 10^{-1}$	158	165	$1.0000 \times 10^{0}$
4	43	$1.0000 \times 10^{0}$	135	108	$1.4111 \times 10^{-1}$	96	166	$5.9741 \times 10^{-2}$
7	43	$-5.1450 \times 10^{-1}$	136	109	$1.0000 \times 10^{0}$	98	166	$1.0000 \times 10^{-1}$
8	43	$-5.1450 \times 10^{-1}$	141	109	$1.0000 \times 10^{0}$	159	167	$1.0000 \times 10^{0}$
9	43	$-1.0000 \times 10^{0}$	137	110	$1.0000 \times 10^{0}$	160	168	$1.0000 \times 10^{0}$
10	43	$-1.0000 \times 10^{0}$	142	110	$1.0000 \times 10^{0}$	161	169	$1.0000 \times 10^{0}$
71	43	$-1.0000 \times 10^{0}$	138	111	$1.0000 \times 10^{0}$	97	170	$-9.7570 \times 10^{-1}$
76	43	$-1.0000 \times 10^{0}$	143	111	$1.0000 \times 10^{0}$	162	170	$1.0000 \times 10^{0}$
81	43	$1.0000 \times 10^{0}$	138	112	$5.5000 \times 10^{-1}$	97	171	$2.1911 \times 10^{-1}$
1	44	$8.0000 \times 10^{-1}$	143	112	$-5.5000 \times 10^{-1}$	99	171	$-1.0000 \times 10^{0}$
2	44	$-8.0000 \times 10^{-1}$	139	113	$1.0000 \times 10^{0}$	163	171	$1.0000 \times 10^{0}$
5	44	$1.0000 \times 10^{0}$	144	113	$1.0000 \times 10^{0}$	97	172	$-5.9741 \times 10^{-2}$
6	44	$-1.0000 \times 10^{0}$	136	114	$-5.5000 \times 10^{-1}$	99	172	$-1.0000 \times 10^{-1}$
7	44	$8.5749 \times 10^{-1}$	140	114	$1.0000 \times 10^{0}$	164	173	$1.0000 \times 10^{0}$
8	44	$-8.5749 \times 10^{-1}$	141	114	$5.5000 \times 10^{-1}$	165	174	$1.0000 \times 10^{0}$
72	44	$-1.0000 \times 10^{0}$	145	114	$1.0000 \times 10^{0}$	166	175	$-1.0000 \times 10^{0}$
77	44	$-1.0000 \times 10^{0}$	92	115	$5.1450 \times 10^{-1}$	167	176	$-1.0000 \times 10^{0}$
82	44	$1.0000 \times 10^{0}$	93	115	$5.1450 \times 10^{-1}$	98	177	$1.0000 \times 10^{0}$
73	45	$-1.0000 \times 10^{0}$	146	115	$1.0000 \times 10^{0}$	99	177	$1.0000 \times 10^{0}$
78	45	$-1.0000 \times 10^{0}$	151	115	$1.0000 \times 10^{0}$ $1.0000 \times 10^{0}$	168	177	$-1.0000 \times 10^{0}$
83	45	$1.0000 \times 10^{0}$ $1.0000 \times 10^{0}$	92	116	$-8.5749 \times 10^{-1}$	98	178	$1.0000 \times 10^{-1}$ $1.0000 \times 10^{-1}$
1	46	$1.6000 \times 10^{-1}$ $1.6000 \times 10^{-1}$	93	116	$8.5749 \times 10^{-1}$	99	178	$-1.0000 \times 10^{-1}$
2	46	$-1.6000 \times 10^{-1}$	147	116	$1.0000 \times 10^{0}$	169	178	$1.0000 \times 10^{0}$ $1.0000 \times 10^{0}$
5	46	$1.5000 \times 10^{-1}$	152	116	$1.0000 \times 10^{-0}$ $1.0000 \times 10^{0}$	98	178	$1.0000 \times 10^{-1}$ $1.0000 \times 10^{-1}$
6	46	$-1.5000 \times 10^{-1}$	148	116	$1.0000 \times 10^{-0}$ $1.0000 \times 10^{0}$	90 99	179	$1.0000 \times 10^{-1}$ $1.0000 \times 10^{-1}$
7	46	$-1.5000 \times 10^{-1}$ $1.7150 \times 10^{-1}$	153	117	$1.0000 \times 10^{-0}$ $1.0000 \times 10^{0}$	99 170	180	$-1.0000 \times 10^{0}$ $-1.0000 \times 10^{0}$
8	46	$-1.7150 \times 10^{-1}$ $-1.7150 \times 10^{-1}$	92	117	$-2.4524 \times 10^{-2}$	1/0	100	-1.0000 × 10
8 72	46 46	$-1.7150 \times 10$ $-1.0000 \times 10^{-1}$	92 93	118	$-2.4524 \times 10$ $2.4524 \times 10^{-2}$	_	_	_
14	40	-1.0000 X 10 1	73	110	2.4324 X 10 2			

There are 8 degrees of freedom.

The full state space equations:

$$\begin{bmatrix} \mathbf{E} & \mathbf{0} \\ \mathbf{0} & \mathbf{I} \end{bmatrix} \begin{Bmatrix} \dot{\mathbf{x}} \\ \mathbf{y} \end{Bmatrix} = \begin{bmatrix} \mathbf{A} & \mathbf{B} \\ \mathbf{C} & \mathbf{D} \end{bmatrix} \begin{Bmatrix} \mathbf{x} \\ \mathbf{u} \end{Bmatrix}$$

			-0.	11711	-0	-0	-0.35302	-0.09832	0.24675	-0.36894	-0.02193	0.29442	0.24848	-0.26691	-0.33845
		-613.65	-3	46.5	-386.74	-6535.8	-1159.8	-1919.4	-298.21	445.32	-72.642	1457.2	-679.81	-1337.3	-101.23
		-0	-0.	07009	-0	-0	-0.42821	0.75136	-0.06475	0.15051	-0.02394	0.03656	0.03579	0.04578	0.26685
		-0	0.0	5519	-0	-0	0.27908	0.11638	-0.01859	-0.42594	0.08304	0.06686	0.03729	0.18892	-0.15004
		1181.6	-69	95.98	5264.5	-794.1	1901.9	2168.9	2630.1	-1347.1	-5170.9	-3228.6	1209.7	664.68	-1363.2
		-5971	20	32.5	-4154.2	-2242.6	-1529.6	-1070.4	1946.7	815.14	1660.3	-304.52	-943.47	-3296.6	728.2
		3555.8	-94	10.51	1213.3	1873	509.1	232.5	-1637.5	-348.7	159.99	680.29	108.81	1639.2	69.997
		8610.4	-31	168.2	5099.4	4477.7	2482.9	1801.3	-3355.2	-939.48	-2279.4	743.07	2239.3	5788.7	-1563.9
A	в]	563.13	17	5.54	-1676.8	315.47	-774.79	-956.77	-1243.7	296.16	2027.3	1298.8	-848.94	-362.14	825.04
C	D =	-10607	3470.2		-2437.1	-4745.6	-1209.2	47.782	6599.4	217.16	-1601.6	-3902.8	-1065.8	-6153.6	380.02
L	J	-10515	43	86.7	-3673.5	-1438.4	-1410.1	308.47	6773.1	-78.68	-243.43	-4468	-2001.5	-6960.3	1554
		10993	-24	163.8	-2183	-1618	-2357.8	-4675.4	-8330.2	315.31	6076.3	7393.2	-3162.8	1463.3	2518.3
		838.72		84.6	-3392.8	-821.31	-2514.5	-2554.9	687.09	-855	3057.5	116.2	-4753.9	-5640.4	3761.5
		-4285.2		886	-2481	-1409.7	-1299.3	-853.58	2139.1	256.36	1088.1	-792.04	-1504.8	-3483.7	1086
		-10957		25.9	-3978.7	-3915.3	-1152.5	-178.18	3962.8	1519.5	111.33	-1562.1	737.02	-3253.9	-733.51
		2259.4	-9	62.5	3180.2	2738.7	1674	1847.2	157.44	-666.42	-2222.6	-1257.9	1382.6	2275.8	-1005.5
		-0.1232	-0.	01795	0.31602	0.0391	0.07852	0.09387	0.07858	-0.00892	0.01237	-0.03385	0.01546	0.04504	-0.03354
		0.04809	-0.	06784	0.10656	0.23013	-0.04133	-0.10207	-0.0327	0.05558	-0.00966	0.13477	0.01403	-0.00659	-0.06912
	г 1	0	0	-0	-0	0	0	0	0	-0	-0	-0	0	0	-0
	0	2.2883	-0	0	-1.4052	3.3069	-0.9808	1.578	-0.29413	0.45	-0.60884	2.5764	3.1878	-0.02343	1.3674
	0	-0	1	-0	-0	0	0	0	0	0	0	0	-0	0	-0
	-0	0	-0	1	-0	-0	0	0	-0	0	0	-0	-0	-0	-0
	-0	-1.4052	-0	-0	4.6238	-6.2892	0.55533	-3.0006	0.31688	-0.05597	0.94316	-5.0658	-6.0009	1.4704	-2.3575
	0	3.3069	0	-0	-6.2892	19.264	-3.6063	7.7986	-1.0077	0.1126	-1.5927	7.9188	13.147	-5.6729	3.7936
	0	-0.9808	0	0	0.55533	-3.6063	4.3377	-2.2916	0.12125	-0.07808	1.0805	-1.6027	-2.8356	-1.8792	-0.83227
Б	0	1.578	0	0	-3.0006	7.7986	-2.2916	7.6641	-2.1395	0.86438	-3.6717	4.1552	5.8568	0.05633	0.49498
E =	0	-0.29413	0	-0	0.31688	-1.0077	0.12125	-2.1395	2.7061	-1.7856	1.2867	0.45371	-0.4178	-1.0828	0.04931
	-0	0.45	0	0	-0.05597	0.1126	-0.07808	0.86438	-1.7856	4.0592	-0.22036	-1.2821	0.17241	2.2912	0.89829
	-0	-0.60884	0	0	0.94316	-1.5927	1.0805	-3.6717	1.2867	-0.22036	3.8922	-2.0826	-1.6036	-1.5509	0.24827
	-0	2.5764	0	-0	-5.0658	7.9188	-1.6027	4.1552	0.45371	-1.2821	-2.0826	10.674	9.3935	-0.92743	3.1054
	0	3.1878	-0	-0	-6.0009	13.147	-2.8356	5.8568	-0.4178	0.17241	-1.6036	9.3935	13.307	-2.1353	3.8886
	0	-0.02343	0	-0	1.4704	-5.6729	-1.8792	0.05633	-1.0828	2.2912	-1.5509	-0.92743	-2.1353	9.2266	0.20518
	1 -	1.0454			0.0555	0 =00.4			0 0 1001		0.0400=	0 4054	0.0007	0.00=40	0.0004
	-0	1.3674	-0	-0	-2.3575	3.7936	-0.83227	0.49498	0.04931	0.89829	0.24827	3.1054	3.8886	0.20518	3.2931