## APPLICATION Chemical Industry

## Carbon and the Reduction of Iron Ore

Some metals, especially iron, are separated from their ores through reduction reactions in a blast furnace. The blast furnace gets its name from the fact that air or pure oxygen is blown into the furnace, where it oxidizes carbon to form carbon monoxide, CO. Carbon and its compounds are important reactants in this process.

What happens inside the blast furnace to recover the iron from its ore? The actual chemical changes that occur are complex. A simplified explanation begins with the reaction of oxygen in hot air with coke, a form of carbon. Some of the coke burns to form carbon dioxide.

$$C(s) + O_2(g) \longrightarrow CO_2(g)$$

As the concentration of oxygen is decreased, the carbon dioxide comes in contact with pieces of hot coke and is reduced to carbon monoxide.

$$CO_2(g) + C(s) \longrightarrow 2CO(g)$$

The carbon monoxide now acts as a reducing agent to reduce the iron oxides in the ore to metallic iron.

$$Fe_2O_3(s) + 3CO(g) \longrightarrow 2Fe(l) + 3CO_2(g)$$

The reduction is thought to occur in steps as the temperature in the furnace increases. The following are some of the possible steps.

$$Fe_2O_3 \longrightarrow Fe_3O_4 \longrightarrow FeO \longrightarrow Fe$$


The white-hot liquid iron collects in the bottom of the furnace and is removed every four or five hours. The iron may be cast in molds or converted to steel in another process.

Limestone, present in the center of the furnace, decomposes to form calcium oxide and carbon dioxide.

$$CaCO_3(s) \longrightarrow CaO(s) + CO_2(g)$$

The calcium oxide then combines with silica, a silicon compound, to form calcium silicate slag.

The relatively high carbon content of iron produced in a blast furnace makes the metal hard but brittle. It also has other impurities, like sulfur and phosphorus, that cause the recovered iron to be brittle. The conversion of iron to steel is essentially a purification process in which impurities are removed by oxidation. This purification process is carried out in another kind of furnace at very high temperatures. All steel contains 0.02 to 1.5% carbon. In fact, steels are graded by their carbon content. Low-carbon steels typically contain 0.03 to 0.3% carbon. Mediumcarbon steels typically contain 0.03 to 0.7% carbon. High-carbon steels contain 0.7 to 1.5% carbon.



Molten iron flowing from the bottom of a blast furnace has been reduced from its ore through a series of reactions at high temperatures in different regions of the furnace.