




IT LOOKS LIKE BASE WALL
HATCH AND INNER FILL
REGION IS NOT BLACK;
UPDATE ALL HATCHES TO BE
BLACK

ADD ROOM IN PARENTHESIS
TO CEILING BEAM OPTIONS (IN
LAYERS) TO HELP NOTE
GREAT ROOM VS. PRIMARY
BED

NOT SURE HOW OVERLAPPING
HIGHLIGHTS APPEAR IN
CHECKOUT WITH MULTIPLY;
LET'S FOLLOW UP WHEN
THESE ARE UPLOADED TO
SEE IF THIS APPEARS OKAY.

HIGHLIGHT FOR "BED001"
APPEARS DARKER THAN
OTHERS; CONFIRM THAT ALL
HIGHLIGHTS ARE MULTIPLY VS.
HAVING TRANSPARENCY PER
TECHS' ASK

"BED001" TURNS SOMETHING
ON IN THE LAUNDRY (AND
MAYBE PRIMARY BATH?).
ISOLATE DOWN TO THE
BEDROOM AREA ONLY

EXPAND BLACK HATCH IN
WALLS OUT TO EXTERIOR
LINE, TYP. ALL EXT. WALLS

DASHED LINES
SOLID LINES
(GHOSTING)

