
SELF CLEAN BLUE - CNC FILE IS X:\3740001.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[55] B25 / R232650 / G3 [56] B26 / R232650 / G7 [77] C17 / R232836 / RG1 [78] C18 / R232836 / RG4 [79] C19 / R232836 / RG2 [80] C20 / R232836 / RG5

SELF CLEAN BLUE - CNC FILE IS X:\3740002.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[7] A7 / R232296 / RG1 [8] A8 / R232296 / RG5 [9] A9 / R232296 / RG2 [10] A10 / R232296 / RG6 [31] B1 / R232646 / G1 [93] D3 / R233139 / H [140] E20 / R232800 / RG1

SELF CLEAN BLUE - CNC FILE IS X:\3740003.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[11] A11 / R232296 / RG3
[12] A12 / R232296 / RG7
[13] A13 / R232296 / RG4
[14] A14 / R232296 / RG8
[73] C13 / R232831 / RG1
[141] E21 / R232800 / RG4

SELF CLEAN BLUE - CNC FILE IS X:\3740004.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[33] B3 / R232646 / G2
[35] B5 / R232647 / G1
[36] B6 / R232647 / G5
[39] B9 / R232647 / G3
[40] B10 / R232647 / G7
[41] B11 / R232647 / G4
[42] B12 / R232647 / G8
[85] C25 / R232965 / G2

SELF CLEAN BLUE - CNC FILE IS X:\3740005.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[47] B17 / R232648 / G3 [48] B18 / R232648 / G7 [49] B19 / R232648 / G4 [50] B20 / R232648 / G8 [52] B22 / R232650 / G5 [74] C14 / R232831 / RG3 [83] C23 / R232965 / G1 [143] E23 / R232800 / RG5

SELF CLEAN BLUE - CNC FILE IS X:\3740006.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[32] B2 / R232646 / G3 [86] C26 / R233139 / A [101] D11 / R233152 / B [102] D12 / R233152 / C [106] D16 / R231838 / RG1

SELF CLEAN BLUE - CNC FILE IS X:\3740007.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[19] A19 / R232484 / RG3 [20] A20 / R232484 / RG7 [44] B14 / R232648 / G5 [46] B16 / R232648 / G6 [84] C24 / R232965 / G3 [88] C28 / R233139 / C [90] C30 / R233139 / E [92] D2 / R233139 / G [96] D6 / R233139 / K [97] D7 / R233139 / L [108] D18 / R231838 / RG2

SELF CLEAN BLUE - CNC FILE IS X:\3740008.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[6] A6 / R232155 / RG6 [53] B23 / R232650 / G2 [66] C6 / R232765 / RG3 [76] C16 / R232831 / RG4 [107] D17 / R231838 / RG3 [130] E10 / R231927 / RG6 [136] E16 / R232780 / RG1 [137] E17 / R232780 / RG3

SELF CLEAN BLUE - CNC FILE IS X:\3740009.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[27] A27 / R232546 / RG3
[28] A28 / R232546 / RG7
[29] A29 / R232546 / RG4
[30] A30 / R232546 / RG8
[75] C15 / R232831 / RG2
[111] D21 / R231845 / RG2
[112] D22 / R231845 / RG3
[125] E5 / R231927 / RG2
[126] E6 / R231927 / RG5
[145] E25 / R232800 / RG6

SELF CLEAN BLUE - CNC FILE IS X:\3740010.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[5] A5 / R232155 / RG3 [65] C5 / R232765 / RG1 [69] C9 / R232823 / RG1 [139] E19 / R232780 / RG4 [146] E26 / R232822 / RG1

SELF CLEAN BLUE - CNC FILE IS X:\3740011.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[15] A15 / R232484 / RG1
[59] B29 / R232755 / RG1
[60] B30 / R232755 / RG4
[61] C1 / R232755 / RG2
[62] C2 / R232755 / RG5
[64] C4 / R232755 / RG6
[98] D8 / R233139 / M
[142] E22 / R232800 / RG2

SELF CLEAN BLUE - CNC FILE IS X:\3740012.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[1] A1 / R232155 / RG1 [2] A2 / R232155 / RG4 [37] B7 / R232647 / G2 [110] D20 / R231845 / RG1 [117] D27 / R231873 / E [124] E4 / R231927 / RG2 [127] E7 / R231927 / RG5

SELF CLEAN BLUE - CNC FILE IS X:\3740013.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[17] A17 / R232484 / RG2
[18] A18 / R232484 / RG6
[21] A21 / R232484 / RG4
[22] A22 / R232484 / RG8
[24] A24 / R232546 / RG5
[116] D26 / R231873 / B
[119] D29 / R231873 / F

SELF CLEAN BLUE - CNC FILE IS X:\3740014.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[45] B15 / R232648 / G2 [63] C3 / R232755 / RG3 [67] C7 / R232765 / RG2 [68] C8 / R232765 / RG4 [109] D19 / R231838 / RG4 [120] D30 / R231927 / RG1 [123] E3 / R231927 / RG4 [128] E8 / R231927 / RG3 [129] E9 / R231927 / RG3 [138] E18 / R232780 / RG2

SELF CLEAN BLUE - CNC FILE IS X:\3740015.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[82] C22 / R232836 / RG6 [114] D24 / R231873 / A [115] D25 / R231873 / D [118] D28 / R231873 / C

SELF CLEAN BLUE - CNC FILE IS X:\3740016.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[26] A26 / R232546 / RG6 [54] B24 / R232650 / G6 [70] C10 / R232823 / RG3 [113] D23 / R231845 / RG4 [131] E11 / R231927 / RG6 [149] E29 / R232822 / RG4

SELF CLEAN BLUE - CNC FILE IS X:\3740017.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF [16] A16 / R232484 / RG5 [91] D1 / R233139 / F [134] E14 / R232754 / RG2 [147] E27 / R232822 / RG2

[148] E28 / R232822 / RG3

SELF CLEAN BLUE - CNC FILE IS X:\3740018.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[38] B8 / R232647 / G6
[94] D4 / R233139 / I
[95] D5 / R233139 / J
[100] D10 / R233152 / A
[103] D13 / R233152 / D
[121] E1 / R231927 / RG1
[122] E2 / R231927 / RG4

SELF CLEAN BLUE - CNC FILE IS X:\3740019.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)



[25] A25 / R232546 / RG2 [72] C12 / R232823 / RG4 [89] C29 / R233139 / D


[BI NO] / RACK NO. / JOB / REF

[99] D9 / R233139 / N [132] E12 / R232754 / RG1 [133] E13 / R232754 / RG3

[144] E24 / R232800 / RG3

SELF CLEAN BLUE - CNC FILE IS X:\3740020.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)




[BI NO] / RACK NO. / JOB / REF

[23] A23 / R232546 / RG1 [34] B4 / R232646 / G4 [43] B13 / R232648 / G1 [51] B21 / R232650 / G1 [71] C11 / R232823 / RG2 [81] C21 / R232836 / RG3 [135] E15 / R232754 / RG4

SELF CLEAN BLUE - CNC FILE IS X:\3740021.DAT STOCK SHEET 3180 MM WIDE x 2520 MM HIGH

(FLIPPED=NO) (EDGE DELETE = NO) (CNC GLASS THICKNESS NOT USED)



[BI NO] / RACK NO. / JOB / REF

[3] A3 / R232155 / RG2 [4] A4 / R232155 / RG5 [57] B27 / R232650 / G4 [58] B28 / R232650 / G8 [87] C27 / R233139 / B [104] D14 / R231542 / E-A [105] D15 / R231542 / E-N