

## Dream Pools and Spas 1105 Washington Blvd Pittsburgh, Pennsylvania 15206 (412) 661- 7665 Laboratory Analysis Report

APM 4

Lab# 2545

<u>Customer</u> American Pools Management

3261 Babcock Blvd. Pittsburgh, PA 15237

Facility Name: Valleybrook Swim Club

Address: 100 Callender Rd

Pittsburgh, PA 15237

Matrix: Recreational Water

Results

Source Type: Baby Pool

**Accredited Analysis** 

Sample Collection

 Date:
 7/29/25

 Time:
 7:56 AM

 Method:
 Grab

Sample Final Analysis

Incubation Date/Time

 Date:
 8/1/25

 Time:
 9:00 AM

 Analyst:
 AS

Analyst

Method

Escherichia Coli:	Absent	Absent	7/30/25	10:00 AM	EB	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/30/25	10:00 AM	EB	SM 9222B
Standard plate count:	0/ml	200/ml	7/29/25	4:00 PM	АН	SM 9215B
Field Analysis	Results	Reporting limit	Dat	e/Time	Analyst	Method
Field Analysis pH:	Results 8.0 SU	7.2 - 7.8 SU	7/29/25	e/Time 7:56 AM	Analyst MM	Method DPD

Reporting limit

## Sample comments

( When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor

andre Smith



## Dream Pools and Spas 1105 Washington Blvd Pittsburgh, Pennsylvania 15206 (412) 661- 7665 Laboratory Analysis Report

APM 4

Lab# 2545

<u>Customer</u> American Pools Management

3261 Babcock Blvd. Pittsburgh, PA 15237

Facility Name: Valleybrook Swim Club

Address: 100 Callender Rd

Pittsburgh, PA 15237

Matrix: Recreational Water

Results

Source Type: Baby Pool

**Accredited Analysis** 

Sample Collection

 Date:
 7/29/25

 Time:
 7:56 AM

 Method:
 Grab

Sample Final Analysis

Incubation Date/Time

 Date:
 8/1/25

 Time:
 9:00 AM

 Analyst:
 AS

Analyst

Method

Escherichia Coli:	Absent	Absent	7/30/25	10:00 AM	EB	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/30/25	10:00 AM	EB	SM 9222B
Standard plate count:	0/ml	200/ml	7/29/25	4:00 PM	АН	SM 9215B
Field Analysis	Results	Reporting limit	Dat	e/Time	Analyst	Method
Field Analysis pH:	Results 8.0 SU	7.2 - 7.8 SU	7/29/25	e/Time 7:56 AM	Analyst MM	Method DPD

Reporting limit

## Sample comments

( When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor

andre Smith