硬件接线图

\otimes SA1 HL0 Χ0 Υ0 Y1 HL1 SQ1 X1 Y2 HL2 PLC SB1 X2 Υ3 HL3 Υ4 HL4 SQ2 Х3 SB5 X4 SB3 X5 Х6 SB4 $C\square M$ СПМ DC 24V

状态转移图

