Force Sensor

Negative

Negative

Positive

Battery

GND

2

U2
47 pF

6

R1
100 kΩ

2

3

+

−

1

U1A
MCP6004

Opamp powered by battery
Floating ground

Output to Raspberry Pi