

OUTPUT VOLTAGE
28V
20V
12V
9V
5V
J1
J2
INPUT
OUTPUT
S1 S2 S3 VOUT
1 X X 5V
0 0 0 9V
0 0 1 12V
0 1 1 20V
0 1 0 28V
SWITCHES
+V_USB
GND
+3V3
CHECK IF YOUR USB SUPPORT PD
error
USB_C ADVANCED POWER SUPPLY