

#### CRCP in BW 8 in Houston District

- Completed in Nov 1989
- 10-in CRCP Slab
- 1-in bond breaker (asphalt-stabilized base)
- 6-in cement-treated base and 6-in limetreated soil
- Coarse aggregate type; Both gravel and limestone






#### **Pavement Condition Evaluations**

(Crack Spacing: Nov 2010, Spalling: Feb 2012)

- Crack spacing evaluations
- Average crack spacing & Spalling (repair) ratio


#### **Crack Spacing Distribution**

#### Transverse Crack Spacing Overall Sections




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	16	6.0%
2-4	45	16.9%
4-6	54	20.3%
6-8	51	19.2%
8-10	48	18.0%
10-12	31	11.7%
12-14	17	6.4%
14-16	3	1.1%
16-18	1	0.4%
Total	266	100%

#### Transverse Crack Spacing Section A




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	6	15.0%
2-4	7	17.5%
4-6	12	30.0%
6-8	9	22.5%
8-10	2	5.0%
10-12	3	7.5%
12-14	1	2.5%
Total	40	100%

#### Transverse Crack Spacing Section B




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	2	5.7%
2-4	4	11.4%
4-6	10	28.6%
6-8	9	25.7%
8-10	3	8.6%
10-12	5	14.3%
12-14	2	5.7%
Total	35	100%

#### Transverse Crack Spacing Section C




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	1	3.4%
2-4	5	17.2%
4-6	4	13.8%
6-8	2	6.9%
8-10	8	27.6%
10-12	3	10.3%
12-14	5	17.2%
14-16	0	0.0%
16-18	1	3.4%
Total	29	100%

#### Transverse Crack Spacing Section D




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	0	0.0%
2-4	5	16.1%
4-6	4	12.9%
6-8	11	35.5%
8-10	5	16.1%
10-12	4	12.9%
12-14	1	3.2%
14-16	1	3.2%
Total	31	100%

#### Transverse Crack Spacing Section E




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	0	0.0%
2-4	2	7.4%
4-6	8	29.6%
6-8	2	7.4%
8-10	8	29.6%
10-12	4	14.8%
12-14	3	11.1%
Total	27	100%

#### Transverse Crack Spacing Section F




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	2	7.4%
2-4	1	3.7%
4-6	4	14.8%
6-8	3	11.1%
8-10	6	22.2%
10-12	6	22.2%
12-14	3	11.1%
14-16	2	7.4%
Total	27	100%

#### Transverse Crack Spacing Section G



Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	4	10.0%
2-4	11	27.5%
4-6	6	15.0%
6-8	7	17.5%
8-10	9	22.5%
10-12	3	7.5%
Total	40	100%


#### Transverse Crack Spacing Section H




Transverse Crack Spacing [ft]	Number	Frequency (%)
0-2	1	2.7%
2-4	10	27.0%
4-6	6	16.2%
6-8	8	21.6%
8-10	7	18.9%
10-12	3	8.1%
12-14	2	5.4%
Total	37	100%

# Average Crack Spacing & Spalling (Repair) Ratio


### Average Crack Spacing for SRG Sections (A, B, C, and D)



### Spalling (Repair) Ratio for SRG Sections (A, B, C, and D)



## Average Crack Spacing for LS Sections (E, F, G, and H)



### Spalling (Repair) Ratio for LS Sections (E, F, G, and H)

