IH 45 in Dallas District

- Completed in 1975
- 8-in CRCP Slab
- 6-in soil cement base
- 6-in lime treated subgrade with 4 % lime



































