

Repair Quotation

Customer name:	Vietnam Electronic Telecommunication and Technology I.S.C (明锐科技)
Customer Code:	205628
Quotation No.:	BJD250120032
Date:	2025/01/20

Item	RMA#	Logistics tracking NO.	Repair code	SN	Encryption IC No.	Product Model	Delivery time	Fault reason	Unit Price (USS)
1	SHD241227025	38	WDXD250117378	WP21110009500687	00320014CC	C4HJL1	2021-11-29 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
2	SHD241227025	38	WDXD250117379	WP22050219502616	0032004616	C4HJL3	2022-06-27 00:00:00	模块损坏/故障	\$20,77
3	SHD241227025	38	WDXD250117380	WP21120135S01159	00320025F0	C4HJL1	2021-12-30 00:00:00	GPS模块故障/don GPS bị lỗi	\$25,78
4	SHD241227025	38	WDXD250117381	WP21120135S01644	003200210E	C4HJL1	2021-12-30 00:00:00	模块损坏/故障	\$16,88
5	SHD241227025	38	WDXD250117384	WP22050219503694	0032004BA4	C4HJL3	2022-06-27 00:00:00	GPS模块故障/don GPS bị lỗi	\$25,78
6	SHD241227025	38	WDXD250117387	WP21110052500003	00320000C1	C4HJL1	2021-11-29 00:00:00	模块损坏/故障	\$20,77
7	SHD241227025	38	WDXD250117389	WM210511050499	HS(HDD)-LHH0401HS		2021-06-01 00:00:00	GPS模块故障/don GPS bị lỗi	\$32,24
8	SHD241227025	38	WDXD250117388	WM2105110505353	HS(HDD)-LHH0401HS		2021-06-01 00:00:00	PCB损坏/故障	\$98,30
9	SHD241227025	38	WDXD250117391	WP21110009500686	00320013EA	C4HJL1	2021-11-29 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
10	SHD241227025	38	WDXD250117386	WP22050219501333	0032004EBC	C4HJL3	2022-06-27 00:00:00	模块损坏/故障	\$20,77
11	SHD241227025	38	WDXD250117390	WM2105110505978	HS(HDD)-LHH0401HS		2021-06-01 00:00:00	PCB损坏/故障	\$98,30
12	SHD241227025	38	WDXD250117394	25011728	00BD0000844	HS(HDD)-LHH0400	2021-12-29 00:00:00	PCB损坏/故障	\$98,30
13	SHD241227025	38	WDXD250117392	WM21051151550220	HS(HDD)-LHH0400		2021-06-29 00:00:00	PCB损坏/故障	\$98,30
14	SHD241227025	38	WDXD250117391	WM21051105050227	00BD0000BCS	HS(HDD)-LHH0401HS	2021-11-29 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
15	SHD241227025	38	WDXD250117393	WM2105153550300	HS(HDD)-LHH0400		2021-12-29 00:00:00	GPS模块故障/don GPS bị lỗi	\$32,24
16	SHD241227025	38	WDXD250117396	25011729	0032007B92	C43	2022-07-13 00:00:00	模块损坏/故障	\$19,77
17	SHD241227025	38	WDXD250117352	WP22050219500861	0032004887	C4HJL3	2022-06-27 00:00:00	不读取芯片	\$17,16
18	SHD241227025	38	WDXD250117367	WP21110052500041	00320000B9	C4HJL1	2021-11-29 00:00:00	读取失败/失败	\$17,30
19	SHD241227025	38	WDXD250117372	WP211100512500498	00320000C69	C4HJL1	2021-11-29 00:00:00	模块损坏/故障	\$19,77
20	SHD241227025	38	WDXD250117350	WP22050219501380	0032003D1E	C4HJL3	2022-06-27 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
21	SHD241227025	38	WDXD250117349	WP22050219501686	00320045CA	C4HJL3	2022-06-27 00:00:00	读取失败/失败	\$22,50
22	SHD241227025	38	WDXD250117363	WP22050219501830	0032003F90	C4HJL1	2022-06-27 00:00:00	模块损坏/故障	\$19,77
23	SHD241227025	38	WDXD250117347	WP22050219501042	00320047FE	C4HJL3	2022-06-27 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
24	SHD241227025	38	WDXD250117353	WP22050219500028	00320041DB	C4HJL1	2022-06-27 00:00:00	读取失败/失败	\$25,78
25	SHD241227025	38	WDXD250117354	WP22050219501582	003200449F	C4HJL3	2022-06-27 00:00:00	模块损坏/故障	\$19,77
26	SHD241227025	38	WDXD250117356	WP21120135S0220	0032002070	C4HJL1	2021-12-30 00:00:00	读取失败/失败	\$17,30
27	SHD241227025	38	WDXD250117358	WP22050219500340	0032004493	C4HJL3	2022-06-27 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
28	SHD241227025	38	WDXD250117359	WP22050219502201	003200486D	C4HJL3	2022-06-27 00:00:00	模块损坏/故障	\$19,77
29	SHD241227025	38	WDXD250117364	WP22050219501564	0032004140	C4HJL3	2022-06-27 00:00:00	读取失败/失败	\$16,88
30	SHD241227025	38	WDXD250117382	WP2112004950473	0032001C26	C4HJL3	2021-12-28 00:00:00	GPS模块故障/don GPS bị lỗi	\$22,50
31	SHD241227025	38	WDXD250117366	WP21120135S0276	00320021EA3	C4HJL1	2021-12-29 00:00:00	模块损坏/故障	\$17,30
32	SHD241227025	38	WDXD250117371	WP2111006950984	00320014A9	C4HJL1	2021-11-29 00:00:00	读取失败/失败	\$19,77
33	SHD241227025	38	WDXD250117374	WP22050219501088	0032004D18	C4HJL3	2022-06-27 00:00:00	读取失败/失败	\$17,30

Total: 1016.03\$

Please issue the T/T of above amount into following company bank account:

Beneficiary Bank: BANK OF BEIJING SHENZHEN BRANCH

BANK ADDRESS: 1/F, FUCHUNDONGFANG BUILDING, NO.7006 SHEN NAN STREET, FUTIAN DISTRICT, SHENZHEN

Beneficiary : STREAMAX TECHNOLOGY CO., LTD

Beneficiary USD BANK A/C #: 0039 2518 0014 2010 7004 925

SWIFT CODE: BJCNCBJSZK

If you have any other questions, you can contact our customer service staff through the following "Call Center" contact information to help you solve the problems.

E-mail: CL@streamax.com

LinkedIn: Streamax Technology Co., Ltd

Facebook: Streamax Technology

1	
2	