

Repair Quotation

Customer name:	Vietnam Electronic Telecommunication and Technology J.S.C (聚越兴管)
Customer Code:	205628
Quotation No.:	BJD250120032
Date:	2025/01/20

Item	RMA#	Logistics tracking NO.	Repair code	SN	Encryption IC No.	Product Model	Delivery time	Fault reason	Unit Price (US\$)
1	SHD241227025	38	WXD250117376	WP21110069500667	00320014CC	C43j1.1	2021-11-29 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
2	SHD241227025	38	WXD250117379	WP22050219502616	0032004616	C43j1.3	2022-06-27 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$20,77
3	SHD241227025	38	WXD250117380	WP21120135501159	00320025F0	C43j1.1	2021-12-30 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$25,78
4	SHD241227025	38	WXD250117381	WP21120135501644	003200210E	C43j1.1	2021-12-30 00:00:00	SIM卡座不良/diêm the SIM bị lỗi	\$16,88
5	SHD241227025	38	WXD250117384	WP22050219503694	0032004BA4	C43j1.3	2022-06-27 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$25,78
6	SHD241227025	38	WXD250117387	WP21110052500003	0032000CC1	C43j1.1	2021-11-29 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$20,77
7	SHD241227025	38	WXD250117389	WM2105110050499		H5(HDD)-LHH0401JHS	2021-06-01 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$32,24
8	SHD241227025	38	WXD250117388	WM2105110050353		H5(HDD)-LHH0401JHS	2021-06-01 00:00:00	PCB断裂/ân mòn PCB	\$98,30
9	SHD241227025	38	WXD250117375	WP21110069500686	00320013EA	C43j1.1	2021-11-29 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
10	SHD241227025	38	WXD250117386	WP22050219501333	0032004EBC	C43j1.3	2022-06-27 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$20,77
11	SHD241227025	38	WXD250117390	WM2105110050978		H5(HDD)-LHH0401JHS	2021-06-01 00:00:00	PCB断裂/ân mòn PCB	\$98,30
12	SHD241227025	38	WXD250117394	25011728	00BD000B44	H5(HDD)-LHH0400	2021-12-29 00:00:00	PCB断裂/ân mòn PCB	\$98,30
13	SHD241227025	38	WXD250117392	WM2105153550220		H5(HDD)-LHH0400	2021-06-29 00:00:00	PCB断裂/ân mòn PCB	\$98,30
14	SHD241227025	38	WXD250117391	WM2105110050227	00BD000BC5	H5(HDD)-LHH0401JHS	2021-11-29 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
15	SHD241227025	38	WXD250117393	WM2105153550300		H5(HDD)-LHH0400	2021-12-29 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$32,24
16	SHD241227025	38	WXD250117396	25011729	0032007B92	C43	2022-07-13 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$19,77
17	SHD241227025	38	WXD250117352	WP22050219500861	00320048B7	C43j1.3	2022-06-27 00:00:00	摄像头模组芯片不良/loại chip máy cam biến hình ảnh bị lỗi	\$17,16
18	SHD241227025	38	WXD250117367	WP21110052500041	0032000BB9	C43j1.1	2021-11-29 00:00:00	SIM卡座不良/diêm the SIM bị lỗi	\$17,30
19	SHD241227025	38	WXD250117372	WP21110052500498	0032000C69	C43j1.1	2021-11-29 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$19,77
20	SHD241227025	38	WXD250117350	WP22050219501380	0032003D1E	C43j1.3	2022-06-27 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
21	SHD241227025	38	WXD250117349	WP22050219501686	00320045CA	C43j1.3	2022-06-27 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
22	SHD241227025	38	WXD250117363	WP22050219501830	0032003F90	C43j1.3	2022-06-27 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$19,77
23	SHD241227025	38	WXD250117347	WP22050219501042	00320047FE	C43j1.3	2022-06-27 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
24	SHD241227025	38	WXD250117353	WP22050219500028	00320041DB	C43j1.3	2022-06-27 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$25,78
25	SHD241227025	38	WXD250117354	WP22050219501582	003200449F	C43j1.3	2022-06-27 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$19,77
26	SHD241227025	38	WXD250117356	WP21120135502250	0032002070	C43j1.1	2021-12-30 00:00:00	SIM卡座不良/diêm the SIM bị lỗi	\$17,30
27	SHD241227025	38	WXD250117358	WP22050219500340	0032004A93	C43j1.3	2022-06-27 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
28	SHD241227025	38	WXD250117359	WP22050219502201	0032004B6D	C43j1.3	2022-06-27 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$19,77
29	SHD241227025	38	WXD250117364	WP22050219501564	0032004140	C43j1.3	2022-06-27 00:00:00	SD卡座不良/diêm the SD bị lỗi	\$16,80
30	SHD241227025	38	WXD250117382	WP21120049500473	0032001C26	C43j1.3	2021-12-28 00:00:00	GPS模块不良/mô đun GPS bị lỗi	\$22,50
31	SHD241227025	38	WXD250117366	WP21120135502726	0032002EA3	C43j1.1	2021-12-29 00:00:00	SIM卡座不良/diêm the SIM bị lỗi	\$17,30
32	SHD241227025	38	WXD250117371	WP21110069500984	00320014A9	C43j1.1	2021-11-29 00:00:00	摄像头不良/loại đầu kính bị lỗi	\$19,77
33	SHD241227025	38	WXD250117374	WP22050219503088	0032004D18	C43j1.3	2022-06-27 00:00:00	SIM卡座不良/diêm the SIM bị lỗi	\$17,30
Total:									1016,03\$

1	Please issue the T/T of above amount into following company bank account:		
	Beneficiary Bank: BANK OF BEIJING SHENZHEN BRANCH		
	BANK ADDRESS: 1/F.,FUCHUNDONGFANG BUILDING,NO.7006 SHEN NAN STREET, FUTIAN DISTRICT, SHENZHEN		
	Beneficiary USD BANK A/C #: 0039 2518 0014 2010 7004 925		
	SWIFT CODE: BJCN CNBJ SJZN		
2	If you have any other questions, you can contact our customer service staff through the following "Call Center" contact information to help you solve the problems.		
	E-mail:CC@streamax.com		
	LinkedIn:Streamax Technology Co., Ltd		
	Facebook:Streamax Technology		
	Website:https://en.streamax.com		