

Repair Quotation

Customer name:	Vietnam Electronic Telecommunication and Technology J.S.C (锐明兴越)
Customer Code:	205628
Quotation No.:	BJD240909003
Date:	2024/09/09

Item	RMA#	Logistics tracking NO.	Repair code	SN	Encryption IC No.	Product Model	Delivery time	Fault reason	Unit Price (US\$)
1	SHD240905040	123556	WXD240905315	WM21051100S0814	00BD000C96	HS(HDD)-LHH0401 HS	2021-12-29 00:00:00	前壳不良/vỏ trước bị lỗi	\$4,75
2	SHD240905040	123556	WXD240905336	WP22050219S00854	0032003CF0	C43 1.3	2022-06-27 00:00:00	SIM卡座不良/diêm thẻ SIM bị lỗi	\$4,75
3	SHD240905040	123556	WXD240905344	24090563		C43	2021-12-29 00:00:00	SIM卡座不良/diêm thẻ SIM bị lỗi	\$4,75
4	SHD240905040	123556	WXD240905325	WP22050219S01014	0032004B0C	C43 1.3	2022-06-27 00:00:00	SIM卡座不良/diêm thẻ SIM bị lỗi	\$4,75
5	SHD240905040	123556	WXD240905342	24090561		C43	2021-12-29 00:00:00	贴片两腿电容不良/tụ điện sơ miêng dán bị lỗi	\$4,75
6	SHD240905040	123556	WXD240905343	24090562		C43	2021-12-29 00:00:00	贴片两腿电容不良/tụ điện sơ miêng dán bị lỗi	\$4,75
7	SHD240905040	123556	WXD240905348	WP22050219S03821	003200492B	C43 1.3	2022-06-27 00:00:00	贴片两腿电容不良/tụ điện sơ miêng dán bị lỗi	\$4,75
8	SHD240905040	123556	WXD240905337	WP21120135S02440	0032001151	C43 1.1	2021-12-29 00:00:00	贴片两腿电容不良/tụ điện sơ miêng dán bị lỗi	\$4,75
9	SHD240905040	123556	WXD240905319	24090560		HS(HDD)-LHH0400	2021-12-29 00:00:00	贴片两腿电容不良/tụ điện sơ miêng dán bị lỗi	\$4,75
10	SHD240905040	123556	WXD240905318	WM21051100S0762	00BD000B68	HS(HDD)-LHH0401 HS	2021-12-29 00:00:00	TVS/ESD不良/not at TVS/ESD bị lỗi	\$4,75
11	SHD240905040	123556	WXD240905347	WP22050219S00532	0032004693	C43 1.3	2022-06-27 00:00:00	电源芯片不良/not at chip nguồn điện bị lỗi	\$4,75
12	SHD240905040	123556	WXD240905316	WM21051100S0651	00BD0006F6	HS(HDD)-LHH0401 HS	2021-12-29 00:00:00	单片协芯片不良/loại chip máy tính chip đơn bị lỗi	\$4,75
13	SHD240905040	123556	WXD240905320	WP22050219S00353	003200467E	C43 1.3	2022-06-27 00:00:00	图像传感器芯片不良/loại chip máy cảm biến hình ảnh bị lỗi	\$5,83
14	SHD240905040	123556	WXD240905328	WP22050219S03454	0032004B28	C43 1.3	2022-06-27 00:00:00	PCB腐蚀/ ăn mòn PCB	\$14,18
15	SHD240905040	123556	WXD240905317	WM21051100S0981		HS(HDD)-LHH0401 HS	2021-06-01 00:00:00	PCB腐蚀/ ăn mòn PCB	\$81,53
16	SHD240905040	123556	WXD240905324	WP21120135S01123	00320029BE	C43 1.1	2021-12-30 00:00:00	人为损坏/ hỏng do con người gây ra - bo mạch điện va chạm gây hỏng	\$32,24
17	SHD240905040	123556	WXD240905314	WM21051100S0463		HS(HDD)-LHH0401 HS	2021-06-01 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$18,38
18	SHD240905040	123556	WXD240905322	WP22050219S03665	0032004778	C43 1.3	2022-06-27 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$9,01
19	SHD240905040	123556	WXD240905339	WP21120135S01316	0032001F35	C43 1.1	2021-12-30 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$9,01
20	SHD240905040	123556	WXD240905334	WP21120135S00787	0032002B7E	C43 1.1	2021-12-30 00:00:00	通信模块不良/mô đun truyền tin bị lỗi	\$9,01
Total:									\$236,19

1	Please issue the T/T of above amount into following company bank account:	
	Beneficiary Bank: BANK OF BEIJING SHENZHEN BRANCH BANK ADDRESS: 1/F.,FUCHUNDONGFANG BUILDING,NO.7006 SHEN NAN STREET,FUTIAN DISTRICT, SHENZHEN Beneficiary USD BANK A/C #: 0039 2518 0014 2010 7004 925 SWIFT CODE: BJCNBNJSZN Beneficiary : STREAMAX TECHNOLOGY CO.,LTD	
2	If you have any other questions, you can contact our customer service staff through the following "Call Center" contact information to help you solve the problems.	
	E-mail:CC@streamax.com	
	LinkedIn:Streamax Technology Co., Ltd	
	Facebook:Streamax Technology	
	Website:https://en.streamax.co	