
HOW TO: Scanner Calibration		Version: 1.0.0
Printer Name: Scanner		Scanner Model: Symbol LS2208
Author: Yamija Munthali		Date Issued: 3 rd November, 2017
	7())))	

Step 1:

Ensure that the Scanner is connected onto the usb port.

Step 2:

Wipe out the dirt on the scanner window with a wet tissue.



Step 3:

Scan the configuration bar codes provided

Set scanner to defaults



Set scan options

Set scanner to Data as it receives



Set the scanner to Send "\$"



Save the Configurations

