HARBORLINE TRAILER & TIRE

2250 Terminal Way, Long Beach, CA 90813 | 562-555-0137 | service@harborline.example

REPAIR INVOICE

Work Order: HL-33092 **Invoice Date:** 07/22/2026

Bill To: Ryder Dedicated - Long Beach **Customer PO:** RY-LB-0912

Trailer/Unit #: TRL-5531 **VIN:** 1UYVS2530LM774410

Equipment: 53' Reefer Trailer

#	Type	Part #	Description	Qty	Rate	Amount
1	LABOR		Dismount/mount 2 trailer tires, axle 2	1.0	115.00	115.00
2	PART	RC-29575	Tire 295/75R22.5 recap	2	235.00	470.00
3	PART	VS-445	Valve stem, brass	2	6.50	13.00
4	FEE		Tire disposal	2	5.00	10.00
5	LABOR		Repair chafed ABS harness, axle 1 RH	0.8	115.00	92.00
6	PART	449-0213	ABS sensor extension cable	1	58.40	58.40
7	FEE		Sublet: reefer unit diagnostic (ThermoTech)			145.00

SUBTOTAL	903.40
CA STATE TAX 6.25%	33.84
LA COUNTY TAX 1.00%	5.41
INVOICE TOTAL	**942.65**

TECHNICIAN NOTES / RECOMMENDATIONS (NOT BILLED)

- Axle 1 brake shoes at ~25% lining. Recommend replacement within 30 days. Est. $480.00

Signature on file. Net 30.