41 Harbor Industrial Pkwy, Duluth, MN 55802 218-555-0123

REPAIR ORDER: NTW-88310 CLOSED: 2026-09-21
CUSTOMER: Ryder Dedicated - Duluth TRAILER #: DL-4471
VIN: 1JJV532D4ML218840

LN	TYPE	PART NO.	DESCRIPTION	QTY	UNIT	AMOUNT
1	LABOR		Replace LH rear marker lamp wiring	1.4	118.00	165.20
2	PART	ML-1442R	LED marker lamp, red	2	23.80	47.60
3	PART	WH-16GA	16 ga wire harness pigtail	3	9.15	27.45
4	LABOR		Repair landing gear crank	2.0	118.00	236.00
5	PART	LG-GBX20	Landing gear gearbox	1	312.00	312.00
6	CORE	LG-GBX20C	Gearbox core charge	1	60.00	60.00

(continued on page 2)

LN	TYPE	PART NO.	DESCRIPTION	QTY	UNIT	AMOUNT
7	LABOR		Replace rear door seals	1.0	118.00	118.00
8	PART	DS-5300	Rear door seal kit	1	74.90	74.90
9	FEE		Shop supplies			22.00

SUBTOTAL	1,063.15
MN STATE TAX 6.875%	73.09
DULUTH CITY TAX 0.50%	5.32
INVOICE TOTAL	1,141.56
LESS DEPOSIT RECEIVED 09/15	-500.00
BALANCE DUE	641.56

RECOMMENDED - NOT PERFORMED
- Floor boards near nose have soft spots. Quote to replace 3 boards: $640.00