

## Fusion 360 Keyboard Shortcuts Keyboard Shortcuts by pwellever via cheatography.com/134389/cs/27737/

Design Workspace		
Е	Extrude	
Н	Hole	
Q	Press Pull	
F	Model Fillet	
M	Move	
V	Toggle Visibility	
SHFT+N	Toggle Component Color Cycling	
S	Model Toolbox	
Α	Appearance	
CMD+B	Compute All	
J	Joint	
SHFT+J	As-built Joint	
L	Line	
R	2-point Rectangle	
С	Center Diameter Circle	
Т	Trim	
0	Offset	
I	Measure	
Р	Project	
Х	Normal / Construction	
D	Sketch Dimension	
SHFT+S	Scripts and Add-ins	
1	Window Selection	
2	Freeform Selection	
3	Paint Selection	

Drawing Workspace		
Р	Projected View	
M	Move	
С	Center Mark	
D	Dimension	
Т	Text	
В	Balloon	

Animation Workspace		
M	Transform Components	
U	Auto Explode All Levels	
E	Manual Explode	
U	View	
Р	Publish Video	

Display Options	
CMD+OPT+V	Show/Hide ViewCube
CMD+OPT+B	Show/Hide Browser
CMD+OPT+A	Show/Hide Comments
CMD+OPT+C	Show/Hide Text Commands
CMD+OPT+W	Show/Hide Toolbar
CMD+OPT+N	Show/Hide Navigation Bar
CMD+OPT+P	Show/Hide Data Panel
CMD+OPT+R	Reset To Default Layout
SHFT+1	Multiple Views

Visual Styles		
CTRL+4	Shaded	
CTRL+5	Shaded with Hidden Edges	
CTRL+6	Shaded with Visible Edges Only	
CTRL+7	Wireframe	
CTRL+8	Wireframe with Hidden Edges	
CTRL+9	Wireframe with Visible Edges Only	



By **pwellever** cheatography.com/pwellever/

Published 26th April, 2021. Last updated 26th April, 2021. Page 1 of 1. Sponsored by **Readable.com**Measure your website readability!
https://readable.com