



Average accuracy (with units in cm) =

True position	Measured Position	Error
x _{ti}	x _{mi}	x_{ti} - x_{mi}
1	1	0
.2	.5	3
0	.38	380
1.6	1.475	.125
	1.19	.010
1.2		

