Tensile / Compression Strength Tester

Hung Ta Instrument | Model: HT-8116

Benchtop force tester for connectors & contacts.



PRODUCT OVERVIEW

Benchtop force tester for connector pull-out, insertion force & contact retention. Digital display with peak hold function.

Category
Wires and Cable

KEY FEATURES / SPECIFICATIONS

Tests	Pull-out, insertion force, contact retention	**Display**	Digital with peak hold

TYPICAL APPLICATIONS

Connector manufacturers • Wire harness QC

REFERENCED STANDARDS

IEC 60352 | MIL-C-26500

CONFIGURATION & QUOTATION

Tell us the sample material, dimensions, required test method, standard and capacity. We will check the suitable machine, fixture and configuration before quotation.

AI illustrative render only - not a confirmed supplier photograph or exact configuration. Confirm actual appearance and specifications before order.