Hung Ta / PRODUCT CATALOGUE

HT-8116

Tensile / Compression Strength Tester

Benchtop force tester for connectors & contacts.



Product overview

Benchtop force tester for connector pull-out, insertion force & contact retention. Digital display with peak hold function.

Technical specifications

Tests	Pull-out, insertion force, contact retention
Display	Digital with peak hold

Typical applications

Connector manufacturers / Wire harness QC

Referenced standards

IEC 60352 / MIL-C-26500

Configuration & quotation

Send the specimen material and dimensions, required force range, test method and factory location. Confirm the supplied machine, fixtures and accessories in the quotation.

Specifications are reference values for configuration review. Contact Hung Ta Instrument for the current supplied configuration.