

KiCad preparing for work (rev 1.1)

1. Obtain Barsotion KiCad libraries

```
git clone git@github.com:Barsotion/kicad-lib.git
kilm setup
```

For updating from server:

```
git pull
kilm setup
```

Be shore there are no critical errors:

```
PS C:\Users\victo\Documents\KiCad\kicad-lib> kilm setup
Using KiCad library from environment variable: C:\Users\victo\Documents\KiCad\kicad-lib
Warning: KICAD_3D_LIB not set, 3D models might not work correctly
Consider adding a 3D model directory with 'kilm add-3d'
```

```
Symbol library directory: C:\Users\victo\Documents\KiCad\kicad-lib
3D models directory: Not configured
```


```
Found KiCad configuration at: C:\Users\victo\AppData\Roaming\kicad\10.0
Error updating environment variables: argument of type 'NoneType' is not iterable
Created backup of symbol library table
Created backup of footprint library table
Added 24 libraries to KiCad configuration
Pinned 20 symbol and 6 footprint libraries in KiCad
```

```
Setup complete! Restart KiCad for changes to take effect.
```

Turn off standard KiCad libraries pack


On the main KiCad menu, Preferences -> Manage Symbol Libraries...:

Symbol Libraries





On the main KiCad menu, Preferences -> Manage Footprint Libraries...:



Footprint Libraries






On the main KiCad menu, Preferences -> Preferences...:



You should to install a [GOST type B](#) font.







Then, your KiCad is ready to work.