CUSTOMER SERVICE BULLETIN

Radio Shaek CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	John Per Howard
Description	
Model	16
Stock No.	36-6002
Date	11/16/82
Page 1 of	, ,

Problem & CAN 512 K of RAM be added to MOD 16 WITH THE HIGH RES. BOARD Added.

Solution VES THERE ARE A TOTAL OF 8 AVAILABLE SLOTS - THIS CONFIGURATION REQUIRES 7 - LEAVING ONE MORE FOR A HARD DIST