CUSTOMER SERVICE BULLETIN

Radio Shaek CUSTOMER SERVICE BULLETIN

Bulletin No. 45Ø5-4

Description Accounts Payable

Model Model II

Stock No. 26-4505 Version 1.0

Date October 6, 1980

Page 1 of 2

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

After error code 61 has occurred there is not a way to correct the problem.

Solution

Attached is a progarm to fix the index in Accounts Payable if an error code 61 has occurred. Try the change in Bulletin 4505-2 on backups, then mail out this program.

PROCEDURE FOR RE-INDEXING APS - (26-45\$)

- Type, BASIC -F:3 and press ENTER
- Type in the following program.

See next page for the program.

CUSTOMER SERVICE BULLETIN

Subject _____Accounts Payable Bulletin # 4505-4 Page _____2 Of __2

```
20000 ZN=VN:ZD=VD
20010 VN=1:VT=0:VD=0
20020 FOR W9=0 TO ZN-1
20030 P(W9,0)=0 : P(W9,1)=0
20040 NEXT
20050 FOR ZZ=1 TO ZN-1
20060 GET 2,ZZ
2ØØ7Ø VV=CVI(VØ$)
20080 V$(1)=VF$(1)
20090 GOSUB 1700
20100 VT=VT+1:VN=VN+1
20110 NEXT ZZ
20120 IF ZD=0 THEN 1000
20130 CLOSE 1
20140 OPEN"I",1,VP$
20150 FOR W9=1 TO 23
20160 INPUT#1,XX!
2Ø17Ø NEXT
20180 FOR W9=1 TO VN-1
20190 INPUT#1,X1,X2
20200 IF X1>0 THEN 20280
20210 VL=ABS(X1)
20220 FOR W8=0 TO 1
20230 FOR W7=1 TO VN-1
20/240/ IF P(W7,W8)=VL THEN P(W7,W8)=-VL :W7=VN-1
20250 NEXT W7, W8
20260 VD=VD+1:VT=VT-1
20270 IF VD=ZD THEN W9=VN-1
20280 NEXT W9
2Ø29Ø GOTO 1ØØØ
3. Type, SAVE "RECOVER/ASC", A and press <ENTER>
4. Type, LOAD "APS/BAS" and press <ENTER>
5. Type, MERGE "RECOVER/ASC" and press <ENTER>
Type, RUN and press <ENTER>
7. Enter the password. At the Main Menu, press <BREAK>.
8. Type, GOTO 20000 and press <ENTER>
The recovery process will be completed and then return to the Main Menu.
Press Fl to exit the program.
```