CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

Bulletin No. 45\,\mathcal{9}6-\,\mathcal{9}4

Description Business Mailing List

Model Model II

Stock No. 26-4506 Version 2.0

Date Dec. 29, 1981

Page 1 of 2

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

If you run SETUP and option for a revision, the revised information will not be stored under the appropriate filename.

Solution

The following routine can be used to change the name you assigned to the Mailing List system (MAILING LIST 26-4506). With a BACKUP of your Mailing List in drive 0, RUN the following program while in BASIC:

- 1Ø CLEAR5ØØ:DEFINTA-Z:DIMC\$(7):CLS:PRINT@1525,"This program allows you to change the Mailing List system name as is stored in the system information data file. You must rename all three Mailing List files after running this routine."
- 20 PRINT@410,;:INPUT"ENTER THE CURRENT MAILING LIST SYSTEM NAME"; F0\$:GOSUB90
- 30 PRINT@490,;:INPUT"ENTER THE NEW MAILING LIST SYSTEM NAME";SN\$:GOSUB50
- 4Ø PRINT@985, "CHANGE COMPLETE": PRINT@184Ø,;:END
- 5Ø OPEN"O",1,FØ\$
- 6Ø PRINT#1,SN\$:PRINT#1,NA\$:PRINT#1,TL\$:PRINT#1,AD\$:PRINT#1,CSZ\$: PRINT#1,FM\$
- 7Ø PRINT#1,CP;M;MØ;M1;M3;M4;M5;M6;M7;M8
- 80 FORI=0TO7:PRINT#1,C\$(I):NEXT:CLOSE1:RETURN
- 9Ø FØ\$=FØ\$+"Ø:Ø":OPEN"I",1,FØ\$
- 100 LINEINPUT#1,SN\$:LINEINPUT#1,NA\$:LINEINPUT#1,TL\$:LINEINPUT#1,AD\$
- 110 LINEINPUT#1,CSZ\$:LINEINPUT#1,FM\$
- 12Ø INPUT#1,CP,M,MØ,M1,M2,M3,M4,M5,M6,M7,M8
- 13Ø FORI=ØTO7:LINEINPUT#1,C\$(I):NEXT:CLOSE1:RETURN

CUSTOMER SERVICE BULLETIN

Subject _____Business Mailing List 45%6-Ø4 _____ Page ____2 Of _2

NOTE

After completion of the above you must rename the three Mailing List data files. At TRSDOS READY type

RENAME filename TO newname ENTER RENAME filename TO newname ENTER RENAME filename TO newname ENTER

where 'filename' corresponds to the current Mailing List system, and 'newname' is the name you are changing it to.