CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

 Bulletin No. 1562-5

 Description
 Profile

 Model
 Model I

 Stock No. 26-1562 Version 1.0

 Date
 June 10, 1980

 Page 1 of
 1

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

The program given at the top of page 26 is incorrect.

Solution

The corrections are shown in the new lines below:

Old Line: 60 GET1,2:FORI=0TONF-1:IFI=8THENGET1,3

New Line: 6Ø GET1,2:J=Ø:FORI=ØTONF-1:IFI=8THENGET1,3:J=Ø

Old Line: 90 NEXTI:CLOSE

New Line: 90 J=J+1:NEXTI:CLOSE