CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	453Ø-1
Description Scripsit	
Model	Model II
Stock No.	26-4530 Version 1.0
Date	January 29, 1981
Page 1 of	1

Problem

Repaginate wiping out documents and scrambling text.

Solution

- Reset system and insert a Scripsit diskette.
- 2. Answer the Date Prompt.
- 3. Press <HOLD>
- 4. Answer the Time Prompt.
- 5. Do the following patches.

PATCH SCRIPSIT/6 A=EØ94 F=ØF C=Ø5

PATCH SCRIPSIT/6 A=E235 F=C65667 C=C31ØDC

PATCH SCRIPSIT A=DC10 F=0000000000000 C=B72006210057C3

PATCH SCRIPSIT A=DC17 F=000000000000000 C=3DE2C65667C338E2

- 6. The patches are now complete type STARTUP to get into Scripsit's Main Menu.
- 7. Make a backup of the patched diskette.