817-390-3090

A Division of Tandy Corporation

700 ONE TANDY CENTER, FORT WORTH, TEXAS 76102

TO: All Computer Centers

CC: C. Phillips, T. Cromer,

J. Sigler, D. Brown,

V. Chandler

FROM: Wes Stewart

DATE: March 28, 1979

SUBJECT: TAND

TANDY-10 DISKETTES, BULK TAPE ERASER, & KNOWN BUGS

IN 2.0 ADOS

Do not erase any Tandy-10 diskettes, single or dual sided, with a bulk tape eraser. If you do, the entire diskette will be erased, including the soft sector format. There is no capability to format the diskettes on the Tandy-10.

The format program on the ½ meg machine is not a true format. It was intended to erase an ADDS*PLUS diskette for use as an ADOS diskette since ADDS*PLUS and ADOS cannot be on the same diskette.

The only known bugs I have found in 2.0 ADOS are:

- The Stat Program will not work properly if *.* parameter is used. The results are unpredictable.
- 2. If you type: A > BASIC (PROGRAM NAME) (ENTER)
 Where the program name is a basic program to be loaded
 and executed automatically and the program name does not
 exist. Again, the results are unpredictable.

Usually the machine will have to be turned off and rebooted.

If you have any questions or have any errors you have found in ADOS or BASIC, call me at 817/390-3095.

