## **CUSTOMER SERVICE BULLETIN**

## Radio Shack

Ø312-14 Bulletin No.

Description TRSDOS 1.3

Model

Model III

Stock No.

26-Ø312 Ver.Ø1.Ø3.Ø2

**Date** 

March 1, 1983

Page 1 of

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

## **Problem**

The Software Write Protect Command is not working properly.

THE FOLLOWING PATCHES ARE REQUIRED!

## **Solution**

After patches from this Bulletin have been applied, the version number will be \$1.\$3.\$3. Please make the necessary entry in your Version Log.

```
PATCH *2 (ADD=4F56,FIND=2F,CHG=21)
```

- PATCH \*2 (ADD=4F58,FIND=2D,CHG=1F)
- PATCH \*2 (ADD=4F6B,FIND=1A,CHG=ØC)
- PATCH \*2 (ADD=4F7Ø,FIND=C5D5E521ØØ4311,CHG=CD8A4FCDF75Ø28)
- PATCH \*2 (ADD=4F77,FIND=ØØ4DØ1ØØØ1EDBØ,CHG=283A38513C2ØØ7)
- PATCH \*2 (ADD=4F7E,FIND=E1D1C1CDF75Ø28,CHG=ØC3A1344B93ØCD)
- PATCH \*2 (ADD=4F85,FIND=123A38513C2ØØ7,CHG=3E1BC38A4EC5D5)
- PATCH \*2 (ADD=4F8C,FIND=ØC3A1344B93ØBF,CHG=E521ØØ4D11ØØ43)
- PATCH \*2 (ADD=4F93,FIND=3E1BC38A4E453A,CHG=0100012001EBED)
- PATCH \*2 (ADD=4F9A,FIND=754E77C5D5E521,CHG=BØE1D1C1C9ØØ45)
- PATCH \*2 (ADD=4FA1,FIND=004D1100430100,CHG=3A754E77B7CD8A)
- PATCH \*2 (ADD=4FA8,FIND=01EDB0E1D1C1CD,CHG=4FCDC24AFE0F28)
- PATCH \*2 (ADD=4FAF,FIND=C24A,CHG=C8B7)