


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Cleomarta Mendes

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-MILA-23331 2Mbps



Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

11.962753 DVB-S2 2 0 0.0 E 1 1 16.667000

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.176284 GHz Frequency Symbol Rate : 4.882955 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.0 dB SNR : -43 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.4 dBm

ODU Output Power : 33.4 dBm

EIRP
______
Es/No
                    : 12.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -276 us (281443 us)
Frequency correction: 130 Hz
System Information:
    Name
                        : SEE-MILA-23331
    Location
                        : Mirabela - MG
    Contact
    System Up time : 0 days, 05:33:59
CPU Load : 12%
    System time (UTC) : 02 December 2017 19:01:24
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:60:75
Satellite (DVB) : 00:20:0e:10:60:75
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.213.223.2 Dynamic 74:e6:e2:d4:e4:73 1
Pinging 10.213.223.1 with 32 bytes of data:
Reply from 10.213.223.1: bytes=32 time=561ms TTL=56
Reply from 10.213.223.1: bytes=32 time=556ms TTL=56
Reply from 10.213.223.1: bytes=32 time=559ms TTL=56
Reply from 10.213.223.1: bytes=32 time=567ms TTL=56
Reply from 10.213.223.1: bytes=32 time=563ms TTL=56
Reply from 10.213.223.1: bytes=32 time=567ms TTL=56
Reply from 10.213.223.1: bytes=32 time=670ms TTL=56
Reply from 10.213.223.1: bytes=32 time=533ms TTL=56
Reply from 10.213.223.1: bytes=32 time=562ms TTL=56
Reply from 10.213.223.1: bytes=32 time=555ms TTL=56
Ping statistics for 10.213.223.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 533ms, Maximum = 670ms, Average = 569ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Cleomarta Mendes Função: Diretora MASP: 3634622 Telefone: 38-32391232 Funcionamento: 07:00h às 17:00h