


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Jeane Ferreira de Sousa

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-SACO-22228 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 * 0 0 12.176420 DVB-S2 104 0 0.0 E

Yes

0 0.0 E 16.667000 11.962753 DVB-S2 2 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Prode : 12.176297 GHz Frequency Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot : ACM : Short Frame length DVB S2 Mode DVB S2 Stream type : MPEG-TS : 0.20 Roll off SNR : 15.4 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                   : On (DVB-RCS2)
State
IDU Output Power : -19.1 dBm
ODU Output Power : 33.3 dBm
EIRP
                    : 46.6 dBW
Es/No
                    : 11.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -96 us (281573 us)
Frequency correction: 80 Hz
System Information:
                   : SEE-SACO-22228
   Name
    Location
                       : S¦O FRANCISCO - MG
    Contact
   System Up time : 0 days, 01:18:36 CPU Load : 5%
    System time(UTC) : 28 October 2017 20:08:00
    Broadcast Message : not set
HW:
                       : SatLink 2000
    Model
                       : 120033
    HW ID
    Main board ID
                       : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:49:96
Satellite (DVB) : 00:20:0e:10:49:96
NetAddr State MacAddr
    10.213.27.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.27.1 with 32 bytes of data:
Reply from 10.213.27.1: bytes=32 time=570ms TTL=56
Reply from 10.213.27.1: bytes=32 time=572ms TTL=56
Reply from 10.213.27.1: bytes=32 time=579ms TTL=56
Reply from 10.213.27.1: bytes=32 time=551ms TTL=56
Reply from 10.213.27.1: bytes=32 time=556ms TTL=56
Reply from 10.213.27.1: bytes=32 time=573ms TTL=56
Reply from 10.213.27.1: bytes=32 time=561ms TTL=56
Reply from 10.213.27.1: bytes=32 time=553ms TTL=56
Reply from 10.213.27.1: bytes=32 time=549ms TTL=56
Reply from 10.213.27.1: bytes=32 time=557ms TTL=56
Ping statistics for 10.213.27.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 549ms, Maximum = 579ms, Average = 562ms
```

Lista de sites acessados:

<u>www.globo.com</u> – ok

www.yahoo.com - ok

<u>www.hotmail.com</u> – ok

www.google.com – ok

www.educacao.mg.gov.br - ok

www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Jeane Ferreira de Sousa

Função: Diretora

Identidade: MASP 11266038

Telefone: 38- 99953-5354

Horário de funcionamento – 07:00 as 12:00