


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan P de Brito Júnior Responsável/cliente: WELINGTON CARLOS GRE/Prodemge: João Antinossi **GOCALVES** Porta kbps Plataforma Consórcio VSAT-ID EMC/Vodanet 2Mbps **VSAT** SEE-INIM-23146

Port eth 0 SEE-INIM-23146 (10.214.141.1)



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176415 GHz Symbol Rate : 8.882770 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.9 dB Input Power : -38 dBm

Satellite (DVB) TX Configuration

.____

Auto start : Enabled IDU Output Power : -15 dBm IDU Max Output Power: 0.0 dBm Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -14.8 dBm

Es/No : 15.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -227 us (266030 us)

Frequency correction: 260 Hz

System Information:

Name : SEE-INIM-23146 Location : Inhapim - MG

Contact :

System Up time : 5 days, 00:21:04

CPU Load : 14%

System time(UTC) : 08 January 2018 19:24:38

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4c:5a Satellite (DVB) : 00:20:0e:10:4c:5a

Pinging 10.214.141.1 with 32 bytes of data:

Reply from 10.214.141.1: bytes=32 time=541ms TTL=56 Reply from 10.214.141.1: bytes=32 time=564ms TTL=56 Reply from 10.214.141.1: bytes=32 time=550ms TTL=56 Reply from 10.214.141.1: bytes=32 time=536ms TTL=56 Reply from 10.214.141.1: bytes=32 time=530ms TTL=56 Reply from 10.214.141.1: bytes=32 time=530ms TTL=56 Reply from 10.214.141.1: bytes=32 time=599ms TTL=56 Reply from 10.214.141.1: bytes=32 time=552ms TTL=56 Reply from 10.214.141.1: bytes=32 time=574ms TTL=56 Reply from 10.214.141.1: bytes=32 time=559ms TTL=56

Ping statistics for 10.214.141.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 530ms, Maximum = 599ms, Average = 553ms

Resp: Welington Carlos Gonçalves Cargo: Diretor Masp: 1076881-0

Telefone: 33- 9 9947-1439 Horário: 07:00 as 18:00

www.hotmail.com www.google.com www.prodemge.gov.br www.globo.com www.youtube.com