

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Gilvan P de Brito Júnior

Responsável/cliente: Marli Maria Rodrigues GRE/Prodemge: João Antinossi Batista

> Consórcio VSAT-ID Plataforma Porta kbps

EMC/Vodanet SEE-TENI-22978 2048/1024 **VSAT**



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

PY watchdog : 15 minute

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State

: On : Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 65281, Proder : 12.176317 GHz : 4 882007 Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.3 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
 ______
                     : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                      : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                      : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -13.2 dBm
ODU Output Power : 34.8 dBm
EIRP
                      : 48.1 dBW
Es/No
                      : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -326 us (280693 us)
Frequency correction: 10 Hz
System Information:
                      : SEE-TENI-22978
   Name
    Location
                       : TEÓFILO OTONI - MG
    Contact
    System Up time : 0 days, 00:23:23
    CPU Load
                        : 11%
    System time(UTC) : 22 November 2017 12:57:07
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
                        : 120033
    HW ID
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5d:66
Satellite (DVB) : 00:20:0e:10:5d:66
   NetAddr
               State MacAddr
                                           Ιf
   10.215.177.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.215.177.1 with 32 bytes of data:
Reply from 10.215.177.1: bytes=32 time=605ms TTL=56
Reply from 10.215.177.1: bytes=32 time=541ms TTL=56
Reply from 10.215.177.1: bytes=32 time=575ms TTL=56
Reply from 10.215.177.1: bytes=32 time=537ms TTL=56
Reply from 10.215.177.1: bytes=32 time=533ms TTL=56
Reply from 10.215.177.1: bytes=32 time=546ms TTL=56
Reply from 10.215.177.1: bytes=32 time=531ms TTL=56
Reply from 10.215.177.1: bytes=32 time=522ms TTL=56
Reply from 10.215.177.1: bytes=32 time=528ms TTL=56
Reply from 10.215.177.1: bytes=32 time=522ms TTL=56
Ping statistics for 10.215.177.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 605ms, Average = 544ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
www.hotmail.com – ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br – ok
Responsável pelo teste de navegação: Nome: ELOISA HELENA PEIXOTO Função: Diretora MASP 840999-7 Telefone: (33) 98821-3794 Horário de funcionamento da escola: 07:00 as 17:00