


TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Gustavo Oliveira	
GRE/Prodemge: João Antinossi		Responsável/cliente And	acele Rosa dos Santos
Consórcio EMC/Vodanet	VSAT-ID SEE-SEAS-22570	Porta kbps 2Mbps	Plataforma VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 15.6 dB Input Power : -36 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -20.6 dBm ODU Output Power : 33.3 dBm **EIRP** : 46.6 dBW

Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -452 us (281581 us)

Frequency correction: 40 Hz

arp show

State MacAddr NetAddr 10.213.153.2 Dynamic 64:1c:67:61:83:29 1

device show

System Information:

: SEE-SEAS-22570 Name

Location : Serranopolis de Minas - MG

Contact

: 0 days, 00:08:21 : 15% System Up time

CPU Load

System time(UTC) : 14 November 2017 19:10:03

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.1

MAC addresses:

: 00:20:0e:10:49:fe Ethernet (LAN) Satellite (DVB) : 00:20:0e:10:49:fe

Pinging 10.213.153.1 with 32 bytes of data:

Reply from 10.213.153.1: bytes=32 time=560ms TTL=56 Reply from 10.213.153.1: bytes=32 time=549ms TTL=56 Reply from 10.213.153.1: bytes=32 time=546ms TTL=56 Reply from 10.213.153.1: bytes=32 time=553ms TTL=56 Reply from 10.213.153.1: bytes=32 time=532ms TTL=56 Reply from 10.213.153.1: bytes=32 time=541ms TTL=56 Reply from 10.213.153.1: bytes=32 time=540ms TTL=56 Reply from 10.213.153.1: bytes=32 time=544ms TTL=56 Reply from 10.213.153.1: bytes=32 time=557ms TTL=56 Reply from 10.213.153.1: bytes=32 time=529ms TTL=56

Ping statistics for 10.213.153.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 529ms, Maximum = 560ms, Average = 545ms

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Anacele Rosa dos Santos
Cargo	Diretora
Identidade	874717-2
Telefone	038-9-9903-3136
Funcionamento	07:00-22:20
Onde ficou	Sala da diretora