


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

**GRE/Prodemge:** João Antinossi Responsável/cliente: Benedita Olaia Bezerra

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **VSAT** SEE-SAES-22256 2Mbps



Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 03201, --: 12.176217 GHz : 4.882988 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.8 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
_____
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                   : On (DVB-RCS2)
State
IDU Output Power : -15.8 dBm
ODU Output Power : 33.3 dBm
EIRP
                    : 46.3 dBW
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -249 us (281217 us)
Frequency correction: 130 Hz
System Information:
   Name
                       : SEE-SAES-22256
    Location
                        : S¦O JO¦O DAS MISS¦ES - MG
   Contact
   System Up time : 0 days, 00:40:37 CPU Load : 7%
    System time(UTC) : 28 October 2017 19:34:30
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:57:af
    Satellite (DVB)
                       : 00:20:0e:10:57:af
NetAddr
            State MacAddr
    10.213.55.2 Dynamic e8:9a:8f:b7:bd:4a
Pinging 10.213.55.1 with 32 bytes of data:
Reply from 10.213.55.1: bytes=32 time=592ms TTL=56
Reply from 10.213.55.1: bytes=32 time=559ms TTL=56
Reply from 10.213.55.1: bytes=32 time=570ms TTL=56
Reply from 10.213.55.1: bytes=32 time=546ms TTL=56
Reply from 10.213.55.1: bytes=32 time=535ms TTL=56
Reply from 10.213.55.1: bytes=32 time=571ms TTL=56
Reply from 10.213.55.1: bytes=32 time=588ms TTL=56
Reply from 10.213.55.1: bytes=32 time=549ms TTL=56
Reply from 10.213.55.1: bytes=32 time=575ms TTL=56
Reply from 10.213.55.1: bytes=32 time=585ms TTL=56
Ping statistics for 10.213.55.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 592ms, Average = 567ms
```

## Lista de sites acessados: www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok

www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok

Responsável pelo teste de navegação:

Nome: Benedita Olaia Bezerra

Função: Professora

Identidade: MASP 1097839-3

Telefone: 38- 99898-1951

Horário de funcionamento – 07:00 as 21:20