


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Alberto Nunes Ferreira

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-SAES-22277 **VSAT** 2Mbps



Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet : 12.176391 GHz Network

Frequency Symbol Rate : 4.883029 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 16.0 dB SNR Input Power : -33 dBm

```
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)

IDU Output Power : -17.9 dBm

ODU Output Power : 33.4 dBm

EIRP
Es/No
                     : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -269 us (281238 us)
Frequency correction: 140 Hz
# arp show
                  State MacAddr
   NetAddr
                                               Τf
    10.213.76.2 Dynamic 74:e6:e2:d4:e4:73 1
# device show
System Information:
    Name
                         : SEE-SAES-22277
    Location
                         : S¦O JO¦O DAS MISS¦ES - MG
    Contact
    System Up time : 0 days, 00:05:01 CPU Load : 4%
    System time (UTC) : 29 October 2017 19:27:32
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:55:63
Satellite (DVB) : 00:20:0e:10:55:63
# arp show
                 State MacAddr
    10.213.76.3 Dynamic e4:be:ed:90:94:9a 1
Pinging 10.213.76.1 with 32 bytes of data:
Reply from 10.213.76.1: bytes=32 time=553ms TTL=56
Reply from 10.213.76.1: bytes=32 time=560ms TTL=56
Reply from 10.213.76.1: bytes=32 time=566ms TTL=56
Reply from 10.213.76.1: bytes=32 time=584ms TTL=56
Reply from 10.213.76.1: bytes=32 time=591ms TTL=56
Reply from 10.213.76.1: bytes=32 time=571ms TTL=56
Reply from 10.213.76.1: bytes=32 time=523ms TTL=56
Reply from 10.213.76.1: bytes=32 time=567ms TTL=56
Reply from 10.213.76.1: bytes=32 time=551ms TTL=56
```

```
Reply from 10.213.76.1: bytes=32 time=582ms TTL=56

Ping statistics for 10.213.76.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 523ms, Maximum = 591ms, Average = 564ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação:

Nome: Alberto Nunes Ferreira

Função: Diretor Masp: 4507604

Telefone: 38-99827-6720

Funcionamento: 07:00 às 17:00h