


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: João Carlos widar

GRE/Prodemge: João Antinossi Responsável/cliente: Elton Fonseca Almeida

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-UBAI-222852MBPSVSAT



PRTG Traffic Grapher V6.2.0.907 - 19/10/2017 23:48:17

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176001 GHz Symbol Rate : 4.883115 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short
DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.8 dB Input Power : -26 dBm

#

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -15.0 dBm
ODU Output Power : 33.6 dBm

EIRP : 46.6 dBW Es/No : 15.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -236 us (281716 us)

Frequency correction: 60 Hz

System Information:

Name : SEE-UBAI-22285 Location : UBA - MG

Contact :

System Up time : 0 days, 00:22:21

CPU Load : 9%

System time(UTC) : 19 October 2017 22:38:53

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4b:72 Satellite (DVB) : 00:20:0e:10:4b:72

arp show

NetAddr State MacAddr If 10.213.84.2 Dynamic 54:04:a6:8e:d3:f6 1

#

C:\Documents and Settings\Administrator.DVB-RCS.000>ping 10.148.0.123 -n 10

Pinging 10.148.0.123 with 32 bytes of data:

```
Reply from 10.148.0.123: bytes=32 time=556ms TTL=62 Reply from 10.148.0.123: bytes=32 time=555ms TTL=62 Reply from 10.148.0.123: bytes=32 time=543ms TTL=62 Reply from 10.148.0.123: bytes=32 time=543ms TTL=62 Reply from 10.148.0.123: bytes=32 time=583ms TTL=62 Reply from 10.148.0.123: bytes=32 time=584ms TTL=62 Reply from 10.148.0.123: bytes=32 time=578ms TTL=62 Reply from 10.148.0.123: bytes=32 time=563ms TTL=62 Reply from 10.148.0.123: bytes=32 time=565ms TTL=62 Reply from 10.148.0.123: bytes=32 time=568ms TTL=62 Reply from 10.148.0.123: bytes=32 time=568ms TTL=62
```

Ping statistics for 10.148.0.123:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 543ms, Maximum = 584ms, Average = 563ms

Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Elton Fonseca Almeida Função: assistente técnico Identidade: Masp- 369697.8