

# TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Eduardo Tarda

GRE/Prodemge: João Antinossi


Responsável/cliente José Osvaldo Vieria

Consórcio
EMC/Vodanet

VSAT-ID
SEE-POTE-22891

Porta kbps
2Mbps
VSAT





#### SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

# dvb tx show

#### Satellite (DVB) TX Configuration

Auto start : Enabled

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

### Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS2)
IDU Output Power : -16.7 dBm
ODU Output Power : 33.3 dBm
EIRP : 46.6 dBW
Es/No : 13.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -206 us (280826 us)

Frequency correction: 130 Hz

# dvb rx show

#### Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Name

Yes

Yes

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Enable 4.883300 12.176420 DVB-S2 104 0 0.0 E \*00 1 1 16.667000 11.962753 DVB-S2 2 0.00ESatellite (DVB) Receiver Status Rx State : On **DVB** State : Forward link up Network : 65281, Prodemge@Vodanet : 12.176477 GHz Frequency Symbol Rate : 4.882985 Msps S2 ModCod - receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6 Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS Roll off : 0.20 : 16.4 dB Input Power : -27 dBm # arp show NetAddr State MacAddr 10.215.155.2 Dynamic b8:70:f4:6e:b3:ab 1 # device show System Information: : SEE-POTE-22891 Name Location : Pot - MG Contact System Up time : 0 days, 00:20:50 : 19% CPU Load System time(UTC) : 20 November 2017 18:50:15 Broadcast Message : not set HW: Model : SatLink 2000 : 120033 HW ID Main board ID : 120026 R6.2 MAC addresses: Ethernet (LAN) : 00:20:0e:10:59:37 Satellite (DVB) : 00:20:0e:10:59:37 Pinging 10.215.155.1 with 32 bytes of data: Reply from 10.215.155.1: bytes=32 time=574ms TTL=56 Reply from 10.215.155.1: bytes=32 time=568ms TTL=56 Reply from 10.215.155.1: bytes=32 time=551ms TTL=56 Reply from 10.215.155.1: bytes=32 time=554ms TTL=56 Reply from 10.215.155.1: bytes=32 time=529ms TTL=56 Reply from 10.215.155.1: bytes=32 time=589ms TTL=56 Reply from 10.215.155.1: bytes=32 time=742ms TTL=56 Reply from 10.215.155.1: bytes=32 time=561ms TTL=56 Reply from 10.215.155.1: bytes=32 time=638ms TTL=56 Reply from 10.215.155.1: bytes=32 time=533ms TTL=56 Ping statistics for 10.215.155.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 529ms, Maximum = 742ms, Average = 583ms www.yahoo.com.br

#### www.hotmail.com

www.google.com

## www.prodemge.gov.br

Responsável	José Osvaldo Vieria
Cargo	Diretor
Identidade	291680-7
Telefone	033-9-8801-0126
Funcionamento	07:00-18:30
Onde ficou	Secretaria