


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE NOC/Operadora: Ricardo Benavides Operadora/Cliente: Ederson Martins Pires GRE/Prodemge: João Antinossi Responsável/cliente: Luiz Carlos Pereira VSAT-ID Consórcio Plataforma Porta kbps EMC/Vodanet SEE-LAHA-23661 **VSAT** 2Mbps





Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

12.176420 DVB-S2 104 * 0 0 8.883000 0 0.0 E Yes 1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176512 GHz Symbol Rate : 8.883120 Msps

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.4 dB Input Power : -39 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -18 dBm IDU Max Output Power: 0.0 dBm Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -18.0 dBm

Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -271 us (266109 us)

Frequency correction: 140 Hz

System Information:

Name : SEE-LAHA-23661 Location : Lajinha - MG

Contact

System Up time : 0 days, 00:57:07

CPU Load : 12%

System time(UTC) : 11 January 2018 17:30:22

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:7b:d2 Satellite (DVB) : 00:20:0e:10:7b:d2

NetAddr State MacAddr If

10.215.20.2 Dynamic 1c:39:47:5b:e2:48 1

Pinging 10.215.20.1 with 32 bytes of data:

Reply from 10.215.20.1: bytes=32 time=525ms TTL=56 Reply from 10.215.20.1: bytes=32 time=523ms TTL=56 Reply from 10.215.20.1: bytes=32 time=579ms TTL=56 Reply from 10.215.20.1: bytes=32 time=521ms TTL=56 Reply from 10.215.20.1: bytes=32 time=573ms TTL=56 Reply from 10.215.20.1: bytes=32 time=579ms TTL=56 Reply from 10.215.20.1: bytes=32 time=537ms TTL=56 Reply from 10.215.20.1: bytes=32 time=532ms TTL=56 Reply from 10.215.20.1: bytes=32 time=532ms TTL=56 Reply from 10.215.20.1: bytes=32 time=532ms TTL=56

Ping statistics for 10.215.20.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Reply from 10.215.20.1: bytes=32 time=566ms TTL=56

Approximate round trip times in milli-seconds:

Minimum = 521ms, Maximum = 579ms, Average = 546ms

Responsável: Luiz Carlos Pereira

Cargo: Diretor MASP: 564.547-8

Telefone: 033 99907-7666 Horário: 07:00 - 22:00

Onde ficou: Instalado na diretória a pedido do Diretor

www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com