

## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Elvis Maycon Gonçalves

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-SACO-22227 **VSAT** 2Mbps



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 \* 0 0 4.883300 0 0.0 E

Yes

1 0 0.0 E 11.962753 DVB-S2 2 16.667000 1

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176127 GHz Frequency Symbol Rate : 4.883046 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 16APSK-5/6 - current max : 21

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
                    : Enabled
Auto start
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                     : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -18.1 dBm
ODU Output Power : 32.7 dBm
EIRP
                     : 46.0 dBW
                     : 13.0 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -346 us (281700 us)
Frequency correction: 170 Hz
System Information:
    Name
                        : SEE-SACO-22227
    Location
                        : SAO FRANCISCO
    Contact
                        :
    System Up time : 0 days, 00:03:20
CPU Load : 14%
System time(UTC) : 25 October 2017 16:55:38
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:55:6b
    Satellite (DVB)
                        : 00:20:0e:10:55:6b
              State MacAddr
    10.213.26.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.26.1 with 32 bytes of data:
Reply from 10.213.26.1: bytes=32 time=557ms TTL=56
Reply from 10.213.26.1: bytes=32 time=564ms TTL=56
Reply from 10.213.26.1: bytes=32 time=568ms TTL=56
Reply from 10.213.26.1: bytes=32 time=579ms TTL=56
Reply from 10.213.26.1: bytes=32 time=547ms TTL=56
Reply from 10.213.26.1: bytes=32 time=553ms TTL=56
Reply from 10.213.26.1: bytes=32 time=562ms TTL=56
Reply from 10.213.26.1: bytes=32 time=536ms TTL=56
Reply from 10.213.26.1: bytes=32 time=523ms TTL=56
Reply from 10.213.26.1: bytes=32 time=567ms TTL=56
Ping statistics for 10.213.26.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 523ms, Maximum = 579ms, Average = 555ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok <u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Elvis Maycon Gonçalves Função: Vice-Diretor Identidade: RG M15836363
Telefone: 38-99973-7182
Horário de funcionamento – 07hrs às 12hrs