

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: HERNANI MOTA DE MACEDO

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-CHTE-22766 2Mbps **VSAT**





Satellite (DVB) RX Configuration _____

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network

: 65281, Prodemge@Vodanet : 12.176410 GHz : 4.882951 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.7 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-I
IDU Output Power : -17.2 dBm
ODU Output Power : 33.1 dBm
                    : On (DVB-RCS2)
State
EIRP
                    : 46.4 dBW
Es/No
                    : 15.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -184 us (280841 us)
Frequency correction: 100 Hz
System Information:
                       : SEE-CHTE-22766
   Name
    Location
                       : Chapada do Norte - MG
    Contact
   System Up time : 0 days, 00:29:29 CPU Load : 17%
    System time(UTC) : 18 November 2017 20:09:20
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
                       : 120033
    HW ID
                       : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:63:93
Satellite (DVB) : 00:20:0e:10:63:93
NetAddr
          State MacAddr
    10.214.73.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.214.73.1 with 32 bytes of data:
Reply from 10.214.73.1: bytes=32 time=541ms TTL=56
Reply from 10.214.73.1: bytes=32 time=587ms TTL=56
Reply from 10.214.73.1: bytes=32 time=616ms TTL=56
Reply from 10.214.73.1: bytes=32 time=541ms TTL=56
Reply from 10.214.73.1: bytes=32 time=589ms TTL=56
Reply from 10.214.73.1: bytes=32 time=537ms TTL=56
Reply from 10.214.73.1: bytes=32 time=551ms TTL=56
Reply from 10.214.73.1: bytes=32 time=555ms TTL=56
Reply from 10.214.73.1: bytes=32 time=546ms TTL=56
Reply from 10.214.73.1: bytes=32 time=766ms TTL=56
Ping statistics for 10.214.73.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 537ms, Maximum = 766ms, Average = 582ms
```

Lista de sites acessados: www.globo.com – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com – ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: HERNANI MOTA DE MACEDO Função: SECRETARIO MASP: 441251-7 Telefone: (33) 999329347 Funcionamento: 06:00 as 18:00