


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Marisa Mendes de Barros

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet **VSAT** SEE-PEUZ-22197 2Mbps



Satellite (DVB) RX Configuration : Enabled Auto start

Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status _____

: Forward link up

: 65281, Prodemge@Vodanet

: On

DVB State : Forward link : 65281, Proder

Frequency : 12.176349 GHz

Symbol Rate : 4.882989 **

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short
DVB S2 Mode : ACM : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.8 dB

```
Input Power
                   : -31 dBm
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                    : On (DVB-RCS2)
State
IDU Output Power : -19.2 dBm
ODU Output Power : 33.4 dBm
EIRP
                    : 46.7 dBW
Es/No
                    : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -383 us (281398 us)
Frequency correction: 90 Hz
System Information:
   Name
                        : SEE-PEUZ-22197
    Location
                        : PEDRAS DE MARIA DA CRUZ - MG
    Contact
    System Up time : 0 days, 00:30:25 CPU Load : 15%
    System time(UTC) : 27 October 2017 15:11:11
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:64:f2
Satellite (DVB) : 00:20:0e:10:64:f2
# arp show
  NetAddr
                State MacAddr
   10.212.250.2 Dynamic 64:1c:67:62:2e:12 1
C:\Documents and Settings\Administrator.DVB-RCS>ping -t 10.212.250.1
Pinging 10.212.250.1 with 32 bytes of data:
Reply from 10.212.250.1: bytes=32 time=549ms TTL=56
Reply from 10.212.250.1: bytes=32 time=580ms TTL=56
Reply from 10.212.250.1: bytes=32 time=573ms TTL=56
Reply from 10.212.250.1: bytes=32 time=566ms TTL=56
Reply from 10.212.250.1: bytes=32 time=560ms TTL=56
Reply from 10.212.250.1: bytes=32 time=536ms TTL=56
```

```
Reply from 10.212.250.1: bytes=32 time=572ms TTL=56
Reply from 10.212.250.1: bytes=32 time=560ms TTL=56
Reply from 10.212.250.1: bytes=32 time=534ms TTL=56
Reply from 10.212.250.1: bytes=32 time=539ms TTL=56

Ping statistics for 10.212.250.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 534ms, Maximum = 580ms, Average = 556ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Marisa Mendes de Barros Nascimento

Função: Diretora MASP: 931 496-4