

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Erminio Junior Operadora/Cliente: Ederson Martins

Responsável/cliente: RENATA LUCIA DE OLIVEIRA **GRE/Prodemge:** João Antinossi

CAMPOS

Consórcio VSAT-ID Porta kbps **Plataforma** EMC/Vodanet SEE-DUDE-23657 **VSAT** 2Mbps





Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

4.883300 12.176420 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176445 GHz : 8.882858 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short Frame length : Shown DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.5 dB Input Power : -38 dBm

Satellite (DVB) TX Configuration

```
_____
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
                    : On (DVB-RCS2)
IDU Output Power : -18.2 dBm
                     : 15.5 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -299 us (266192 us)
Frequency correction: 140 Hz
# arp show
                                             Ιf
   NetAddr
                State MacAddr
    10.215.16.2 Dynamic 1c:39:47:5b:e2:48 1
# device show
No Such Command
# device show
System Information:
    Name
                        : SEE-DUDE-23657
    Location
                        : Durande - MG
    Contact
   System Up time : 0 days, 00:35:25

CPU Load : 13%

System time(UTC) : 12 January 2018 16:23:19
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Eumernet (LAN) : 00:20:0e:10:7d:15
Satellite (DVB) : 00:20:0e:10:7d:15
   Ethernet (LAN)
Pinging 10.215.16.1 with 32 bytes of data:
Reply from 10.215.16.1: bytes=32 time=578ms TTL=56
Reply from 10.215.16.1: bytes=32 time=595ms TTL=56
Reply from 10.215.16.1: bytes=32 time=538ms TTL=56
Reply from 10.215.16.1: bytes=32 time=570ms TTL=56
Reply from 10.215.16.1: bytes=32 time=531ms TTL=56
Reply from 10.215.16.1: bytes=32 time=524ms TTL=56
Reply from 10.215.16.1: bytes=32 time=537ms TTL=56
Reply from 10.215.16.1: bytes=32 time=616ms TTL=56
Reply from 10.215.16.1: bytes=32 time=609ms TTL=56
Reply from 10.215.16.1: bytes=32 time=525ms TTL=56
Ping statistics for 10.215.16.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
Minimum = 524ms, Maximum = 616ms, Average = 537ms
```

Lista de sites acessados: www.globo.com – ok

<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Desmansával mala tasta da naviacação.
Responsável pelo teste de navegação:
Nome: RENATA LUCIA DE OLIVEIRA CAMPOS
Cargo: DIRETORA
Masp: 812.459-6
Masp. 612.439-0