


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Wallace Teixeira Operadora/Cliente: Gilvan P de Brito Júnior

GRE/Prodemge: João Antinossi Responsável/cliente: DINEUSA DE OLIVEIRA

> Plataforma Consórcio **VSAT-ID** Porta kbps EMC/Vodanet 2MBPS **VSAT** SEE-ITMI-23195



# dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State

: Forward link up : 65281, Prodemge@Vodanet Network

Frequency : 12.176501 GHz Symbol Rate : 4.882942 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                    : 18.1 dB
Input Power
                    : -34 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                    : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -12.9 dBm
ODU Output Power : 34.8 dBm
EIRP
                    : 47.8 dBW
Es/No
                     : 15.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -161 us (281127 us)
Frequency correction: -90 Hz
# device show
System Information:
   Name
                        : SEE-ITMI-23195
    Location
                        : itanhomi mg
    Contact
                        :
   System Up time : 0 days, 05:59:56
CPU Load : 8%
System time(UTC) : 07 December 2017 05:02:48
    Broadcast Message : not set
HW:
    HW ID
                        : SatLink 2000
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:49:9a
Satellite (DVB) : 00:20:0e:10:49:9a
 Transec not Supported by this device !
# # arp show
   NetAddr State MacAddr
                                             Ιf
Pinging 10.214.230.1 with 32 bytes of data:
Reply from 10.214.230.1: bytes=32 time=546ms TTL=56
Reply from 10.214.230.1: bytes=32 time=555ms TTL=56
Reply from 10.214.230.1: bytes=32 time=525ms TTL=56
Reply from 10.214.230.1: bytes=32 time=558ms TTL=56
Reply from 10.214.230.1: bytes=32 time=552ms TTL=56
Reply from 10.214.230.1: bytes=32 time=576ms TTL=56
Reply from 10.214.230.1: bytes=32 time=539ms TTL=56
Reply from 10.214.230.1: bytes=32 time=556ms TTL=56
Reply from 10.214.230.1: bytes=32 time=572ms TTL=56
Reply from 10.214.230.1: bytes=32 time=542ms TTL=56
```

```
Ping statistics for 10.214.230.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 576ms, Average = 552ms

Lista de sites acessados:
    www.globo.com = ok
    www.yahoo.com = ok
    www.hotmail.com = ok
    www.educacao.mg.gov.br = ok
    www.prodemge.gov.br = ok

Responsável pelo teste de navegação:
Nome: DINEUSA DE OLIVEIRA
Função: DIRETORA
Identidade: Masp- 871184-8
```