

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Joao Gustavo


GRE/Prodemge: João Antinossi


Responsável/cliente Leidimar Rocha Ruas

Consórcio
EMC/Vodanet

VSAT-ID
SEE-ALRA-23118

Porta kbps
2Mbps
Plataforma
VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

#

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP : max

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -13.1 dBm
ODU Output Power : 35.3 dBm
EIRP : 48.6 dBW
Es/No : 11.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -350 us (280027 us)

Frequency correction: 50 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Name

Yes

Yes

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Enable 4.883300 12.176420 DVB-S2 104 0 0.0 E *00 1 1 16.667000 11.962753 DVB-S2 2 0.00ESatellite (DVB) Receiver Status Rx State : On **DVB** State : Forward link up Network : 65281, Prodemge@Vodanet : 12.176464 GHz Frequency Symbol Rate : 4.883061 Msps S2 ModCod - receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6 Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS Roll off : 0.20 : 16.4 dB Input Power : -33 dBm # arp show NetAddr State MacAddr 10.214.27.2 Dynamic b4:99:ba:00:92:6b 1 # device show System Information: : SEE-ALRA-23118 Name Location : ALMENARA Contact System Up time : 0 days, 03:18:48 CPU Load : 15% System time(UTC) : 05 December 2017 12:57:48 Broadcast Message : not set HW: Model : SatLink 2000 : 120033 HW ID Main board ID : 120026 R6.2 MAC addresses: Ethernet (LAN) : 00:20:0e:10:57:d4 Satellite (DVB) : 00:20:0e:10:57:d4 Pinging 10.214.27.1 with 32 bytes of data: Reply from 10.214.27.1: bytes=32 time=553ms TTL=56 Reply from 10.214.27.1: bytes=32 time=533ms TTL=56 Reply from 10.214.27.1: bytes=32 time=536ms TTL=56 Reply from 10.214.27.1: bytes=32 time=517ms TTL=56 Reply from 10.214.27.1: bytes=32 time=550ms TTL=56 Reply from 10.214.27.1: bytes=32 time=536ms TTL=56 Reply from 10.214.27.1: bytes=32 time=544ms TTL=56 Reply from 10.214.27.1: bytes=32 time=633ms TTL=56 Reply from 10.214.27.1: bytes=32 time=530ms TTL=56 Reply from 10.214.27.1: bytes=32 time=566ms TTL=56 Ping statistics for 10.214.27.1: Packets: Sent = 10, Received = 9, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 517ms, Maximum = 633ms, Average = 526ms Resp:Leidimar Rocha Ruas Cargo: Diretora Masp:886563-6 Telefone:033-9-8819-7855 Horário:07:00-17:30

Onde ficou: Em um computador da diretoria

www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com