


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Marina Cardoso Teixeira

> Porta kbps Consórcio **VSAT-ID** Plataforma EMC/Vodanet **SEE-SEES-22966** 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Bandwidth Traffic IN Bandwidth Traffic OUT

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 65281, Prode : 12.176581 GHz Frequency Symbol Rate : 4.883009 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.3 dB SNR Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.6 dBm

ODU Output Power : 33.4 dBm

EIRP
_____
Es/No
                    : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -238 us (280200 us)
Frequency correction: 140 Hz
System Information:
    Name
                        : SEE-SEES-22966
    Location
                        : Serra dos Aimorés - MG
    Contact
    System Up time : 0 days, 00:41:12 CPU Load : 16%
    System time(UTC) : 01 December 2017 16:20:44
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:51:c4
Satellite (DVB) : 00:20:0e:10:51:c4
    Ethernet (LAN)
NetAddr
          State MacAddr
   10.215.165.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.215.165.1 with 32 bytes of data:
Reply from 10.215.165.1: bytes=32 time=553ms TTL=56
Reply from 10.215.165.1: bytes=32 time=541ms TTL=56
Reply from 10.215.165.1: bytes=32 time=555ms TTL=56
Reply from 10.215.165.1: bytes=32 time=522ms TTL=56
Reply from 10.215.165.1: bytes=32 time=515ms TTL=56
Reply from 10.215.165.1: bytes=32 time=562ms TTL=56
Reply from 10.215.165.1: bytes=32 time=545ms TTL=56
Reply from 10.215.165.1: bytes=32 time=569ms TTL=56
Reply from 10.215.165.1: bytes=32 time=556ms TTL=56
Reply from 10.215.165.1: bytes=32 time=535ms TTL=56
Ping statistics for 10.215.165.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 515ms, Maximum = 569ms, Average = 545ms
```

| Lista de sites acessados: |
|---|
| www.globo.com – ok |
| www.yahoo.com – ok |
| www.hotmail.com – ok |
| www.google.com – ok |
| www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok |
| <u>www.proderrige.gov.br</u> – ok |
| Responsável pelo teste de navegação: |
| Nome: Marina Cardoso Teixeira |
| Função: Diretora |
| MASP: 1076361-3 |
| Telefone: 33-988338423 |
| Telefolic. 33 700330 123 |
| Funcionamento: 07:00h às 19:00h |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |